



# SOUTH CAROLINA HISTORICAL SOCIETY

## Charles N. Bayless photograph collection SCHS# VM 0564.00

**Description:** 3 linear feet (8 boxes)

**Creator:** Charles N. Bayless

**Biographical Note:** Charles Nield Bayless (1914-1991), a native of Kentucky, was an architect who practiced in a law firm in Lexington, Kentucky, for 35 years. After retirement, Bayless moved to Charleston, South Carolina, where he took up a project of photographic documentation, funded in part by grants from the National Endowment for the Arts, of important lowcountry structures, photographing exteriors and interiors of historic buildings in several counties in the 1970s and 1980s. In 1986 he published his photographs of *Charleston Ironwork*.

**Scope and content:** Collection consists of thousands of black and white photographic prints and negatives of historic buildings, including houses and churches, in the counties of Charleston, Georgetown, Beaufort, and Berkeley, as well as one plantation house in Orangeburg County, The Rocks. Most of the Charleston County images depict historic homes and churches in the city of Charleston. Properties include historic plantations in the counties of Georgetown and Berkeley, as well as locations on Edisto Island. Dated images in this collection range between 1975 and 1985.

**Note:** Some of the Charles N. Bayless photographs are available online through the Library of Congress and the Lowcountry Digital Library. Photographs are also held by The Charleston Archive at the Charleston County Public Library, Historic Charleston Foundation, and the Beaufort District Collection at the Beaufort County Library.

**Preferred citation:** Bayless, Charles N. (1914-1991). Charles N. Bayless photograph collection (VM 0564.00). South Carolina Historical Society.

**Search terms:**

Architecture -- South Carolina -- Photographs  
Architecture, Domestic -- South Carolina -- Photographs  
Church architecture -- South Carolina -- Photographs  
Historic buildings -- South Carolina -- Beaufort County  
Historic buildings -- South Carolina -- Berkeley County  
Historic buildings -- South Carolina -- Charleston County  
Historic buildings -- South Carolina -- Edisto Island  
Historic buildings -- South Carolina -- Georgetown County  
Historic buildings -- South Carolina -- Photographs

Plantations -- South Carolina -- Photographs  
Charleston (S.C.) -- Buildings, structures, etc  
The Rocks Plantation (Orangeburg County, S.C.)

**Summary list:**

- Box 1 CNB 001-419.4 (prints)
- Box 2 CNB 420-735.12 (prints)
- Box 3 CNB 735.13-799.19 (prints)
- Box 4 CNB 801-1019 (prints)
- Box 5 CNB 0-376 (negatives)
- Box 6 CNB 377-743.9 (negatives)
- Box 7 CNB 743.10-859.2 (negatives)
- Box 8 CNB 860-1037 (negatives)

\*To conduct a keyword search: PC users- Control + F and MAC users- Command + F.

**Container listing:**

**File number (CNB): 001**

Address: Anne St

Print: X

Negative:

Description: Camden Depot

**File number (CNB): 002**

Address: Anne St

Print: X

Negative:

Description: Camden Depot

**File number (CNB): 003**

Address: Anne St

Print: X

Negative:

Description: Camden Depot

**File number (CNB): 004**

Address: 178 Ashley

Print: X

Negative:

Description: color

**File number (CNB): 004.1 (1)**

Address: 178 Ashley

Print:

Negative: X

Description: Westside fence

**File number (CNB): 004.1 (2)**

Address: 178 Ashley

Print:

Negative: X

Description: Westside fence

**File number (CNB): 004.2**

Address: 178 Ashley

Print:

Negative: X

Description: Westside, entry from southwest

**File number (CNB): 004.3**

Address: 178 Ashley

Print:

Negative: X

Description: Southwestside, cornice, console, and corner column cap

**File number (CNB): 004.4 (1)**

Address: 178 Ashley

Print:

Negative: X

Description: Southwest side, balcony, water table and corner column base

**File number (CNB): 004.4 (2)**

Address: 178 Ashley

Print:

Negative: X

Description: Southwest side, balcony, water table and corner column base

**File number (CNB): 005**

Address: 178 Ashley

Print: X

Negative:

Description: entry from west

**File number (CNB): 005.1**

Address: 178 Ashley

Print: X

Negative:

Description: NW corner

**File number (CNB): 005.2**

Address: 178 Ashley

Print: X

Negative:

Description: portico cornice detail

**File number (CNB): 005.3**

Address: 178 Ashley

Print: X

Negative:

Description: S side

**File number (CNB):** 005.4

Address: 178 Ashley

Print: X

Negative:

Description: SE corner

**File number (CNB):** 005.5

Address: 178 Ashley

Print: X

Negative:

Description: w side balcony detail

**File number (CNB):** 005.6

Address: 178 Ashley

Print: X

Negative:

Description:

**File number (CNB):** 005.6

Address: 178 Ashley

Print:

Negative: X

Description: Southside, column cap

**File number (CNB):** 005.7

Address: 178 Ashley

Print:

Negative: X

Description: Southside column base & balustrade

**File number (CNB):** 005.8

Address: 178 Ashley

Print:

Negative: X

Description: Southside, 1st floor entry on portico

**File number (CNB):** 005.9

Address: 178 Ashley

Print:

Negative: X

Description: Southside, 1st floor, window on portico

**File number (CNB):** 005.10

Address: 178 Ashley

Print:

Negative: X

Description: Eastside, 1st floor window, typical window detail

**File number (CNB):** 005.11

Address: 178 Ashley

Print:

Negative: X  
Description: 1st flr- entry hall, stairs looking east  
**File number (CNB):** 005.12  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr- entry hall, west and north walls  
**File number (CNB):** 005.13  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - entry hall, ceiling looking east  
**File number (CNB):** 005.14  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - entry hall, ceiling piece  
**File number (CNB):** 005.15  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - stair hall, stairs  
**File number (CNB):** 005.16  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - stair hall, ceiling looking northeast  
**File number (CNB):** 005.17  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - stair hall, ceiling looking southwest  
**File number (CNB):** 005.18  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - stair hall, ceiling piece  
**File number (CNB):** 005.19  
Address: 178 Ashley  
Print:  
Negative: X  
Description: 1st flr - west room, south & west walls  
**File number (CNB):** 005.20  
Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - west room, north wall, entry hall beyond

**File number (CNB):** 005.21

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - west room, looking east

**File number (CNB):** 005.22

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr- west room, mantle

**File number (CNB):** 005.23

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - west room, window enframement, typical of 1st flr except east wing, showing also relation to door casing

**File number (CNB):** 005.24

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - west room, cornice

**File number (CNB):** 005.25

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - west room, ceiling piece

**File number (CNB):** 005.26

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - center hall, door casing to stair hall. Typical of all 1st flr doors other than east wing

**File number (CNB):** 005.27

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - center hall, ceiling

**File number (CNB):** 005.28

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - center hall, ceiling pieces

**File number (CNB): 005.29**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - east room, north wall

**File number (CNB): 005.30**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr- east room, east and south walls

**File number (CNB): 005.32**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr- east room, mantle

**File number (CNB): 005.33**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - east room, cornice

**File number (CNB): 005.34**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr- east room, ceiling piece

**File number (CNB): 005.35**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - northeast room, north wall

**File number (CNB): 005.36**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - northeast room, typical door, service hall beyond

**File number (CNB): 005.37**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr - northeast room, mantle

**File number (CNB): 005.38**

Address: 178 Ashley

Print:

Negative: X

Description: 1st flr- northeast room, ceiling piece

**File number (CNB):** 005.39

Address: 178 Ashley

Print:

Negative: X

Description: 2nd flr - west room, looking northwest

**File number (CNB):** 005.40

Address: 178 Ashley

Print:

Negative: X

Description: 2nd flr- west room, mantle

**File number (CNB):** 005.41

Address: 178 Ashley

Print:

Negative: X

Description: 2nd flr- west room, ceiling piece and cornice

**File number (CNB):** 005.43

Address: 178 Ashley

Print:

Negative: X

Description: 2nd flr - stairhall, ceiling piece

**File number (CNB):** 007

Address: 192 Ashley

Print: X

Negative:

Description: entry

**File number (CNB):** 007.1

Address: 192 Ashley

Print: X

Negative:

Description: first floor details

**File number (CNB):** 007.2

Address: 192 Ashley

Print:

Negative: X

Description: Entry gate

**File number (CNB):** 008

Address: 1 Atlantic

Print: X

Negative:

Description: n side

**File number (CNB):** 009

Address: 3 Atlantic

Print: X



Negative:

Description: n side

**File number (CNB):** 010

Address: 69 Barre

Print: X

Negative:

Description: House entry

**File number (CNB):** 010.1

Address: 69 Barre

Print: X

Negative:

Description: N side of E entry

**File number (CNB):** 010.2

Address: 69 Barre

Print:

Negative: X

Description: Entry cornice

**File number (CNB):** 010.3 (1)

Address: 69 Barre

Print:

Negative: X

Description: Entry, iron railing of stoop

**File number (CNB):** 010.3 (2)

Address: 69 Barre

Print:

Negative: X

Description: Entry, iron railing of stoop

**File number (CNB):** 010.4

Address: 69 Barre

Print:

Negative: X

Description: Entry- ground floor vent grille

**File number (CNB):** 010.5

Address: 69 Barre

Print:

Negative: X

Description: Eastside, wood entry gate

**File number (CNB):** 011

Address: 69 Barre

Print: X

Negative:

Description: Dependencies NE corner

**File number (CNB):** 012

Address: 69 Barre

Print: X  
Negative:  
Description: " NE side  
**File number (CNB):** 013  
Address: 69 Barre  
Print: X  
Negative:  
Description: NW corner  
**File number (CNB):** 014  
Address: 69 Barre  
Print: X  
Negative:  
Description: House NW corner  
**File number (CNB):** 014.1  
Address: 69 Barre  
Print: X  
Negative:  
Description: NE side  
**File number (CNB):** 014.2  
Address: 69 Barre  
Print: X  
Negative:  
Description: SW corner  
**File number (CNB):** 014.3  
Address: 69 Barre  
Print: X  
Negative:  
Description: E side  
**File number (CNB):** 014.4  
Address: 69 Barre  
Print: X  
Negative:  
Description: S side pediment  
**File number (CNB):** 014.5  
Address: 69 Barre  
Print: X  
Negative:  
Description: E side pediment  
**File number (CNB):** 014.6  
Address: 69 Barre  
Print: X  
Negative:  
Description: dependencies SW corner  
**File number (CNB):** 014.7

Address: 69 Barre

Print: X

Negative:

Description: 1st flr entry from portico

**File number (CNB):** 014.8

Address: 69 Barre

Print: X

Negative:

Description: " hall looking SE

**File number (CNB):** 014.9

Address: 69 Barre

Print: X

Negative:

Description: " North

**File number (CNB):** 014.10

Address: 69 Barre

Print: X

Negative:

Description: " south

**File number (CNB):** 014.11

Address: 69 Barre

Print: X

Negative:

Description: 1st flr hall ceiling centerpiece & cornice

**File number (CNB):** 014.12

Address: 69 Barre

Print: X

Negative:

Description: details under 2nd flr landing

**File number (CNB):** 014.13

Address: 69 Barre

Print: X

Negative:

Description: door to SE room

**File number (CNB):** 014 +-

Address: 69 Barre

Print: X

Negative:

Description: 1st flr hall door to SE room and cornice

**File number (CNB):** 014.15

Address: 69 Barre

Print: X

Negative:

Description: 1st flr hall stairwell

**File number (CNB): 014.16**

Address: 69 Barre

Print: X

Negative:

Description: SE room looking NE

**File number (CNB): 014.17**

Address: 69 Barre

Print: X

Negative:

Description: NE "

**File number (CNB): 014.18**

Address: 69 Barre

Print: X

Negative:

Description: " mantel

**File number (CNB): 014.19**

Address: 69 Barre

Print: X

Negative:

Description: "ceiling center piece

**File number (CNB): 014.20**

Address: 69 Barre

Print: X

Negative:

Description: " cornice

**File number (CNB): 014.21**

Address: 69 Barre

Print: X

Negative:

Description: " SW " looking NW

**File number (CNB): 014.22**

Address: 69 Barre

Print: X

Negative:

Description: north wall

**File number (CNB): 014.23**

Address: 69 Barre

Print: X

Negative:

Description: ceiling center piece

**File number (CNB): 014.24**

Address: 69 Barre

Print: X

Negative:

Description: " mantel

**File number (CNB):** 014.25

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr stair hall window

**File number (CNB):** 014.26

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr filled in center hall with partition under arch looking north

**File number (CNB):** 014.28

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr center hall room glazed arch partition taken from under this dividing arch & installed in 1st floor arch

**File number (CNB):** 014.29

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr SE room, N wall ceiling centerpiece destroyed

**File number (CNB):** 014.30

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr Se room Wdw, architrave & rm cornice

**File number (CNB):** 014.31

Address: 69 Barre

Print: X

Negative:

Description: 2nd flr SE room black marble mantel

**File number (CNB):** 015

Address: 1 Broad

Print: X

Negative:

Description:

**File number (CNB):** 016

Address: 1 Broad

Print: X

Negative:

Description:

**File number (CNB):** 017

Address: 1 Broad

Print: X

Negative:

Description:

**File number (CNB): 018**

Address: 3 Broad

Print: X

Negative:

Description: n Side

**File number (CNB): 019**

Address: 7 9 11 Broad

Print: X

Negative:

Description: n Side

**File number (CNB): 019.1**

Address: 11 Broad

Print:

Negative: X

Description: Window guard

**File number (CNB): 020**

Address: 12 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 021**

Address: 13 Broad

Print: X

Negative:

Description: N side

**File number (CNB): 022**

Address: 15 Broad

Print: X

Negative:

Description: N side 2nd flr window guard

**File number (CNB): 022.1 (1)**

Address: 15 Broad

Print:

Negative: X

Description: Northside, 2nd flr, window guard

**File number (CNB): 022.1 (2)**

Address: 15 Broad

Print:

Negative: X

Description: Northside, 2nd flr, window guard

**File number (CNB): 022.1 (3)**

Address: 15 Broad

Print:

Negative: X

Description: Northside, 2nd flr, window guard

**File number (CNB):** 023

Address: 16 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 024

Address: 16 Broad

Print: X

Negative:

Description: w side

**File number (CNB):** 024.1

Address: 16 Broad

Print: X

Negative:

Description: pediment eagle

**File number (CNB):** 024.2 (1)

Address: 16 Broad

Print:

Negative: X

Description: Southside, window guard cast iron not original to site

**File number (CNB):** 024.2 (2)

Address: 16 Broad

Print:

Negative: X

Description: Southside, window guard cast iron not original to site

**File number (CNB):** 024.3

Address: 16 Broad

Print:

Negative: X

Description: Southside, gate installed in wall; these ironworks probably from 1850 remodeling; gate formerly opened into passage between 14 and 16 Broad and is now (1981) in interior courtyard

**File number (CNB):** 025

Address: 17 Broad

Print: X

Negative:

Description: n side

**File number (CNB):** 026

Address: 28 Broad

Print: X

Negative:

Description: S side

**File number (CNB): 027**

Address: 29 Broad

Print: X

Negative:

Description: N side

**File number (CNB): 028**

Address: 30 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 029.1**

Address: 33 Broad

Print: X

Negative: X

Description: Partial balcony

**File number (CNB): 030**

Address: 1 Broad

Print: X

Negative:

Description:

**File number (CNB): 030.1**

Address: 1 Broad

Print:

Negative: X

Description: Corner entry door

**File number (CNB): 030.2**

Address: 1 Broad

Print:

Negative: X

Description: Eastside entry

**File number (CNB): 030.3**

Address: 1 Broad

Print:

Negative: X

Description: Detail, iron grille in eastside door, same for corner door

**File number (CNB): 031**

Address: 25 East Battery

Print: X

Negative:

Description:

**File number (CNB): 032**

Address: 25 East Battery

Print: X



Negative:

Description:

**File number (CNB):** 033

Address: 25 East Battery

Print: X

Negative:

Description:

**File number (CNB):** 034

Address: 25 East Battery

Print: X

Negative:

Description:

**File number (CNB):** 035.1

Address: 43 East Bay

Print:

Negative: X

Description: Eastside, entry gates and door, wood

**File number (CNB):** 035

Address: 43 East Bay

Print: X

Negative:

Description:

**File number (CNB):** 036

Address: 36 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 037

Address: 37 Broad

Print: X

Negative:

Description: n side

**File number (CNB):** 038

Address: 38 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 039

Address: 40 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 040

Address: 41 Broad

Print: X  
Negative:  
Description: n side  
**File number (CNB):** 041  
Address: 42 Broad  
Print: X  
Negative:  
Description: s side  
**File number (CNB):** 042  
Address: 43 45 47 Broad  
Print: X  
Negative:  
Description: nw corner  
**File number (CNB):** 043  
Address: 49 Broad  
Print: X  
Negative:  
Description: n side  
**File number (CNB):** 044  
Address: 49 Broad  
Print: X  
Negative:  
Description: ne corner  
**File number (CNB):** 044.1 (1)  
Address: 49 Broad  
Print:  
Negative: X  
Description: Northside, 2nd flr railing, probably before 1770  
**File number (CNB):** 044.1 (2)  
Address: 49 Broad  
Print:  
Negative: X  
Description: Northside, 2nd flr railing, probably before 1770  
**File number (CNB):** 044.1 (3)  
Address: 49 Broad  
Print:  
Negative: X  
Description: Northside, 2nd flr railing, probably before 1770  
**File number (CNB):** 044.2 (1)  
Address: 49 Broad  
Print:  
Negative: X  
Description: Balcony support  
**File number (CNB):** 044.2 (2)

Address: 49 Broad

Print:

Negative: X

Description: Balcony support

**File number (CNB):** 045

Address: 50 Broad

Print: X

Negative:

Description: e side

**File number (CNB):** 046

Address: 50 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 047

Address: 50 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB):** 047.1

Address: 50 Broad

Print:

Negative: X

Description: c.1776 (Evening Post 9/11/68); Southside, west pass gate, east gate similar, c.1967; copy of original ironwork showing on early drawings but disappeared between 1886 and 1916 (Sonn)

**File number (CNB):** 047.2

Address: 50 Broad

Print:

Negative: X

Description: Southside, entry ironwork c.1967; copy of original shown on early drawings, which disappeared between 1886 and 1916

**File number (CNB):** 048

Address: 51-53 Broad

Print: X

Negative:

Description: n side

**File number (CNB):** 048.1 (1)

Address: 53 Broad

Print:

Negative: X

Description: East gate, cut down to fit opening; compare with 6 Tradd #908. These two were a pair of gates formerly between 179 and 181 Meeting

**File number (CNB):** 048.1 (2)

Address: 53 Broad

Print:

Negative: X

Description: East gate, cut down to fit opening; compare with 6 Tradd #908. These two were a pair of gates formerly between 179 and 181 Meeting

**File number (CNB):** 048.2

Address: 53 Broad

Print:

Negative: X

Description: West gate

**File number (CNB):** 049

Address: 54 Broad

Print: X

Negative:

Description: SE corner

**File number (CNB):** 049.1

Address: 54 Broad

Print:

Negative: X

Description: Balcony

**File number (CNB):** 049.2

Address: 54 1/2 Broad

Print:

Negative: X

Description: Southgate from north side; gate altered to fit opening; lattice at bottom appears not to be original

**File number (CNB):** 050

Address: 60-64 Broad

Print: X

Negative:

Description: S side

**File number (CNB):** 050.1

Address: 60-64 Broad

Print:

Negative: X

Description: Dormer detail

**File number (CNB):** 051

Address: 60-64 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB):** 52

Address: 60-64 Broad

Print: X

Negative:

Description: courtyard E side

**File number (CNB):** 53

Address: 60-64 Broad

Print: X

Negative:

Description: portico entry

**File number (CNB):** 54

Address: 60-64 Broad

Print: X

Negative:

Description: courtyard N side

**File number (CNB):** 55

Address: 60-64 Broad

Print: X

Negative:

Description: main entry s side

**File number (CNB):** 56

Address: 60-64 Broad

Print: X

Negative:

Description: courtyard SE corner

**File number (CNB):** 56.1

Address: 60-64 Broad

Print:

Negative: X

Description: Southside- 2nd flr, east railing. All railings this building probably by same artisan as 23 King (851) before Revolution (Sonn) and not original to building

**File number (CNB):** 056.2 (1)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside - 2nd flr, east railing detail

**File number (CNB):** 056.2 (2)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside - 2nd flr, east railing detail

**File number (CNB):** 056.2 (3)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside - 2nd flr, east railing detail

**File number (CNB):** 056.2 (4)

Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, east railing detail  
**File number (CNB):** 056.2 (5)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside -2nd flr, east railing detail  
**File number (CNB):** 056.2 (6)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside -2nd flr, east railing detail  
**File number (CNB):** 056.3  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside- 2nd flr, window railing  
**File number (CNB):** 056.4 (1)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, west railing detail  
**File number (CNB):** 056.4 (2)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, west railing detail  
**File number (CNB):** 056.4 (3)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, west railing detail  
**File number (CNB):** 056.4 (4)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, west railing detail  
**File number (CNB):** 056.4 (5)  
Address: 60-64 Broad

Print:  
Negative: X  
Description: Southside - 2nd flr, west railing detail  
**File number (CNB):** 056.4 (6)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside - 2nd flr, west railing detail

**File number (CNB):** 056.5 (1)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside- 2nd flr, balcony support

**File number (CNB):** 056.5 (2)

Address: 60-64 Broad

Print:

Negative: X

Description: Southside- 2nd flr, balcony support

**File number (CNB):** 057

Address: 63 Broad

Print: X

Negative:

Description: N side

**File number (CNB):** 058

Address: 68 Broad

Print: X

Negative:

Description: house NE corner

**File number (CNB):** 059

Address: 68 Broad

Print: X

Negative:

Description: dependency NW corner

**File number (CNB):** 060

Address: 68 Broad

Print: X

Negative:

Description: " SW "

**File number (CNB):** 060.1

Address: 68 Broad

Print:

Negative: X

Description: Gate and right (East) side pier c.1935-44 to replace wood gate and pier

**File number (CNB):** 060.2

Address: 68 Broad

Print:

Negative: X

Description: House, southside, balcony

**File number (CNB): 061**

Address: 80 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 061.1**

Address: 80 Broad

Print:

Negative: X

Description: Southeast corner - roof detail, c1882

**File number (CNB): 062**

Address: 80 Broad

Print: X

Negative:

Description: nw corner

**File number (CNB): 062.1**

Address: 80 Broad

Print: X

Negative:

Description: ground flr entry

**File number (CNB): 062.2**

Address: 80 Broad

Print: X

Negative:

Description: first flr entry

**File number (CNB): 062.3**

Address: 80 Broad

Print: X

Negative:

Description: pediment & 2nd flr details

**File number (CNB): 062.4**

Address: 80 Broad

Print: X

Negative:

Description: nw corner detail 2nd flr

**File number (CNB): 062.5**

Address: 80 Broad

Print:

Negative: X

Description: Southside, 1st floor, entry and window

**File number (CNB): 063**

Address: 82-86 Broad

Print: X

Negative:



Description: sw corner s side is remains of 1790s building altered

**File number (CNB): 064**

Address: 83 Broad

Print: X

Negative:

Description: NE corner

**File number (CNB): 065**

Address: 83 Broad

Print: X

Negative:

Description: e side

**File number (CNB): 066**

Address: 83 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 066.1**

Address: 83 Broad

Print:

Negative: X

Description: Southside, original building with later additions removed

**File number (CNB): 067**

Address: 83 Broad

Print: X

Negative:

Description: nw corner

**File number (CNB): 068**

Address: 83 Broad

Print: X

Negative:

Description: from NW

**File number (CNB): 068.1**

Address: 83-89 Broad

Print:

Negative: X

Description: left to right- from Northwest

**File number (CNB): 069**

Address: 85-87 Broad

Print: X

Negative:

Description: n side before 1977 remodel

**File number (CNB): 070**

Address: 85-87 Broad

Print: X

Negative:

Description: s side original wall with later additions stripped

**File number (CNB):** 070.1

Address: 85-87 Broad

Print: X

Negative:

Description: e side before 1977 remodel

**File number (CNB):** 070.2

Address: 85-87 Broad

Print: X

Negative:

Description: s side roof framing exposed after 1978 fire

**File number (CNB):** 070.3

Address: 85-87 Broad

Print: X

Negative: X

Description: Southside, roof framing; note in lower left corner 1x2, 4" [IOG?], furring strips under roof sheathing perpendicular to rafters; furring strips run under dormer cheek sheathing

**File number (CNB):** 071

Address: 92 Broad

Print: X

Negative:

Description: s side

**File number (CNB):** 071

Address: 92 Broad

Print: X

Negative:

Description: slightly different angle than first CNB 071

**File number (CNB):** 071.1 (1)

Address: 92 Broad

Print:

Negative: X

Description: Westside

**File number (CNB):** 071.1 (2)

Address: 92 Broad

Print:

Negative: X

Description: Westside

**File number (CNB):** 072

Address: 92 Broad

Print: X

Negative:

Description: w side

**File number (CNB):** 072.1

Address: 92 Broad

Print:

Negative: X

Description: Northside

**File number (CNB): 072.2**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southwest room, north wall

**File number (CNB): 072.3**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southwest room, north wall chimney piece

**File number (CNB): 072.4**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southwest, mantle

**File number (CNB): 072.5**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southeast, north wall

**File number (CNB): 072.6**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southeast room, mantle. Shelf & cove mould not original

**File number (CNB): 072.7**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - southeast room, looking northwest to include southwest room

**File number (CNB): 072.8**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr- southeast room, east wall showing brick wall of adjacent building

**File number (CNB): 072.9**

Address: 92 Broad

Print:

Negative: X

Description: 1st flr - northwest room, small, mantle shelf not original

**File number (CNB):** 072.10

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - stair hall, looking south. Arch not original to house

**File number (CNB):** 072.11

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr- hall looking northeast, showing original cornice in room which was cut down to form stair hall from 2 to 3 floor

**File number (CNB):** 072.12

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southwest room, north wall

**File number (CNB):** 072.13

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southwest room, east wall

**File number (CNB):** 072.14

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southwest room, south wall

**File number (CNB):** 072.15

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southwest room, north wall chimney piece, note false returns in cornice

**File number (CNB):** 072.16

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southwest room, mantle, cornice not original

**File number (CNB):** 072.17

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southeast room, north wall, mantle shelf & cornice not original

**File number (CNB):** 072.18

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - southeast room, east wall, framing original

**File number (CNB):** 072.19

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr- southeast room, east wall, door detail of adjoining building

**File number (CNB):** 072.20

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - northeast room, south wall, mantle shelf not original

**File number (CNB):** 072.21

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr- northeast room, looking at northeast corner and east window

**File number (CNB):** 072.22

Address: 92 Broad

Print:

Negative: X

Description: 2nd flr - northwest room, south wall, mantle shelf & cornice not original

**File number (CNB):** 072.23

Address: 92 Broad

Print:

Negative: X

Description: 3rd flr - southwest room, looking north, note chair rail blocking door

**File number (CNB):** 072.24

Address: 92 Broad

Print:

Negative: X

Description: 3rd flr- southwest room, south wall

**File number (CNB):** 072.25

Address: 92 Broad

Print:

Negative: X

Description: 3rd flr - southeast room looking northeast

**File number (CNB):** 072.26

Address: 92 Broad

Print:

Negative: X

Description: 3rd flr - northwest room, looking southeast showing chimney const. in both chimneys

**File number (CNB):** 072.27

Address: 92 Broad

Print:

Negative: X

Description: 3rd flr - northeast room looking northeast showing window in east wall. 3rd flr not original to house

**File number (CNB): 073**

Address: 93 Broad

Print: X

Negative:

Description: n side

**File number (CNB): 074**

Address: 95 Broad

Print: X

Negative:

Description: ne corner

**File number (CNB): 074.1**

Address: 95 Broad

Print: X

Negative:

Description: entry

**File number (CNB): 075**

Address: 102 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB): 076**

Address: 102 Broad

Print: X

Negative:

Description: entry

**File number (CNB): 077**

Address: 110 Broad

Print: X

Negative:

Description: house SE corner

**File number (CNB): 077.1**

Address: 110 Broad

Print:

Negative: X

Description: Southside balcony

**File number (CNB): 078**

Address: 110 Broad

Print: X

Negative:

Description: house e corner

**File number (CNB): 079**

Address: 110 Broad

Print: X

Negative:

Description: " se corner

**File number (CNB): 079.1**

Address: 110 Broad

Print: X

Negative:

Description: kitchen s side affter removal of passage to house

**File number (CNB): 079.2**

Address: 110 Broad

Print: X

Negative:

Description: house, n side, top of wdw

**File number (CNB): 080**

Address: 110 Broad

Print: X

Negative:

Description: house 1st flr sw room n wall

**File number (CNB): 081**

Address: 110 Broad

Print: X

Negative:

Description: ktichen SE corner

**File number (CNB): 082**

Address: 110 Broad

Print: X

Negative:

Description: SW corner

**File number (CNB): 082.1**

Address: 110 Broad

Print: X

Negative:

Description: house n side after removal of passage to house

**File number (CNB): 082.2**

Address: 110 Broad

Print: X

Negative:

Description: kitchen s side

**File number (CNB): 083**

Address: 110 Broad

Print: X

Negative:

Description: kitchen interior 1st flr se corner room before stucco removal

**File number (CNB): 084**

Address: 110 Broad

Print: X

Negative:

Description: "" after stucco removal

**File number (CNB): 085**

Address: 110 Broad

Print: X

Negative:

Description: kitchen interior w wall

**File number (CNB): 085.1**

Address: 110 Broad

Print: X

Negative:

Description: " oven detail

**File number (CNB): 086**

Address: 110 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB): 087**

Address: 110 Broad

Print: X

Negative:

Description: carriage house s side

**File number (CNB): 087.1**

Address: 110 Broad

Print: X

Negative:

Description: all buildings n side

**File number (CNB): 087.2**

Address: 110 Broad

Print: X

Negative:

Description: privy, SE corner reconstructed

**File number (CNB): 088**

Address: 110 Broad

Print: X

Negative:

Description: house SW corner

**File number (CNB): 089**

Address: 110 Broad

Print: X



Negative:

Description: w side

**File number (CNB):** 090

Address: 110 Broad

Print: X

Negative:

Description: N side

**File number (CNB):** 091 H

Address: 116 Broad

Print: X

Negative:

Description: s side entry

**File number (CNB):** 091 V

Address: 116 Broad

Print: X

Negative:

Description:

**File number (CNB):** 091.1

Address: 116 Broad

Print: X

Negative:

Description: s side entry pediment detail

**File number (CNB):** 092

Address: 116 Broad

Print: X

Negative:

Description: s side ground flr wdw

**File number (CNB):** 093

Address: 116 Broad

Print: X

Negative:

Description: " portico, corner column ground work

**File number (CNB):** 093.1 (1)

Address: 116 Broad

Print:

Negative: X

Description: House, southside, 2nd floor balcony

**File number (CNB):** 093.1 (2)

Address: 116 Broad

Print:

Negative: X

Description: House, southside, 2nd floor balcony

**File number (CNB):** 093.2

Address: 116 Broad

Print:

Negative: X

Description: House, southside cornice and console

**File number (CNB):** 093.3

Address: 116 Broad

Print:

Negative: X

Description: House, southside 1st floor balcony support

**File number (CNB):** 094

Address: 116 Broad

Print: X

Negative:

Description: house sw corner

**File number (CNB):** 094.1

Address: 116 Broad

Print: X

Negative:

Description: " sheet metal quoins

**File number (CNB):** 095

Address: 116 Broad

Print: X

Negative:

Description: house rear porch w side

**File number (CNB):** 096

Address: 116 Broad

Print: X

Negative:

Description: n side

**File number (CNB):** 096.1

Address: 116 Broad

Print: X

Negative:

Description: house sw corner

**File number (CNB):** 097

Address: 116 Broad

Print: X

Negative:

Description: carriage house n side

**File number (CNB):** 098

Address: 116 Broad

Print: X

Negative:

Description: carriage house s side

**File number (CNB):** 098.1

Address: 116 Broad

Print: X

Negative:

Description: " e side

**File number (CNB):** 099

Address: 117 Broad

Print: X

Negative:

Description: nw corner

**File number (CNB):** 099.1

Address: 117 Broad

Print:

Negative: X

Description: Entry detail, not original to house

**File number (CNB):** 099.2 (1)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB):** 099.2 (2)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB):** 099.2 (3)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB):** 099.2 (4)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB):** 099.2 (5)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB):** 099.2 (6)

Address: 117 Broad

Print:

Negative: X

Description: Center iron work detail

**File number (CNB): 099.3**

Address: 117 Broad

Print:

Negative: X

Description: Fence detail, northside

**File number (CNB): 100**

Address: 119 Broad

Print: X

Negative:

Description: n side

**File number (CNB): 101**

Address: 119 Broad

Print: X

Negative:

Description: Entry detail

**File number (CNB): 102**

Address: 122 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 103**

Address: 122 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB): 104**

Address: 122 Broad

Print: X

Negative:

Description: ne corner

**File number (CNB): 105**

Address: 122 Broad

Print: X

Negative:

Description: n side

**File number (CNB): 106**

Address: 125 Broad

Print: X

Negative:

Description: n side

**File number (CNB): 107**

Address: 125 Broad

Print: X

Negative:

Description: w side

**File number (CNB): 108**

Address: 158 Broad

Print: X

Negative:

Description: se corner

**File number (CNB): 108.1**

Address: 158 Broad

Print: X

Negative:

Description: s side

**File number (CNB): 109**

Address: 160 Broad

Print: X

Negative:

Description: nw corner

**File number (CNB): 110**

Address: 167 Broad

Print: X

Negative:

Description: nw corner

**File number (CNB): 111**

Address: 170 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB): 112**

Address: 180 Broad

Print: X

Negative:

Description: se corner

**File number (CNB): 113**

Address: 180 Broad

Print: X

Negative:

Description: sw corner

**File number (CNB): 114**

Address: Annandale Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 115**

Address: Annandale Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 116**

Address: Annandale Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 117**

Address: Annandale Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 118**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 119**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 120**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 121**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 122**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 123**

Address: Arcadia Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 124**

Address: Arcadia Plantation

Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 125**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 126**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 127**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 128**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 129**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 130**  
Address: Arcadia Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 131**  
Address: Beneventum Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 132**  
Address: Beneventum Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 133**

Address: Beneventum Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 134

Address: Beneventum Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 135

Address: Cat Island Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 136

Address: Cat Island Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 137

Address: Chicora Wood Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 137.1

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Georgetown Co.; c1819. House, southwest corner

**File number (CNB):** 138

Address: Chicora Wood Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB):** 138.1

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Chicora Wood Plantation - c1819. House, southside

**File number (CNB):** 138.2

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Chicora Wood Plantation - c1819. House, southeast side



**File number (CNB): 139**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 139.1**

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Chicora Wood Plantation - House, northside - chimneys & dormers reconstructed, also windows on northside of 1 1/2 storey wing to original locations determined by framing

**File number (CNB): 139.2**

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Chicora Wood Plantation - House, westside

**File number (CNB): 140**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 140.1**

Address: Chicora Wood Plantation

Print:

Negative: X

Description: Chicora Wood Plantation - House, northeast side

**File number (CNB): 141**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 142**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 143**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 144**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 145**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 146**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 147**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 148**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 149**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 150**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 151**

Address: Chicora Wood Plantation

Print: X

Negative:

Description:

**File number (CNB): 152**

Address: Dirleton Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 153**

Address: Dirleton Plantation

Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 154**  
Address: Dirleton Plantation  
Print: X  
Negative:  
Description: interior doors; two #154s but this prob. Dirleton  
**File number (CNB): 154**  
Address: Hopsewee Plantation  
Print: X  
Negative:  
Description: Georgetown County; outbuilding  
**File number (CNB): 155**  
Address: Hopsewee Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 156**  
Address: Hopsewee Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 157**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 158**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 159**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 160**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 161**

Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 162**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 163**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 164**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 165**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 166**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 167**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 168**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County  
**File number (CNB): 169**  
Address: Mansfield Plantation  
Print: X  
Negative:  
Description: Georgetown County

**File number (CNB): 170**

Address: Mansfield Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 171**

Address: Mansfield Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 172**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 173**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 174**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 175**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 176**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 177**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 178**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 179**

Address: Wicklow Hall Plantation

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 180**

Address: Prince Frederick Church

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 181**

Address: Prince Frederick Church

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 182**

Address: Prince Frederick Church

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 182.1**

Address: Prince Frederick Church

Print: X

Negative:

Description: Georgetown County

**File number (CNB): 183**

Address: 80 Broad

Print: X

Negative:

Description:

**File number (CNB): 184**

Address: 80 Broad

Print: X

Negative:

Description:

**File number (CNB): 185**

Address: 80 Broad

Print: X

Negative:

Description:

**File number (CNB): 185.1**

Address: 80 Broad

Print: X

Negative:

Description:

**File number (CNB):** 185.2

Address: 80 Broad

Print: X

Negative:

Description:

**File number (CNB):** 185.3

Address: 80 Broad

Print:

Negative: X

Description: Northside - Palladian window detail

**File number (CNB):** 185.4

Address: 80 Broad

Print:

Negative: X

Description: Northwest corner including St. Michael's church

**File number (CNB):** 185.5 (1)

Address: 80 Broad

Print:

Negative: X

Description: 1st flr- entry, looking north to treasurer's office, c.1882

**File number (CNB):** 185.5 (2)

Address: 80 Broad

Print:

Negative: X

Description: 1st flr- entry, looking north to treasurer's office, c.1882

**File number (CNB):** 185.6

Address: 80 Broad

Print:

Negative: X

Description: 1st flr - stair hall, looking east, c1882

**File number (CNB):** 185.7

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Council Chambers looking east, c1882-1886

**File number (CNB):** 185.8 (1)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Council Chambers looking west, c1882 & 1886

**File number (CNB):** 185.8 (2)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Council Chambers looking west, c1882 & 1886

**File number (CNB):** 185.9

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr- Council Chambers, balcony railing from Academy of Music installed 1882

**File number (CNB):** 185.10

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr- Council Chamber, painting of "Officers of the Volunteer Fire Department, Charleston SC, 1841" by Christian Meyr. Note City Hall at extreme right of brick with marble trim

**File number (CNB):** 185.11 (1)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Mayor's office - looking north, wood work, c1882

**File number (CNB):** 185.11 (2)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Mayor's office - looking north, wood work, c1882

**File number (CNB):** 185.11 (3)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Mayor's office - looking north, wood work, c1882

**File number (CNB):** 185.11 (4)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr - Mayor's office - looking north, wood work, c1882

**File number (CNB):** 185.12 (1)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr- Mayor's office, north wall

**File number (CNB):** 185.12 (2)

Address: 80 Broad

Print:

Negative: X

Description: 2nd flr- Mayor's office, north wall



**File number (CNB): 185.13**

Address: 80 Broad

Print:

Negative: X

Description: Stair landing, between 1st and 2nd floors, window guard

**File number (CNB): 186**

Address: 101-107 Bull

Print: X

Negative:

Description:

**File number (CNB): 186.1**

Address: 101-107 Bull

Print: X

Negative:

Description:

**File number (CNB): 187**

Address: 101-107 Bull

Print: X

Negative:

Description:

**File number (CNB): 188**

Address: 19 Church

Print: X

Negative:

Description:

**File number (CNB): 188.1 (1)**

Address: 19 Church

Print:

Negative: X

Description: Garden gate

**File number (CNB): 188.1 (2)**

Address: 19 Church

Print:

Negative: X

Description: Garden gate

**File number (CNB): 189**

Address: 20 Church

Print: X

Negative:

Description:

**File number (CNB): CHB 190**

Address: 20 Church

Print: X

Negative:

Description:

**File number (CNB):** 190.1 (1)

Address: 20 Church

Print:

Negative: X

Description: Westside, half carriage gate and entire gate

**File number (CNB):** 190.1 (2)

Address: 20 Church

Print:

Negative: X

Description: Westside, half carriage gate and entire gate

**File number (CNB):** 191

Address: 35 Church

Print: X

Negative:

Description:

**File number (CNB):** 191.1

Address: 35 Church

Print:

Negative: X

Description: Basement window gate

**File number (CNB):** 191.2

Address: 35 Church

Print:

Negative: X

Description: Southside, balcony

**File number (CNB):** 192

Address: 37 Church

Print: X

Negative:

Description:

**File number (CNB):** 193

Address: 38 Church

Print: X

Negative:

Description:

**File number (CNB):** 194

Address: 38 Church

Print: X

Negative:

Description:

**File number (CNB):** 194.1

Address: 38 Church

Print:

Negative: X  
Description: Carriage and pass gate with fence  
**File number (CNB):** 195

Address: 38 Church

Print: X

Negative:

Description:

**File number (CNB):** 195.1 (1)

Address: 38 Church

Print:

Negative: X

Description: Garden pass gate

**File number (CNB):** 195.1 (2)

Address: 38 Church

Print:

Negative: X

Description: Garden pass gate

**File number (CNB):** 196

Address: 39 Church

Print: X

Negative:

Description:

**File number (CNB):** 197

Address: 39 Church

Print: X

Negative:

Description:

**File number (CNB):** 197.1

Address: 39 Church

Print:

Negative: X

Description: Carriage gate, after 1916

**File number (CNB):** 198

Address: 59 Church

Print: X

Negative:

Description: se corner

**File number (CNB):** 199

Address: 59 Church

Print: X

Negative:

Description: n side

**File number (CNB):** 200

Address: 59 Church

Print: X

Negative:

Description: e side entry

**File number (CNB): 201**

Address: 61 Church

Print: X

Negative:

Description: sw corner

**File number (CNB): 202**

Address: 61 Church

Print: X

Negative:

Description: e side south end entry

**File number (CNB): 202.2**

Address: 61 Church

Print: X

Negative:

Description: e side

**File number (CNB): 202.3**

Address: 61 Church

Print:

Negative: X

Description: Double entry gate - center, from east. South gate, same

**File number (CNB): 202.4**

Address: 61 Church

Print:

Negative: X

Description: Lamp standard and single pass gate; lamp not original

**File number (CNB): 203**

Address: 69 Church

Print: X

Negative:

Description: house se corner

**File number (CNB): 204**

Address: 69 Church

Print: X

Negative:

Description: house w side, kitchen on left

**File number (CNB): 205**

Address: 69 Church

Print: X

Negative:

Description: kitchen & slave quarters s side

**File number (CNB): 206**

Address: 69 Church

Print: X

Negative:

Description: "" SW corner

**File number (CNB): 207**

Address: 69 Church

Print: X

Negative:

Description: privy (L), laundry (R) S side

**File number (CNB): 208**

Address: 69 Church

Print: X

Negative:

Description: stable ruins e side roof and left wall in foreground

**File number (CNB): 209**

Address: 71 Church

Print: X

Negative:

Description: SE corner

**File number (CNB): 209.1**

Address: 71 Church

Print: X

Negative:

Description: brick and cornice detail

**File number (CNB): 209.2**

Address: 71 Church

Print: X

Negative:

Description: s side

**File number (CNB): 209.3**

Address: 71 Church

Print: X

Negative:

Description: entry

**File number (CNB): 209.4**

Address: 71 Church

Print: X

Negative:

Description: 1st flr e room n wall mantel and cornice 1800

**File number (CNB): 209.5**

Address: 71 Church

Print: X

Negative:

Description: 1st flr e room mantel

**File number (CNB): 209.6**

Address: 71 Church

Print: X

Negative:

Description: " cornice

**File number (CNB): 209.7**

Address: 71 Church

Print: X

Negative:

Description: 2nd flr e room n wall mantel and cornice 1800

**File number (CNB): 209.8**

Address: 71 Church

Print: X

Negative:

Description: " mantel

**File number (CNB): 209.9**

Address: 71 Church

Print: X

Negative:

Description: "cornice

**File number (CNB): 209.10**

Address: 71 Church

Print: X

Negative:

Description: 2nd flr w room n wall

**File number (CNB): 209.11**

Address: 71 Church

Print:

Negative: X

Description: c.1730; eastside balcony detail, probably of 1800 refurbishing of house

**File number (CNB): 209.12**

Address: 71 Church

Print:

Negative: X

Description: Southeast corner, original building cornice

**File number (CNB): 209.13**

Address: 71 Church

Print:

Negative: X

Description: Southwest corner, original building cornice

**File number (CNB): 209.14**

Address: 71 Church

Print:

Negative: X

Description: Westside, original house; southside, first addition, probably c.1800 (on left)

**File number (CNB):** 209.15 (1)

Address: 71 Church

Print:

Negative: X

Description: Southwest cornice, corner detail, exterior corner

**File number (CNB):** 209.15 (2)

Address: 71 Church

Print:

Negative: X

Description: Southwest cornice, corner detail, exterior corner

**File number (CNB):** 209.16

Address: 71 Church

Print:

Negative: X

Description: Southwest cornice, interior corner

**File number (CNB):** 210

Address: 76 Church

Print: X

Negative:

Description: sw corner

**File number (CNB):** 211

Address: 78 Church

Print: X

Negative:

Description: NW corner

**File number (CNB):** 211.1 (1)

Address: 78 Church

Print:

Negative: X

Description: before 1791, west side, balcony

**File number (CNB):** 211.1 (2)

Address: 78 Church

Print:

Negative: X

Description: before 1791, west side, balcony

**File number (CNB):** 211.2

Address: 78 Church

Print:

Negative: X

Description: Center bay of balcony

**File number (CNB):** 211.3

Address: 78 Church

Print:

Negative: X

Description: Balcony from south

**File number (CNB):** 211.4

Address: 78 Church

Print:

Negative: X

Description: Balcony, southside bracket and railing detail

**File number (CNB):** 211.5 (1)

Address: 78 1/2 Church

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 211.5 (2)

Address: 78 1/2 Church

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 212

Address: 83-85 Church

Print: X

Negative:

Description: Se corner

**File number (CNB):** 212.1

Address: 83-85 Church

Print:

Negative: X

Description: Transom grille

**File number (CNB):** 213

Address: 86 Church

Print: X

Negative:

Description: House nw Corner

**File number (CNB):** 214

Address: 86 Church

Print: X

Negative:

Description: south dependency NW corner

**File number (CNB):** 215

Address: 86 Church

Print: X

Negative:

Description: N dependency s side

**File number (CNB):** 215.1

Address: 86 Church



Print: X  
Negative:  
Description: N dependency interior of w entry in s side  
**File number (CNB):** 215.2  
Address: 86 Church  
Print: X  
Negative:  
Description: " n wall of kitchen from w entry s side  
**File number (CNB):** 215.3  
Address: 86 Church  
Print: X  
Negative:  
Description: " n wall of kitchen from entry  
**File number (CNB):** 216  
Address: 87 Church  
Print: X  
Negative:  
Description: e side copy of photo from 1883  
**File number (CNB):** 217  
Address: 87 Church  
Print: X  
Negative:  
Description: e side when house was a bakery  
**File number (CNB):** 217.1  
Address: 87 Church  
Print: X  
Negative:  
Description: e side 1977  
**File number (CNB):** 217.2  
Address: 87 Church  
Print:  
Negative: X  
Description: c.1883- Eastside - from the "Georgian Period"  
**File number (CNB):** 217.3 (1)  
Address: 87 Church  
Print:  
Negative: X  
Description: House - eastside roof  
**File number (CNB):** 217.3 (2) small  
Address: 87 Church  
Print:  
Negative: X  
Description: House - eastside roof  
**File number (CNB):** 217.3 (3) small

Address: 87 Church

Print:

Negative: X

Description: House - eastside roof

**File number (CNB):** 217.4 (1)

Address: 87 Church

Print:

Negative: X

Description: House excavations - eastside. Brick foundations of pre-1740 John Milner frame house, east of southeast corner of extant 1770 house, looking down.

**File number (CNB):** 217.4 (2) small

Address: 87 Church

Print:

Negative: X

Description: House excavations - eastside. Brick foundations of pre-1740 John Milner frame house, east of southeast corner of extant 1770 house, looking down.

**File number (CNB):** 217.5 (1)

Address: 87 Church

Print:

Negative: X

Description: Same as 217.4, except looking north

**File number (CNB):** 217.5 (2) small

Address: 87 Church

Print:

Negative: X

Description: Same as 217.4, except looking north

**File number (CNB):** 217.5a (1)

Address: 87 Church

Print:

Negative: X

Description: Same as 217.4, except looking southast

**File number (CNB):** 217.5a (2) small

Address: 87 Church

Print:

Negative: X

Description: Same as 217.4, except looking southast

**File number (CNB):** 217.5a (3) small

Address: 87 Church

Print:

Negative: X

Description: Same as 217.4, except looking southast

**File number (CNB):** 217.6 (1)

Address: 87 Church

Print:

Negative: X

Description: House excavations - eastside. Brick steps with wood treads from foundation of 1740 John Milner brick house, east of northeast corner of extant 1770 house, looking northeast. Note recess in brick stair wing wall for wood treads

**File number (CNB):** 217.6 (2) small

Address: 87 Church

Print:

Negative: X

Description: House excavations - eastside. Brick steps with wood treads from foundation of 1740 John Milner brick house, east of northeast corner of extant 1770 house, looking northeast. Note recess in brick stair wing wall for wood treads

**File number (CNB):** 217.6 (3) small

Address: 87 Church

Print:

Negative: X

Description: House excavations - eastside. Brick steps with wood treads from foundation of 1740 John Milner brick house, east of northeast corner of extant 1770 house, looking northeast. Note recess in brick stair wing wall for wood treads

**File number (CNB):** 217.6a (1)

Address: 87 Church

Print:

Negative: X

Description: Same as 217.6, except looking east

**File number (CNB):** 217.6a (2) small

Address: 87 Church

Print:

Negative: X

Description: Same as 217.6, except looking east

**File number (CNB):** 217.7 (1)

Address: 87 Church

Print:

Negative: X

Description: House - basement. South chimney from east

**File number (CNB):** 217.7 (2) small

Address: 87 Church

Print:

Negative: X

Description: House - basement. South chimney from east

**File number (CNB):** 217.7a (1)

Address: 87 Church

Print:

Negative: X

Description: House - basement. South chimney from west

**File number (CNB):** 217.7a (2) small

Address: 87 Church

Print:

Negative: X

Description: House - basement. South chimney from west

**File number (CNB):** 217.8

Address: 87 Church

Print:

Negative: X

Description: House- 1st flr, southwest room, west wall

**File number (CNB):** 217.9

Address: 87 Church

Print:

Negative: X

Description: House - 1st flr. Northwest room, west wall

**File number (CNB):** 217.10

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall, measured drawing room from "The Georgian Period"

**File number (CNB):** 217.11 (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall, door to hall

**File number (CNB):** 217.11 (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall, door to hall

**File number (CNB):** 217.11a (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall chimney piece fret, mahogany

**File number (CNB):** 217.11a (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall chimney piece fret, mahogany

**File number (CNB):** 217.11b (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall, chimney piece cornice

**File number (CNB):** 217.11b(2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, west wall, chimney piece cornice

**File number (CNB):** 217.11c (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, south wall, typical cornice return over all windows

**File number (CNB):** 217.11c (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, south wall, typical cornice return over all windows

**File number (CNB):** 217.12 (1)

Address: 87 Church

Print:

Negative: X

Description: 2nd flr - Southeast room, west wall mantle fret

**File number (CNB):** 217.12 (2) small

Address: 87 Church

Print:

Negative: X

Description: 2nd flr - Southeast room, west wall mantle fret

**File number (CNB):** 217.12a (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, mantle console

**File number (CNB):** 217.12a (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, mantle console

**File number (CNB):** 217.12a (3) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, mantle console

**File number (CNB):** 217.12b (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southwest room, mantle, center freize block

**File number (CNB):** 217.12b (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southwest room, mantle, center freize block

**File number (CNB):** 217.12b (3) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southwest room, mantle, center freize block

**File number (CNB):** 217.13 (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, typical cornice intersection, also showing west wall door pediment & chimney piece returns

**File number (CNB):** 217.13 (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, typical cornice intersection, also showing wet wall door pediment & chimney piece returns

**File number (CNB):** 217.13a (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, cornice intersection of east & south walls, showing typical cornice return over window

**File number (CNB):** 217.13a (2) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Southeast room, cornice intersection of east & south walls, showing typical cornice return over window

**File number (CNB):** 217.14 (1)

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Northeast room, Holmes breakfront. Carved wood basket & loose wood flowers from pediment, mahogany

**File number (CNB):** 217.14 (2) double - small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Northeast room, Holmes breakfront. Carved wood basket & loose wood flowers from pediment, mahogany

**File number (CNB):** 217.14 (3) double - small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Northeast room, Holmes breakfront. Carved wood basket & loose wood flowers from pediment, mahogany

**File number (CNB):** 217.14 (4) small

Address: 87 Church

Print:

Negative: X

Description: House - 2nd flr. Northeast room, Holmes breakfront. Carved wood basket & loose wood flowers from pediment, mahogany

**File number (CNB):** 217.15

Address: 87 Church

Print:

Negative: X

Description: House- 2nd flr, southwest room, east wall

**File number (CNB):** 217.16 (1)

Address: 87 Church

Print:

Negative: X

Description: House- 2nd flr, northwest room, east wall; at the intersection of east and north wall there was uncovered a strip of original wood graining which once covered the entire east wall when built c.1770

**File number (CNB):** 217.16 (2)

Address: 87 Church

Print:

Negative: X

Description: House- 2nd flr, northwest room, east wall; at the intersection of east and north wall there was uncovered a strip of original wood graining which once covered the entire east wall when built c.1770

**File number (CNB):** 217.17 (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. Northwest hip rafter at wall bearing

**File number (CNB):** 217.17 (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. Northwest hip rafter at wall bearing

**File number (CNB):** 217.17a (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. Northwest hip rafter at midpoint

**File number (CNB):** 217.17a (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. Northwest hip rafter at midpoint

**File number (CNB):** 217.17b (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from northeast. Note iron wedge in iron strapping

**File number (CNB):** 217.17b (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from northeast. Note iron wedge in iron strapping

**File number (CNB):** 217.17c (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from east

**File number (CNB):** 217.17c (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from east

**File number (CNB):** 217.17d (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from southeast

**File number (CNB):** 217.17d (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post base from southeast

**File number (CNB):** 217.17e (1)

Address: 87 Church

Print:



Negative: X

Description: House - attic. East king post top from northeast

**File number (CNB):** 217.17e (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post top from northeast

**File number (CNB):** 217.17f (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post top, from southwest, showing ridge rafter

**File number (CNB):** 217.17f (2)

Address: 87 Church

Print:

Negative: X

Description: House - attic. East king post top, from southwest, showing ridge rafter

**File number (CNB):** 217.17g (1)

Address: 87 Church

Print:

Negative: X

Description: House - attic. North chimney framing from southeast

**File number (CNB):** 217.17g (2) small

Address: 87 Church

Print:

Negative: X

Description: House - attic. North chimney framing from southeast

**File number (CNB):** 218

Address: 87 Church

Print: X

Negative:

Description: Se corner

**File number (CNB):** 219

Address: 87 Church

Print: X

Negative:

Description: w side

**File number (CNB):** 220

Address: 87 Church

Print: X

Negative:

Description: kitchen SE corner

**File number (CNB):** 220.1

Address: 87 Church

Print:

Negative: X

Description: Kitchen- southside, west end

**File number (CNB): 220.2**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - Southside, east end

**File number (CNB): 220.3 (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - Southside, well under eats end door

**File number (CNB): 220.3 (2) double - small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - Southside, well under eats end door

**File number (CNB): 220.3 (3) double - small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - Southside, well under eats end door

**File number (CNB): 220.4**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - east side, 2nd flr

**File number (CNB): 220.5**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - northside, at right

**File number (CNB): 220.6**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - west side

**File number (CNB): 221**

Address: 87 Church

Print: X

Negative:

Description: w room laundry and fireplace

**File number (CNB): 222**

Address: 87 Church

Print: X

Negative:

Description: e room w wall

**File number (CNB):** 222.1 (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. Repaired eastside of chimney foundation

**File number (CNB):** 222.1 (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. Repaired eastside of chimney foundation

**File number (CNB):** 222.1 (3) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. Repaired eastside of chimney foundation

**File number (CNB):** 222.1a (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. Repaired westside of chimney foundation

**File number (CNB):** 222.1a (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. Repaired westside of chimney foundation

**File number (CNB):** 222.1b (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. East wall showing bricked up original door to grade (behind stool)

**File number (CNB):** 222.1b (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. East wall showing bricked up original door to grade (behind stool)

**File number (CNB):** 222.1c (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. South wall showing arch in wall, where wall is built over well

**File number (CNB): 222.1c (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. South wall showing arch in wall, where wall is built over well

**File number (CNB): 222.2 (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. South wall, bricked up steps to exterior, 19th century

**File number (CNB): 222.2 (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. South wall, bricked up steps to exterior, 19th century

**File number (CNB): 222.2 (3) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - basement. South wall, bricked up steps to exterior, 19th century

**File number (CNB): 222.3**

Address: 87 Church

Print:

Negative: X

Description: Kitchen- 1st flr, east room, north and east walls; note bricked up window in east wall above electric heater

**File number (CNB): 222.3a (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 1st flr. East room, east wall. Window is one moved from original position, shown in 222.3

**File number (CNB): 222.3a (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 1st flr. East room, east wall. Window is one moved from original position, shown in 222.3

**File number (CNB): 222.3a (3) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 1st flr. East room, east wall. Window is one moved from original position, shown in 222.3

**File number (CNB): 222.4 (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, east wall

**File number (CNB): 222.4 (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, east wall

**File number (CNB): 222.4a (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, north wall

**File number (CNB): 222.4a (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, north wall

**File number (CNB): 222.4b (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room, west wall

**File number (CNB): 222.4b (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room, west wall

**File number (CNB): 222.4c (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room, north wall

**File number (CNB): 222.4c (2) small**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room, north wall

**File number (CNB): 222.5 (1)**

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, looking southwest to stairs

**File number (CNB):** 222.5 (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. East room, looking southwest to stairs

**File number (CNB):** 222.5a (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room looking southeast into stairs

**File number (CNB):** 222.5a (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room looking southeast into stairs

**File number (CNB):** 222.5a (3) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 2nd flr. West room looking southeast into stairs

**File number (CNB):** 222.6 (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. Looking southwest to stairs from east room

**File number (CNB):** 222.6 (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. Looking southwest to stairs from east room

**File number (CNB):** 222.6 (3) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. Looking southwest to stairs from east room

**File number (CNB):** 222.6a (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. West room, looking southeast to stairs

**File number (CNB):** 222.6a (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. West room, looking southeast to stairs

**File number (CNB):** 222.6b (1)

Address: 87 Church

Print:

Negative: X

Description: Kitchen -3rd flr. East room, looking into dormer cheek & door to stairs, southwest

**File number (CNB):** 222.6b (2) small

Address: 87 Church

Print:

Negative: X

Description: Kitchen - 3rd flr. East room, looking into dormer cheek & door to stairs, southwest

**File number (CNB):** 223

Address: 87 Church

Print: X

Negative:

Description: stable 19th c nw corner

**File number (CNB):** 223.1

Address: 87 Church

Print:

Negative: X

Description: Stable- northside, east end

**File number (CNB):** 223.2 (1)

Address: 87 Church

Print:

Negative: X

Description: Stable- northside, west end

**File number (CNB):** 223.2 (2)

Address: 87 Church

Print:

Negative: X

Description: Stable- northside, west end

**File number (CNB):** 223.3

Address: 87 Church

Print:

Negative: X

Description: Stable, westside

**File number (CNB):** 223.4

Address: 87 Church

Print:

Negative: X

Description: Stable, northeast side

**File number (CNB):** 223.5

Address: 87 Church

Print:

Negative: X

Description: Stable - eastside

**File number (CNB): 223.6**

Address: 87 Church

Print:

Negative: X

Description: Stable- southside, center

**File number (CNB): 224**

Address: 87 Church

Print: X

Negative:

Description: privy kitchen & stable from sw

**File number (CNB): 224.1**

Address: 87 Church

Print:

Negative: X

Description: Privy- southeast side, 19th century as rebuilt to conform to original door and vent openings as per brick openings

**File number (CNB): 224.2**

Address: 87 Church

Print:

Negative: X

Description: Privy - southwest side, rebuilt 1982

**File number (CNB): 224.3**

Address: 87 Church

Print:

Negative: X

Description: Privy - northside

**File number (CNB): 224.4**

Address: 87 Church

Print:

Negative: X

Description: Shed - 19th century, southside

**File number (CNB): 224.4a**

Address: 87 Church

Print:

Negative: X

Description: Shed - 19th century, showing intersection of roof with kitchen on west and adjacent house on north

**File number (CNB): 224.5**

Address: 87 Church

Print:

Negative: X



Description: Shed - southeast corner, 19th c

**File number (CNB): 225**

Address: 89-91 Church

Print: X

Negative:

Description: NE corner

**File number (CNB): 225.1**

Address: 89-91 Church

Print: X

Negative: X

Description: Eastside - pre-1930 photograph

**File number (CNB): 225.2**

Address: 89-91 Church

Print: X

Negative: X

Description: Westside, pre-1935, from old photographs

**File number (CNB): 226**

Address: 90 Church

Print: X

Negative:

Description: sw corner

**File number (CNB): 227**

Address: 90 Church

Print: X

Negative:

Description: n side of dependencies

**File number (CNB): 227.1**

Address: 90 Church

Print: X

Negative:

Description: cornice and portico

**File number (CNB): 228**

Address: 92 Church

Print: X

Negative:

Description: sw corner

**File number (CNB): 229**

Address: 92 Church

Print: X

Negative:

Description: NW corner

**File number (CNB): 229.1**

Address: 92 Church

Print: X

Negative:

Description: cornice and portico

**File number (CNB):** 229.2

Address: 92 Church

Print:

Negative: X

Description: Pass and carriage gates; note moulded brick cap and base of brick piers, also recessed panel on left pier to provide pocket for gate

**File number (CNB):** 230

Address: 94 Church

Print: X

Negative:

Description: sw corner

**File number (CNB):** 231

Address: 94 Church

Print: X

Negative:

Description: NW corner

**File number (CNB):** 231.1 (1)

Address: 92 Church

Print: X

Negative: X

Description: Building cornice; northeast corner

**File number (CNB):** 231.1 (2)

Address: 92 Church

Print:

Negative: X

Description: Building cornice; northeast corner

**File number (CNB):** 232

Address: 96 Church

Print: X

Negative:

Description: sw corner

**File number (CNB):** 233

Address: 131 Church

Print: X

Negative:

Description: Se corner

**File number (CNB):** 233.1

Address: 131 Church

Print:

Negative: X

Description: Carriage gate, note larger recess in brick wall for larger original gate; no arch or lintel used to support recess bead; brick pier not original

**File number (CNB): 234**

Address: 133 Church

Print: X

Negative:

Description: e side

**File number (CNB): 234.1**

Address: 133 Church

Print:

Negative: X

Description: Entry gate; Dock Street Theater courtyard; design by Albert Simons FAIA c.1934

**File number (CNB): 234.2**

Address: 133 Church

Print:

Negative: X

Description: Entry gate, design by Albert Simons, FAIA c. 1934

**File number (CNB): 235**

Address: 135 Church

Print: X

Negative:

Description: e side

**File number (CNB): 235.1**

Address: 135 Church

Print:

Negative: X

Description: Column cap detail, c.1835

**File number (CNB): 235.2**

Address: 135 Church

Print:

Negative: X

Description: Balcony detail

**File number (CNB): 235.3**

Address: 135 Church

Print:

Negative: X

Description: Cast iron balcony, rebuilt from c.1935 balcony 1934

**File number (CNB): 236**

Address: 136 Church

Print: X

Negative:

Description: Se corner

**File number (CNB): 237**

Address: 136 Church

Print: X

Negative:

Description: w side gate

**File number (CNB): 238**

Address: 136 Church

Print: X

Negative:

Description: sw corner

**File number (CNB): 239**

Address: 136 Church

Print: X

Negative:

Description: NW corner

**File number (CNB): 239.1**

Address: 136 Church

Print:

Negative: X

Description: French Huguenot Church, c.1844 - Northwest corner with red filter

**File number (CNB): 240**

Address: 136 Church

Print: X

Negative:

Description: w side entry

**File number (CNB): 241**

Address: 136 Church

Print: X

Negative:

Description: interior looking west

**File number (CNB): 242**

Address: 136 Church

Print: X

Negative:

Description: interior looking east

**File number (CNB): 242 +-**

Address: 136 Church

Print: X

Negative:

Description: Westside, gable and buttress finials

**File number (CNB): 242.1**

Address: 136 Church

Print: X

Negative:

Description: w side central window

**File number (CNB): 242.2**

Address: 136 Church

Print: X

Negative:

Description: w side central gable

**File number (CNB):** 242.3

Address: 136 Church

Print:

Negative: X

Description: Westside, south window head and cresting, north window same

**File number (CNB):** 243

Address: 137-139 Church

Print: X

Negative:

Description: e side

**File number (CNB):** 244

Address: 137-139 Church

Print: X

Negative:

Description: NE corner

**File number (CNB):** 245

Address: 146 Church

Print: X

Negative:

Description: sw corner

**File number (CNB):** 246

Address: 146 Church

Print: X

Negative:

Description: Se corner

**File number (CNB):** 246.1

Address: 146 Church

Print: X

Negative:

Description: s die

**File number (CNB):** 247

Address: 146 Church

Print: X

Negative:

Description: n side

**File number (CNB):** 247.1

Address: 146 Church

Print: X

Negative:

Description: w side

**File number (CNB):** 247.2

Address: 146 Church

Print:

Negative: X

Description: w side entry railing

**File number (CNB): 247.3**

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Westside, detail entry railing

**File number (CNB): 248**

Address: 146 Church

Print: X

Negative:

Description: s side entry, n side same

**File number (CNB): 249**

Address: 146 Church

Print: X

Negative:

Description: w side entry

**File number (CNB): 250**

Address: 146 Church

Print: X

Negative:

Description: s side gate probably 1838

**File number (CNB): 251**

Address: 146 Church

Print: X

Negative:

Description: interior w exterior door from vestibule

**File number (CNB): 252**

Address: 146 Church

Print: X

Negative:

Description: n exterior door from vestibule s door same

**File number (CNB): 253**

Address: 146 Church

Print: X

Negative:

Description: int - looking east to alter

**File number (CNB): 254**

Address: 146 Church

Print: X

Negative:

Description: int looking NE

**File number (CNB): 255**

Address: 146 Church

Print: X

Negative:

Description: int looing W

**File number (CNB):** 255.1

Address: 146 Church

Print: X

Negative:

Description: nave w end ceiling detail

**File number (CNB):** 255.2

Address: 146 Church

Print: X

Negative:

Description: vault above alter

**File number (CNB):** 255.3

Address: 146 Church

Print: X

Negative:

Description: balcony looking NW

**File number (CNB):** 255.4

Address: 146 Church

Print: X

Negative:

Description: balcony columns

**File number (CNB):** 255.5

Address: 146 Church

Print: X

Negative:

Description: altar from balcony

**File number (CNB):** 255.6

Address: 146 Church

Print: X

Negative:

Description: tpical column and arch const

**File number (CNB):** 255.7

Address: 146 Church

Print: X

Negative:

Description: spandrel, console, cornice and ceiling vault rib

**File number (CNB):** 255.8

Address: 146 Church

Print: X

Negative:

Description: ceiling medallion a

**File number (CNB): 255.9**

Address: 146 Church

Print: X

Negative:

Description: medallion b

**File number (CNB): 255.10**

Address: 146 Church

Print: X

Negative:

Description: arch cherub long wing

**File number (CNB): 255.11**

Address: 146 Church

Print: X

Negative:

Description: arch cherub short wing

**File number (CNB): 255.12**

Address: 146 Church

Print: X

Negative:

Description: interior ceiling rib A

**File number (CNB): 255.13**

Address: 146 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church- ceiling rib "B" c.1835

**File number (CNB): 255.13 (1)**

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior arch

**File number (CNB): 255.13 (2)**

Address: 146 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church - Interior arch

**File number (CNB): 255.14 (1)**

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church- ceiling rib "C" c. 1835

**File number (CNB): 255.14 (2)**

Address: 146 Church

Print: X

Negative: X



Description: St. Philip's Episcopal Church- ceiling rib "C" c. 1835

**File number (CNB):** 255.15

Address: 146 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church- ceiling rib "D" adjacent to alter vault

**File number (CNB):** 255.16

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church- top of tower, south side

**File number (CNB):** 255.17

Address: 146 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church- tower, mid-section, south side

**File number (CNB):** 255.18

Address: 146 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church- tower base, south side, c.1835

**File number (CNB):** 255.19 (1)

Address: 146 Church

Print:

Negative: X

Description: West grave yard, East entry gates, before 1776 (Deas)

**File number (CNB):** 255.19 (2)

Address: 146 Church

Print:

Negative: X

Description: West grave yard, East entry gates, before 1776 (Deas)

**File number (CNB):** 255.20 (1)

Address: 146 Church

Print:

Negative: X

Description: West grave yard, East gate, detail

**File number (CNB):** 255.20 (2)

Address: 146 Church

Print:

Negative: X

Description: West grave yard, East gate, detail

**File number (CNB):** 255.20 (3)

Address: 146 Church

Print:

Negative: X

Description: West grave yard, East gate, detail

**File number (CNB):** 255.21

Address: 146 Church

Print:

Negative: X

Description: North gate, from north

**File number (CNB):** 255.22 (1)

Address: 146 Church

Print:

Negative: X

Description: North gate, from south

**File number (CNB):** 255.22 (2)

Address: 146 Church

Print:

Negative: X

Description: North gate, from south

**File number (CNB):** 255.22 (3)

Address: 146 Church

Print:

Negative: X

Description: North gate, from south

**File number (CNB):** 255.23

Address: 146 Church

Print:

Negative: X

Description: North gate, south side gate and railing braces

**File number (CNB):** 255.24

Address: 146 Church

Print:

Negative: X

Description: West grave yard, railing braces

**File number (CNB):** 255.25 (1)

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior, nave, south wall, door lock for pr. Doors

**File number (CNB):** 255.25 (2) small

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior, nave, south wall, door lock for pr. Doors

**File number (CNB):** 255.26 (1)

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior, nave, south wall, strap hinge for set of folding doors

**File number (CNB):** 255.26 (2)

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior, nave, south wall, strap hinge for set of folding doors

**File number (CNB):** 255.26 (3)

Address: 146 Church

Print:

Negative: X

Description: St. Philip's Episcopal Church - Interior, nave, south wall, strap hinge for set of folding doors

**File number (CNB):** 256

Address: 154 Church

Print: X

Negative: X

Description: St. Philip's Episcopal Church- parish house, c.1850

**File number (CNB):** 257

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: e side

**File number (CNB):** 257.1

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: w side 1st flr windows not original

**File number (CNB):** 257.2

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: s side entry, n side same

**File number (CNB):** 257.3

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: s side entry

**File number (CNB):** 257.4

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st flr SW room E wall, SE room W wall similar

**File number (CNB):** 257.5

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st flr SW room N wall, SE room same

**File number (CNB): 257.6**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st flr SW room S wall

**File number (CNB): 257.7**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " " W wall windows not original

**File number (CNB): 257.8**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " " Mantel not original

**File number (CNB): 257.9**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st flr SE room E wall - wall symmetrical

**File number (CNB): 257.10**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " " mantel detail

**File number (CNB): 257.11**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st floor NE room E wall

**File number (CNB): 257.12**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " " N wall exterior door. Door panels are beaded boards in chevron design, high point at center stile each side. NW door is now in separate corridor and build of vertical boards

**File number (CNB): 257.13**

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 1st flr NW room W wall

**File number (CNB):** 257.14

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 2nd flr SW room E wall (SE room W wall similar)

**File number (CNB):** 257.15

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 2nd flr SE W wall

**File number (CNB):** 257.16

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 2nd flr SW room mantel

**File number (CNB):** 257.17

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " NE room E wall

**File number (CNB):** 257.18

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " NW roomW wall

**File number (CNB):** 257.19

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " SE room E wall Chimney piece

**File number (CNB):** 257.20

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: " SW room N wall

**File number (CNB):** 257.22

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 2nd flr Sw room N wall

**File number (CNB):** 257.22

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: 2nd flr SW room cornice (same as SE)

**File number (CNB):** 257.23

Address: 4 Courthouse Square

Print:

Negative: X

Description: Stoop railing c.1788 (on plot of site) not original to 1760-72 house (there are traces of windows behind stoop)

**File number (CNB):** 257.24

Address: 4 Courthouse Square

Print:

Negative: X

Description: Stoop railing, detail of center panel

**File number (CNB):** 257.25

Address: 4 Courthouse Square

Print:

Negative: X

Description: Southside- door pediment

**File number (CNB):** 258

Address: 8 Courthouse Square

Print: X

Negative:

Description: W side

**File number (CNB):** 259

Address: 8 Courthouse Square

Print: X

Negative:

Description: E side

**File number (CNB):** 259.1

Address: 2-4 Courthouse Square

Print: X

Negative:

Description: entry door hood

**File number (CNB):** 260

Address: 122 East Bay

Print: X

Negative:

Description: W side

**File number (CNB):** 260.1

Address: 122 East Bay

Print:

Negative: X

Description: Westside - partial stoop railing

**File number (CNB):** 260.8

Address: 122 East Bay

Print: X

Negative:

Description: Prints of architectural design

**File number (CNB):** 260.10

Address: 122 East Bay

Print: X

Negative:

Description: "

**File number (CNB):** 260.11

Address: 122 East Bay

Print: X

Negative:

Description: "

**File number (CNB):** 261

Address: 122 East Bay

Print: X

Negative:

Description: sw corner

**File number (CNB):** 261.1

Address: 122 East Bay

Print: X

Negative:

Description: s side

**File number (CNB):** 261.2

Address: 122 East Bay

Print: X

Negative:

Description: NE corner

**File number (CNB):** 261.3

Address: 122 East Bay

Print: X

Negative:

Description: w side niche detail &hurricane bold, head removed 1980

**File number (CNB):** 261.4

Address: 122 East Bay

Print: X

Negative:

Description: w side details, pilaster base and window with guard

**File number (CNB):** 261.5

Address: 122 East Bay

Print: X

Negative:

Description: w side door detail

**File number (CNB): 261.6**

Address: 122 East Bay

Print: X

Negative:

Description: w side cornice and pilaster detail

**File number (CNB): 261.7**

Address: 122 East Bay

Print: X

Negative:

Description: exchange building and customs house, taken from 1865 NW corner

**File number (CNB): 261.8**

Address: 122 East Bay

Print:

Negative: X

Description: Eastside- copy of original drawing by W. Rigby Naylor, 1766-67, in possession of SC Dept. of Archives and History, copyrighted 1973

**File number (CNB): 261.9**

Address: 122 East Bay

Print:

Negative: X

Description: Westside, copyrighted 1973 by SC Dept. of Archives and History

**File number (CNB): 261.10**

Address: 122 East Bay

Print:

Negative: X

Description: Ground floor plan, copyrighted 1973 by SC Dept. Archives and History

**File number (CNB): 261.11**

Address: 122 East Bay

Print:

Negative: X

Description: First floor plan, copyrighted 1973 by SC Dept. Archives and History

**File number (CNB): 261.12**

Address: 122 East Bay

Print:

Negative: X

Description: Westside

**File number (CNB): 261.13**

Address: 122 East Bay

Print:

Negative: X

Description: West/south side

**File number (CNB): 261.14 (1)**

Address: 122 East Bay

Print:



Negative: X

Description: Northside

**File number (CNB):** 261.14 (2)

Address: 122 East Bay

Print:

Negative: X

Description: Northside

**File number (CNB):** 261.15

Address: 122 East Bay

Print:

Negative: X

Description: Eastside

**File number (CNB):** 261.16 (1)

Address: 122 East Bay

Print:

Negative: X

Description: Northeast side

**File number (CNB):** 261.16 (2)

Address: 122 East Bay

Print:

Negative: X

Description: Northeast side

**File number (CNB):** 261.17

Address: 122 East Bay

Print:

Negative: X

Description: Cupola, not original, rebuilt c.1980 based on original drawings

**File number (CNB):** 262

Address: 329 East Bay

Print: X

Negative:

Description: Se corner

**File number (CNB):** 263

Address: 329 East Bay

Print: X

Negative:

Description: e side

**File number (CNB):** 263.2

Address: 329 East Bay

Print:

Negative: X

Description: Eastside - stoop & railing. Note foot scraper over 2nd tread

**File number (CNB):** 263.3

Address: 329 East Bay

Print:

Negative: X

Description: Eastside - front entry

**File number (CNB):** 263.4

Address: 329 East Bay

Print:

Negative: X

Description: Eastside - front entry, head detail

**File number (CNB):** 263.5

Address: 329 East Bay

Print:

Negative: X

Description: Typical window head

**File number (CNB):** 264

Address: 214 Calhoun

Print: X

Negative:

Description: s side

**File number (CNB):** 265

Address: 214 Calhoun

Print: X

Negative:

Description: NE side

**File number (CNB):** 266

Address: 274 Calhoun

Print: X

Negative:

Description: sw corner

**File number (CNB):** 267

Address: 274 Calhoun

Print: X

Negative:

Description: n side

**File number (CNB):** 268

Address: 274 Calhoun

Print: X

Negative:

Description: S side entry 1850

**File number (CNB):** 269

Address: 274 Calhoun

Print: X

Negative:

Description: NE corner

**File number (CNB):** 270

Address: 274 Calhoun

Print: X

Negative:

Description: 1st flr hall looking s

**File number (CNB): 271**

Address: 274 Calhoun

Print: X

Negative:

Description: "" N

**File number (CNB): 272**

Address: 274 Calhoun

Print: X

Negative:

Description: 1st flr stair hall details

**File number (CNB): 273**

Address: 274 Calhoun

Print: X

Negative:

Description: " " arch to front hall filled in 1850

**File number (CNB): 274**

Address: 274 Calhoun

Print: X

Negative:

Description: 1st flr SW room

**File number (CNB): 275**

Address: 274 Calhoun

Print: X

Negative:

Description: " SE room E wall Chimney piece

**File number (CNB): 276**

Address: 274 Calhoun

Print: X

Negative:

Description: 2nd flr Sw room

**File number (CNB): 276.1**

Address: 274 Calhoun

Print: X

Negative:

Description: 1st flr hall ceiling

**File number (CNB): 277**

Address: 276 Calhoun

Print: X

Negative:

Description: Se side formly kitchen of 274

**File number (CNB): 278**

Address: 286 Calhoun

Print: X

Negative: X

Description: House- south side

**File number (CNB): 278.1**

Address: 286 Calhoun

Print:

Negative: X

Description: Southside - portico railing

**File number (CNB): 279**

Address: 286 Calhoun

Print: X

Negative:

Description: house and dependency e side

**File number (CNB): 280**

Address: 286 Calhoun

Print: X

Negative:

Description: dependency NW corner, penthouse new

**File number (CNB): 281**

Address: 286 Calhoun

Print: X

Negative:

Description: house s side entry

**File number (CNB): 281.1**

Address: 286 Calhoun

Print: X

Negative:

Description: 1st flr from portico

**File number (CNB): 281.2**

Address: 286 Calhoun

Print: X

Negative:

Description: " hall entry

**File number (CNB): 281.3**

Address: 286 Calhoun

Print: X

Negative:

Description: " typical door from hall to other rooms

**File number (CNB): 281.4**

Address: 286 Calhoun

Print: X

Negative:

Description: " hall looking N to stair hall

**File number (CNB): 281.5**

Address: 286 Calhoun

Print: X

Negative:

Description: " hall stair hall arch and hall cornice detail

**File number (CNB): 281.5**

Address: 286 Calhoun

Print: X

Negative:

Description: another view, note waintscotting

**File number (CNB): 281.7**

Address: 286 Calhoun

Print: X

Negative:

Description: 1st flr SE room W wall

**File number (CNB): 281.8**

Address: 286 Calhoun

Print: X

Negative:

Description: " " half mantel detail

**File number (CNB): 281.8**

Address: 286 Calhoun

Print: X

Negative:

Description:

**File number (CNB): 281.9**

Address: 286 Calhoun

Print: X

Negative:

Description: " " N wall cornice detail

**File number (CNB): 281.10**

Address: 286 Calhoun

Print: X

Negative:

Description: " " S wall cornice detail

**File number (CNB): 281.11**

Address: 286 Calhoun

Print: X

Negative:

Description: " " door to hall in W wall

**File number (CNB): 281.12**

Address: 286 Calhoun

Print: X

Negative:

Description: " " N wall

**File number (CNB):** 281.13

Address: 286 Calhoun

Print: X

Negative:

Description: " " door to hall

**File number (CNB):** 281.14

Address: 286 Calhoun

Print: X

Negative:

Description: " " cornice and door entablature

**File number (CNB):** 281.15

Address: 286 Calhoun

Print: X

Negative:

Description: " " mantel detail

**File number (CNB):** 281.16

Address: 286 Calhoun

Print: X

Negative:

Description: 1st flr NE room, S wall mantel

**File number (CNB):** 281.17

Address: 286 Calhoun

Print: X

Negative:

Description: 2nd flr stair hall landing

**File number (CNB):** 281.18

Address: 286 Calhoun

Print: X

Negative:

Description: 3rd flr stair hall landing

**File number (CNB):** 282

Address: Calhoun west end

Print: X

Negative:

Description: E side

**File number (CNB):** 283

Address: Calhoun west end

Print: X

Negative:

Description: SW side

**File number (CNB):** 284

Address: 6 & 10 Archdale

Print: X

Negative:

Description: Sw corners

**File number (CNB): 285**

Address: 6 Archdale

Print: X

Negative:

Description: old rendering of church 1787

**File number (CNB): 286**

Address: 6 Archdale

Print: X

Negative:

Description: NW corner

**File number (CNB): 287**

Address: 6 Archdale

Print: X

Negative:

Description: E side

**File number (CNB): 288**

Address: 6 Archdale

Print: X

Negative:

Description: SE corner

**File number (CNB): 289**

Address: 6 Archdale

Print: X

Negative:

Description: Ne corner

**File number (CNB): 289.1**

Address: 6 Archdale

Print: X

Negative: X

Description: Southwest side, tower

**File number (CNB): 290**

Address: 6 Archdale

Print: X

Negative:

Description: w " entry

**File number (CNB): 290.1**

Address: 6 Archdale

Print: X

Negative: X

Description: Westside, center window head

**File number (CNB): 290.2**

Address: 6 Archdale

Print:

Negative: X

Description: Westside, railing detail

**File number (CNB): 291**

Address: 6 Archdale

Print: X

Negative:

Description: int looking E toward altar

**File number (CNB): 292**

Address: 6 Archdale

Print: X

Negative:

Description: " looking W toward choir

**File number (CNB): 293**

Address: 6 Archdale

Print: X

Negative:

Description: Ceiling patterend after Henry VII chapel at Westminster (West to East)

**File number (CNB): 294**

Address: 6 Archdale

Print: X

Negative:

Description: fan pendants springing from (ribbed/fanned vaulting)

**File number (CNB): 295**

Address: 6 Archdale

Print: X

Negative:

Description: ceiling, free drop pendants

**File number (CNB): 296**

Address: 6 Archdale

Print: X

Negative:

Description: altar

**File number (CNB): 296.1**

Address: 6 Archdale

Print: X

Negative:

Description: altar pendent

**File number (CNB): 297**

Address: 10 Archdale

Print: X

Negative:

Description: S side tower



**File number (CNB): 298**

Address: 10 Archdale

Print: X

Negative:

Description: N "

**File number (CNB): 298**

Address: 10 Archdale

Print: X

Negative:

Description: ornamental gate

**File number (CNB): 299**

Address: 10 Archdale

Print: X

Negative:

Description: W " portico

**File number (CNB): 300**

Address: 10 Archdale

Print: X

Negative:

Description: SW corner tower detail

**File number (CNB): 301**

Address: 10 Archdale

Print: X

Negative:

Description: NE corner

**File number (CNB): 302**

Address: 10 Archdale

Print: X

Negative:

Description: w side portico gate

**File number (CNB): 303**

Address: 10 Archdale

Print: X

Negative:

Description: n " gate no 1

**File number (CNB): 303.2**

Address: 10 Archdale

Print:

Negative: X

Description: Northside, fencing external terminal

**File number (CNB): 303.3 (1)**

Address: 10 Archdale

Print:

Negative: X

Description: Northside, railing & gate braces

**File number (CNB):** 303.3 (2)

Address: 10 Archdale

Print:

Negative: X

Description: Northside, railing & gate braces

**File number (CNB):** 303.4

Address: 10 Archdale

Print:

Negative: X

Description: Wrought and cast iron double gate between #6 and #10 cemeteries

**File number (CNB):** 304

Address: 10 Archdale

Print: X

Negative:

Description: vestibule towards nave

**File number (CNB):** 305

Address: 10 Archdale

Print: X

Negative:

Description: interior looking E toward altar

**File number (CNB):** 306

Address: 10 Archdale

Print: X

Negative:

Description: choir and altar

**File number (CNB):** 307

Address: 10 Archdale

Print: X

Negative:

Description: ceiling

**File number (CNB):** 308

Address: 10 Archdale

Print: X

Negative:

Description: medallion

**File number (CNB):** 308.1

Address: 10 Archdale

Print: X

Negative:

Description: E to W

**File number (CNB):** 308.2

Address: 10 Archdale

Print:

Negative: X  
Description: Tower, westside, from 21 Archdale courtyard

**File number (CNB):** 309

Address: 19 Archdale

Print: X

Negative:

Description: NW corner

**File number (CNB):** 310

Address: 19 Archdale

Print: X

Negative:

Description: Se corner entry and porch 1835

**File number (CNB):** 311

Address: 19 Archdale

Print: X

Negative:

Description: Ne corner

**File number (CNB):** 312

Address: 19 Archdale

Print: X

Negative:

Description: entry

**File number (CNB):** 312.1

Address: 19 Archdale

Print: X

Negative:

Description: w side

**File number (CNB):** 312.2

Address: 19 Archdale

Print: X

Negative:

Description: rear stairs masonry

**File number (CNB):** 312.3

Address: 19 Archdale

Print: X

Negative:

Description: interior 1st flr NE room N wall

**File number (CNB):** 312.4

Address: 19 Archdale

Print: X

Negative:

Description: " " SE room N wall

**File number (CNB):** 313

Address: 9 East Battery

Print: X  
Negative:  
Description: S side  
**File number (CNB): 314**  
Address: 9 East Battery  
Print: X  
Negative:  
Description: SE corner  
**File number (CNB): 315**  
Address: 9 East Battery  
Print: X  
Negative:  
Description: NE corner  
**File number (CNB): 315.1 (1)**  
Address: 9 East Battery  
Print:  
Negative: X  
Description: Northeast corner; earthquake bolt heads c.1886-87  
**File number (CNB): 315.1 (2)**  
Address: 9 East Battery  
Print:  
Negative: X  
Description: Northeast corner; earthquake bolt heads c.1886-87  
**File number (CNB): 316**  
Address: 9 East Battery  
Print: X  
Negative:  
Description: E side 2nd flr N end window guard and cornice  
**File number (CNB): 317**  
Address: 9 East Battery  
Print: X  
Negative:  
Description: " 1st flr balcont detail  
**File number (CNB): 318**  
Address: 9 East Battery  
Print: X  
Negative:  
Description: " 2nd flr balcony detail and conrice  
**File number (CNB): 318.1 (1)**  
Address: 9 East Battery  
Print:  
Negative: X  
Description: Southwest side  
**File number (CNB): 318.1 (2)**

Address: 9 East Battery

Print:

Negative: X

Description: Southwest side

**File number (CNB):** 318.2

Address: 9 East Battery

Print:

Negative: X

Description: Southside, west end of house

**File number (CNB):** 318.3

Address: 9 East Battery

Print:

Negative: X

Description: Southside, balconies

**File number (CNB):** 318.4

Address: 9 East Battery

Print:

Negative: X

Description: Southside, balcony detail; same for eastside balconies

**File number (CNB):** 318.5

Address: 9 East Battery

Print:

Negative: X

Description: Southside, balcony support bracket

**File number (CNB):** 318.6

Address: 9 East Battery

Print:

Negative: X

Description: Gazebo, northeast corner

**File number (CNB):** 319

Address: 9 East Battery

Print: X

Negative:

Description: SE corner 2nd flr details

**File number (CNB):** 320

Address: 9 East Battery

Print: X

Negative:

Description: E side ground floor entry

**File number (CNB):** 320.1

Address: 9 East Battery

Print:

Negative: X

Description: Eastside- hitching post

**File number (CNB): 321**

Address: 21 East Battery

Print: X

Negative:

Description: E side

**File number (CNB): 322**

Address: 21 East Battery

Print: X

Negative:

Description: s side

**File number (CNB): 323**

Address: 21 East Battery

Print: X

Negative:

Description: Ne corner

**File number (CNB): 324**

Address: 21 East Battery

Print: X

Negative:

Description: w side

**File number (CNB): 325**

Address: 21 East Battery

Print: X

Negative:

Description: s side 1st flr balcony detail

**File number (CNB): 325.1**

Address: 21 East Battery

Print:

Negative: X

Description: Eastside - 1st flr. Balcony detail

**File number (CNB): 326**

Address: 21 East Battery

Print: X

Negative:

Description: e side parapet detail alston coat of arms

**File number (CNB): 327**

Address: 21 East Battery

Print: X

Negative:

Description: interior ground flr E entry hall looking E

**File number (CNB): 328**

Address: 21 East Battery

Print: X

Negative:

Description: " " E & Shall intersection looking south

**File number (CNB): 329**

Address: 21 East Battery

Print: X

Negative:

Description: int ground flr stair hall looking N

**File number (CNB): 330**

Address: 21 East Battery

Print: X

Negative:

Description: " " SE room N wall

**File number (CNB): 331**

Address: 21 East Battery

Print: X

Negative:

Description: " " SW room N wall

**File number (CNB): 332**

Address: 21 East Battery

Print: X

Negative:

Description: " 1st flr E draing room N wall

**File number (CNB): 333**

Address: 21 East Battery

Print: X

Negative:

Description: " " S hall and W drawing room looking w

**File number (CNB): 334**

Address: 21 East Battery

Print: X

Negative:

Description: int 1st flr w drawing room

**File number (CNB): 335**

Address: 21 East Battery

Print: X

Negative:

Description: " " E drawing room SE wal

**File number (CNB): 336**

Address: 21 East Battery

Print: X

Negative:

Description: " " E drawing room mantel

**File number (CNB): 337**

Address: 21 East Battery

Print: X

Negative:

Description: " " S hall looking N

**File number (CNB):** 338

Address: 21 East Battery

Print: X

Negative:

Description: " " portico entry to S hall

**File number (CNB):** 339

Address: 21 East Battery

Print: X

Negative:

Description: dependency S side

**File number (CNB):** 339.1

Address: 21 East Battery

Print: X

Negative:

Description: E side pass gate, all ironwork assumed 1838

**File number (CNB):** 339.3

Address: 21 East Battery

Print:

Negative: X

Description: Eastside- railing braces

**File number (CNB):** 339.7

Address: 21 East Battery

Print:

Negative: X

Description: Carriage gate, eastside

**File number (CNB):** 346.1

Address: 14 George

Print: X

Negative: X

Description: Northside - showing typical Charleston roof flare before 1860

**File number (CNB):** 352

Address: 10 Judith

Print: X

Negative:

Description: kitchen NE corner

**File number (CNB):** 352.1

Address: 10 Judith

Print: X

Negative:

Description: " SE side

**File number (CNB):** 352.2

Address: 10 Judith



Print: X

Negative:

Description: " N side

**File number (CNB):** 352.3

Address: 10 Judith

Print: X

Negative:

Description: " E side window details

**File number (CNB):** 352.4

Address: 10 Judith

Print: X

Negative:

Description: " inter 1st flr N room looking SE

**File number (CNB):** 352.5

Address: 10 Judith

Print: X

Negative:

Description: " int S room looking NE

**File number (CNB):** 352.6

Address: 10 Judith

Print: X

Negative:

Description: " int 2nd flr N room looking SE

**File number (CNB):** 352.7

Address: 10 Judith

Print: X

Negative:

Description: house S side

**File number (CNB):** 352.8

Address: 10 Judith

Print: X

Negative:

Description: house int 1st flr Se Room mantel

**File number (CNB):** 352.9

Address: 10 Judith

Print: X

Negative:

Description: " " SE room N wall

**File number (CNB):** 353

Address: 21 King

Print: X

Negative:

Description: House in SE corner

**File number (CNB):** 354

Address: 21 King

Print: X

Negative:

Description: " NE corner

**File number (CNB): 355**

Address: 21 King

Print: X

Negative:

Description: " SW corner

**File number (CNB): 356**

Address: 21 King

Print: X

Negative:

Description: " 2nd flr window and cornice

**File number (CNB): 357**

Address: 21 King

Print: X

Negative:

Description: dependency S side

**File number (CNB): 358**

Address: 21 King

Print: X

Negative:

Description: carriage ghouse and NE corner

**File number (CNB): 359**

Address: 21 King

Print: X

Negative:

Description: House 3rd flr window cornice

**File number (CNB): 359.1**

Address: 21 King

Print: X

Negative:

Description: entry

**File number (CNB): 359.2**

Address: 21 King

Print: X

Negative:

Description: house, S side dormer window

**File number (CNB): 360**

Address: 27 King

Print: X

Negative:

Description: 1st flr portico cornice and 2nd flr balustrade

**File number (CNB): 361**

Address: 27 King

Print: X

Negative:

Description: 1st flr entry and entry gate

**File number (CNB): 361.1 (1)**

Address: 27 King

Print:

Negative: X

Description: Eastside- entry gate and fencing, before Revolution (Deas); lamps not original

**File number (CNB): 361.1 (2)**

Address: 27 King

Print:

Negative: X

Description: Eastside- entry gate and fencing, before Revolution (Deas); lamps not original

**File number (CNB): 361.1a**

Address: 27 King

Print:

Negative: X

Description: Forecourt enclosed in English tradition; before 1775 (Deas). The cheval-de-frise and pickets over cresting said to be result of 1822 slave uprising

**File number (CNB): 361.2 (1)**

Address: 27 King

Print:

Negative: X

Description: Eastside- entry gate and picket detail

**File number (CNB): 361.2 (2)**

Address: 27 King

Print:

Negative: X

Description: Eastside- entry gate and picket detail

**File number (CNB): 361.3**

Address: 27 King

Print:

Negative: X

Description: Eastside- wood carriage gate with iron picket overthrow

**File number (CNB): 361.4**

Address: 27 King

Print:

Negative: X

Description: Eastside - wood pass gate, wrought iron knocker

**File number (CNB): 361.5**

Address: 27 King

Print:

Negative: X  
Description: Carriage House - wrought iron strap hinge

**File number (CNB):** 361.6

Address: 27 King

Print:

Negative: X

Description: Eastside- foot scraper

**File number (CNB):** 362

Address: 27 King

Print: X

Negative:

Description: portico pediment detail

**File number (CNB):** 363

Address: 55 Laurens

Print: X

Negative:

Description: house s side

**File number (CNB):** 364

Address: 55 Laurens

Print: X

Negative:

Description: entry

**File number (CNB):** 365

Address: 55 Laurens

Print: X

Negative:

Description: NW corner

**File number (CNB):** 366

Address: 55 Laurens

Print: X

Negative:

Description: S side

**File number (CNB):** 367

Address: 15 Legare

Print: X

Negative:

Description:

**File number (CNB):** 368

Address: 15 Legare

Print: X

Negative:

Description:

**File number (CNB):** 369

Address: 1 Meeting

Print: X

Negative:

Description:

**File number (CNB): 370**

Address: 1 Meeting

Print: X

Negative:

Description:

**File number (CNB): 371**

Address: 1 Meeting

Print: X

Negative:

Description:

**File number (CNB): 371.1**

Address: 1 Meeting

Print:

Negative: X

Description: Eastside- landern c.1922, copied from lantern on 15th century Strozzi Palazza, Florence, Italy; reduced approximately one half size of 9' 0"

**File number (CNB): 372**

Address: 2 Meeting

Print: X

Negative: X

Description: Westside balcony support detail

**File number (CNB): 372.1**

Address: 2 Meeting

Print:

Negative: X

Description: Northside railing

**File number (CNB): 372.2**

Address: 2 Meeting

Print:

Negative: X

Description: Northside- stoop railing

**File number (CNB): 372.3**

Address: 2 Meeting

Print:

Negative: X

Description: Westside- entry gate; overthrow not original

**File number (CNB): 372.4**

Address: 2 Meeting

Print:

Negative: X

Description: Southwest corner

**File number (CNB): 372.5**

Address: 2 Meeting

Print:

Negative: X

Description: Southside- east end

**File number (CNB): 372.6**

Address: 2 Meeting

Print:

Negative: X

Description: Southside

**File number (CNB): 373**

Address: 7 Meeting

Print: X

Negative: X

Description: Southeast corner; brick wall 20th century to replace wood

**File number (CNB): 373.1**

Address: 7 Meeting

Print:

Negative: X

Description: Eastside- portico guard, horizontal member 36" long

**File number (CNB): 374**

Address: 7 Meeting

Print: X

Negative: X

Description: Northeast corner

**File number (CNB): 375**

Address: 7 Meeting

Print: X

Negative: X

Description: Portico; Josiah Smith House

**File number (CNB): 375.1 (1)**

Address: 7 Meeting

Print: X

Negative: X

Description: Pediment and console

**File number (CNB): 375.1 (2)**

Address: 7 Meeting

Print:

Negative: X

Description: Pediment and console

**File number (CNB): 375.2**

Address: 7 Meeting

Print: X

Negative: X

Description: Cupola

**File number (CNB): 375.2**

Address: 7 Meeting

Print: X

Negative:

Description:

**File number (CNB): 376**

Address: 7 Meeting

Print: X

Negative:

Description:

**File number (CNB): 376**

Address: 8 Meeting

Print:

Negative: X

Description: Northwest corner

**File number (CNB): 377**

Address: 8 Meeting

Print: X

Negative: X

Description: Southside

**File number (CNB): 378**

Address: 8 Meeting

Print: X

Negative: X

Description: Entry and balcony detail

**File number (CNB): 378.1**

Address: 8 Meeting

Print:

Negative: X

Description: West balcony detail

**File number (CNB): 378.2**

Address: 8 Meeting

Print:

Negative: X

Description: South balcony detail; west end

**File number (CNB): 378.3**

Address: 8 Meeting

Print:

Negative: X

Description: Westside - balcony

**File number (CNB): 379**

Address: 8 Meeting

Print: X

Negative: X

Description: Kitchen- west side

**File number (CNB): 380**

Address: 8 Meeting

Print: X

Negative: X

Description: Carriage house, west side

**File number (CNB): 381**

Address: 8 Meeting

Print: X

Negative: X

Description: Stable, west side

**File number (CNB): 382**

Address: 15 Meeting

Print: X

Negative: X

Description: Southside; circular porch later

**File number (CNB): 382.1**

Address: 15 Meeting

Print: X

Negative: X

Description: Southeast side; c.1756-1770; John Edwards

**File number (CNB): 382.2**

Address: 15 Meeting

Print: X

Negative: X

Description: Entry

**File number (CNB): 382.3**

Address: 15 Meeting

Print: X

Negative:

Description:

**File number (CNB): 382.3 (1)**

Address: 15 Meeting

Print:

Negative: X

Description: Cornice, console entry porch; balustrade east side

**File number (CNB): 382.3 (2)**

Address: 15 Meeting

Print:

Negative: X

Description: Cornice, console entry porch; balustrade east side

**File number (CNB): 382.4**

Address: 15 Meeting



Print:

Negative: X

Description: Detail, entry landing (Sonn- note foot scraper in lyre on landing)

**File number (CNB):** 382.5

Address: 15 Meeting

Print:

Negative: X

Description: Entry ironwork

**File number (CNB):** 382.6

Address: 15 Meeting

Print:

Negative: X

Description: Small carriage gates, not original

**File number (CNB):** 382.7

Address: 15 Meeting

Print:

Negative: X

Description: Carriage gates, large, not original

**File number (CNB):** 382.8

Address: 15 Meeting

Print:

Negative: X

Description: Eastside- window guard under portico

**File number (CNB):** 382.9

Address: 15 Meeting

Print:

Negative: X

Description: Eastside- entry

**File number (CNB):** 382.1

Address: 15 Meeting

Print:

Negative: X

Description: Eastside

**File number (CNB):** 383.1

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- entry, looking west into stair hall

**File number (CNB):** 383.2

Address: 15 Meeting

Print:

Negative: X

Description: 1st flr- entry, typical door case, looking into southeast room

**File number (CNB):** 383.3

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room, looking southwest

**File number (CNB):** 383.4

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room, chimney piece

**File number (CNB):** 383.5

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room mantel

**File number (CNB):** 383.6

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room and overmantel cornices

**File number (CNB):** 383.7

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room, looking northeast

**File number (CNB):** 383.8

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southeast room, door in north wall

**File number (CNB):** 383.9

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southwest room, looking east

**File number (CNB):** 383.10

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- southwest room chimney piece

**File number (CNB):** 383.11

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast room, west wall; niches not original

**File number (CNB): 383.12**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast room, chimney piece

**File number (CNB): 383.13**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast mantel

**File number (CNB): 383.14**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast room and overmantel cornices

**File number (CNB): 383.15**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast room, looking southeast

**File number (CNB): 383.16**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northeast room, door in south wall

**File number (CNB): 383.17**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northwest room and door cornices c.1942

**File number (CNB): 383.18**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- northwest room, west wall detail c.1947

**File number (CNB): 383.19**

Address: 15 Meeting

Print: X

Negative: X

Description: 1st flr- stair hall, looking east into entry hall

**File number (CNB): 383.20**

Address: 15 Meeting

Print: X

Negative: X

Description: Stair landing, looking northwest into 2nd floor stair hall

**File number (CNB):** 383.21

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- stair hall, north wall, open door to northwest room, closed door to attic door

**File number (CNB):** 383.22

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- stair hall, looking southwest, door to southwest room, mirror glass in wall sash originally an exterior wall

**File number (CNB):** 383.23

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southeast room, looking southwest

**File number (CNB):** 383.24

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southeast room, overmantel

**File number (CNB):** 383.25

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southeast room mantel

**File number (CNB):** 383.26

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southeast room, cornice and overmantel detail

**File number (CNB):** 383.27

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southeast room, looking southeast

**File number (CNB):** 383.28

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- northeast room, west wall

**File number (CNB):** 383.29

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- northeast room, mantel, interlace from Pain's "Practical Builder"

**File number (CNB):** 383.30

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southwest room, east wall

**File number (CNB):** 383.31

Address: 15 Meeting

Print: X

Negative: X

Description: 2nd flr- southwest room, mantel; predominate tile color blue and white, about 5 brown and white

**File number (CNB):** 383.32

Address: 15 Meeting

Print:

Negative: X

Description: Northeast side, termite envelope

**File number (CNB):** 383.33

Address: 15 Meeting

Print:

Negative: X

Description: Southwest side, termite envelope

**File number (CNB):** 383.34

Address: 15 Meeting

Print:

Negative: X

Description: Southeast side, termite envelope

**File number (CNB):** 384

Address: 18 Meeting

Print: X

Negative: X

Description: Southwest corner

**File number (CNB):** 384.1

Address: 18 Meeting

Print: X

Negative: X

Description: Northwest corner

**File number (CNB):** 385 (1)

Address: 18 Meeting

Print: X

Negative: X

Description: Entry detail

**File number (CNB): 385 (2)**

Address: 18 Meeting

Print:

Negative: X

Description: Entry detail

**File number (CNB): 385.1**

Address: 18 Meeting

Print:

Negative:

Description:

**File number (CNB): 385.1 (1)**

Address: 18 Meeting

Print: X

Negative: X

Description: Southeast corner; Thomas Heyward house

**File number (CNB): 385.1 (2)**

Address: 18 Meeting

Print:

Negative: X

Description: Southeast corner; Thomas Heyward house

**File number (CNB): 385.2**

Address: 18 Meeting

Print: X

Negative: X

Description: Portico entry, 1st floor

**File number (CNB): 385.3**

Address: 18 Meeting

Print: X

Negative: X

Description: Dependency, south side

**File number (CNB): 385.4**

Address: 18 Meeting

Print: X

Negative:

Description:

**File number (CNB): 385.5**

Address: 18 Meeting

Print:

Negative: X

Description: Entry door

**File number (CNB): 385.6**

Address: 18 Meeting

Print:

Negative: X

Description: Typical corner cheval-de-frise, probably not typical to house

**File number (CNB): 385.7**

Address: 18 Meeting

Print:

Negative: X

Description: Southwest corner, balcony and pickets, balcony, probably original since windows are floor length

**File number (CNB): 386**

Address: 26 Meeting

Print: X

Negative:

Description:

**File number (CNB): 387**

Address: 26 Meeting

Print: X

Negative:

Description:

**File number (CNB): 387.1**

Address: 26 Meeting

Print:

Negative: X

Description: Pass gate, wood, east side; carriage gate similar but larger

**File number (CNB): 388**

Address: 27 Meeting

Print: X

Negative:

Description:

**File number (CNB): 389**

Address: 31 Meeting

Print: X

Negative:

Description:

**File number (CNB): 389 +-**

Address: 31 Meeting

Print: X

Negative:

Description: Fountain

**File number (CNB): 389.1 (1)**

Address: 31 Meeting

Print: X

Negative: X

Description: North (Ladson St.) gates; formerly at 61 Charlotte St.

**File number (CNB): 389.1 (2)**

Address: 31 Meeting

Print:

Negative: X

Description: North (Ladson St.) gates; formerly at 61 Charlotte St.

**File number (CNB):** 389.1 (3)

Address: 31 Meeting

Print:

Negative: X

Description: North (Ladson St.) gates; formerly at 61 Charlotte St.

**File number (CNB):** 390

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 390.1

Address: 34 Meeting

Print:

Negative: X

Description: Westside- carriage gate north, south gate same, 20th century, by Philip Simmons

**File number (CNB):** 391

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 392

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 393

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 394

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 395

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 396



Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 397**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 398**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 399**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 400**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 400**

Address: 72 Meeting

Print:

Negative: X

Description: South Carolina Society Building - southwest side. Wrought iron railing & lantern

**File number (CNB): 401**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 402**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 403**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 404**

Address: 34 Meeting

Print: X

Negative:

Description:

**File number (CNB): 405**

Address: 57 Meeting

Print: X

Negative:

Description:

**File number (CNB): 406**

Address: 57 Meeting

Print: X

Negative: X

Description: First Scotch Presbyterian Church 1814; southeast corner

**File number (CNB): 407**

Address: 57 Meeting

Print: X

Negative: X

Description: First Scotch Presbyterian Church 1814; northside (Tradd St.)

**File number (CNB): 407.1 (1)**

Address: 57 Meeting

Print: X

Negative: X

Description: First Scotch Presbyterian Church 1814; Cupola detail

**File number (CNB): 407.1 (2)**

Address: 57 Meeting

Print:

Negative: X

Description: First Scotch Presbyterian Church 1814; Cupola detail

**File number (CNB): 407.1 (3)**

Address: 57 Meeting

Print:

Negative: X

Description: First Scotch Presbyterian Church 1814; Cupola detail

**File number (CNB): 407.1 (4)**

Address: 57 Meeting

Print:

Negative: X

Description: First Scotch Presbyterian Church 1814; Cupola detail

**File number (CNB): 407.1 (5)**

Address: 57 Meeting

Print:

Negative: X

Description: First Scotch Presbyterian Church 1814; Cupola detail

**File number (CNB):** 407.3

Address: 57 Meeting

Print:

Negative: X

Description: Choir loft, c 1947 after fire of 1945. Harold Tatum, Archt, H.W. Dabney & Savannah Iron & Wire Works, fabricator of 3 wrought iron grilles

**File number (CNB):** 408

Address: 59 Meeting

Print: X

Negative: X

Description: East side

**File number (CNB):** 409

Address: 59 Meeting

Print: X

Negative: X

Description: Northeast corner

**File number (CNB):** 410

Address: 59 Meeting

Print: X

Negative: X

Description: Southwest corner

**File number (CNB):** 411

Address: 72 Meeting

Print: X

Negative: X

Description: West side

**File number (CNB):** 412

Address: 72 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 412 (1)

Address: 72 Meeting

Print:

Negative: X

Description: Lamp standards c.1750, stair railing c.1805 (A.Deas) and basement window grille

**File number (CNB):** 412 (2)

Address: 72 Meeting

Print:

Negative: X

Description: Lamp standards c.1750, stair railing c.1805 (A.Deas) and basement window grille

**File number (CNB):** 412 (3)

Address: 72 Meeting

Print:

Negative: X

Description: Lamp standards c.1750, stair railing c.1805 (A.Deas) and basement window grille

**File number (CNB):** 412 (4)

Address: 72 Meeting

Print:

Negative: X

Description: Lamp standards c.1750, stair railing c.1805 (A.Deas) and basement window grille

**File number (CNB):** 413

Address: 72 Meeting

Print: X

Negative:

Description:

**File number (CNB):** 413 (1)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413 (2)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413 (3)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413 (4)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413 (5)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413 (6)

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche detail

**File number (CNB):** 413.1

Address: 72 Meeting

Print:

Negative: X

Description: Cartouche, color, before painting 1982

**File number (CNB):** 413.4

Address: 72 Meeting

Print:

Negative: X

Description: Westside, 2nd flr - portico, column base and railing detail

**File number (CNB):** 419.1

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church Tower - central section

**File number (CNB):** 419.4

Address: 80 Meeting

Print: X

Negative: X

Description: St. Michael's Episcopal Church - Half communion rail, c1772, from England to replace original wood rail

**File number (CNB):** 419.4 (1)

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church- gate in west wall (gate in north wall same) by A. lusti or J.A.W. Justi (A. Deas pg 30-31) mentioned in Encyclopedia Britannica

**File number (CNB):** 419.4 (2)

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church- gate in west wall (gate in north wall same) by A. lusti or J.A.W. Justi (A. Deas pg 30-31) mentioned in Encyclopedia Britannica

**File number (CNB):** 419.4 (3)

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church- gate in west wall (gate in north wall same) by A. lusti or J.A.W. Justi (A. Deas pg 30-31) mentioned in Encyclopedia Britannica

**File number (CNB):** 419.4 (4)

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church- gate in west wall (gate in north wall same) by A. lusti or J.A.W. Justi (A. Deas pg 30-31) mentioned in Encyclopedia Britannica

**File number (CNB): 419.25**

Address: 80 Meeting

Print:

Negative: X

Description: St. Michael's Episcopal Church - color, church from southwest

**File number (CNB): 420**

Address: 100 Meeting

Print: X

Negative:

Description: Front façade (N side)

**File number (CNB): 421**

Address: 100 Meeting

Print: X

Negative:

Description: East side from Meeting street

**File number (CNB): 422**

Address: 100 Meeting

Print: X

Negative:

Description: iron work detail on ground flr window

**File number (CNB): 423**

Address: 100 Meeting

Print: X

Negative:

Description: gate iron work, ground floor arcade

**File number (CNB): 423 +-**

Address: 100 Meeting

Print: X

Negative:

Description: S side view from street (gate)

**File number (CNB): 423.2**

Address: 100 Meeting

Print: X

Negative:

Description: ground flr arcade

**File number (CNB): 423.3**

Address: 100 Meeting

Print: X

Negative:

Description: ground flr entrance and stairwell

**File number (CNB): 423.4**

Address: 100 Meeting

Print: X

Negative:

Description: vault door, ground flr

**File number (CNB):** 423.5

Address: 100 Meeting

Print: X

Negative:

Description: 1st floor work room, double fire place

**File number (CNB):** 423.6

Address: 100 Meeting

Print: X

Negative:

Description: barrel vault hallway E?

**File number (CNB):** 423.7

Address: 100 Meeting

Print: X

Negative:

Description: barrel vault hallway W?

**File number (CNB):** 423.8

Address: 100 Meeting

Print: X

Negative:

Description: work room double barrel vault and archway

**File number (CNB):** 423.9

Address: 100 Meeting

Print: X

Negative:

Description: Library/workroom double barrel vault ceiling

**File number (CNB):** 423.10

Address: 100 Meeting

Print: X

Negative:

Description: fire place and \_wall left of library^

**File number (CNB):** 423.11

Address: 100 Meeting

Print: X

Negative:

Description: Marble mantel detail ^

**File number (CNB):** 423.12

Address: 100 Meeting

Print: X

Negative:

Description: middle stairlanding (cantelevering & ironwork)

**File number (CNB):** 423.13

Address: 100 Meeting

Print: X

Negative:

Description: Top floor landing, bust framed within an oculus between two columns and entablature

**File number (CNB):** 423.14

Address: 100 Meeting

Print: X

Negative:

Description: skylight above central stairwell

**File number (CNB):** 423.15

Address: 100 Meeting

Print: X

Negative:

Description: looking down the central stairwell

**File number (CNB):** 423.16

Address: 100 Meeting

Print: X

Negative:

Description: original table? Research room

**File number (CNB):** 424

Address: 141 Meeting

Print: X

Negative: X

Description: Northeast corner

**File number (CNB):** 425

Address: 141 Meeting

Print: X

Negative:

Description: northwest corner

**File number (CNB):** 426

Address: 150 Meeting

Print: X

Negative:

Description: Circular Congragational Church, W side

**File number (CNB):** 427

Address: 150 Meeting

Print: X

Negative:

Description: E side (neo-Romanesque)

**File number (CNB):** 428

Address: 150 Meeting

Print: X

Negative:

Description: N side entrance

**File number (CNB):** 428

Address: 150 Meeting



Print: X

Negative:

Description: ^

**File number (CNB): 428.1**

Address: 150 Meeting

Print: X

Negative:

Description: parrish building? N

**File number (CNB): 428.2**

Address: 150 Meeting

Print: X

Negative:

Description: ne corner

**File number (CNB): 428.4**

Address: 150 Meeting

Print:

Negative: X

Description: Circular Church - southside

**File number (CNB): 428.5**

Address: 150 Meeting

Print:

Negative: X

Description: Circular Church - southwest side

**File number (CNB): 429**

Address: 275 Meeting

Print: X

Negative: X

Description: Center door east façade

**File number (CNB): 429.1**

Address: 275 Meeting

Print: X

Negative:

Description: east portico and pediment from street

**File number (CNB): 429.2**

Address: 275 Meeting

Print: X

Negative:

Description: north side

**File number (CNB): 429.3**

Address: 275 Meeting

Print: X

Negative:

Description: column detail (corinthian)

**File number (CNB): 429.4**

Address: 275 Meeting

Print: X

Negative:

Description: portico ceiling detail

**File number (CNB):** 429.5

Address: 275 Meeting

Print: X

Negative:

Description: iron balustrade

**File number (CNB):** 429.6

Address: 275 Meeting

Print: X

Negative:

Description: southeast corner/side view

**File number (CNB):** 429.7

Address: 275 Meeting

Print: X

Negative:

Description: window detail n/s side same

**File number (CNB):** 429.8

Address: 275 Meeting

Print: X

Negative:

Description: Interior facing west toward altar

**File number (CNB):** 429.9

Address: 275 Meeting

Print: X

Negative:

Description: opposite view ^ facing east

**File number (CNB):** 429.10

Address: 275 Meeting

Print: X

Negative:

Description: East doors to nave

**File number (CNB):** 429.11

Address: 275 Meeting

Print: X

Negative:

Description: full view of altar and apse

**File number (CNB):** 429.12

Address: 275 Meeting

Print: X

Negative:

Description: niche detail (baroque)

**File number (CNB): 429.13**

Address: 275 Meeting

Print: X

Negative:

Description: colum cap, entablture balcony deatil

**File number (CNB): 429.14**

Address: 275 Meeting

Print: X

Negative:

Description: organ? And balcony balustrade detail (baroque)

**File number (CNB): 429.15**

Address: 275 Meeting

Print: X

Negative:

Description: column caps, niche ceiling and cornice details

**File number (CNB): 429.16**

Address: 275 Meeting

Print: X

Negative:

Description: cornice and ceiling detail

**File number (CNB): 429.17**

Address: 275 Meeting

Print: X

Negative:

Description: central ceiling medallion (cross)

**File number (CNB): 429.18**

Address: 275 Meeting

Print: X

Negative:

Description: organ

**File number (CNB): 430**

Address: 286 Meeting

Print: X

Negative:

Description: street view front façade

**File number (CNB): 431**

Address: 286 Meeting

Print: X

Negative:

Description: right side view

**File number (CNB): 431 +-**

Address: 286 Meeting

Print: X

Negative:

Description: ground flr detail

**File number (CNB):** 431.1

Address: 286 Meeting

Print: X

Negative:

Description: exterior window on the right side detail

**File number (CNB):** 431.2

Address: 286 Meeting

Print: X

Negative:

Description: corbel detail on 3 story

**File number (CNB):** 431.3

Address: 286 Meeting

Print: X

Negative:

Description: window detail

**File number (CNB):** 431.4

Address: 286 Meeting

Print: X

Negative:

Description: window detail

**File number (CNB):** 431.5

Address: 286 Meeting

Print: X

Negative:

Description: left side façade

**File number (CNB):** 431.6

Address: 286 Meeting

Print:

Negative: X

Description: Southside - original arcade of portico

**File number (CNB):** 432

Address: 342 Meeting

Print: X

Negative:

Description: north west corner from street

**File number (CNB):** 433

Address: 342 Meeting

Print: X

Negative:

Description: west side from cemetary

**File number (CNB):** 433 +-

Address: 342 Meeting

Print: X

Negative:

Description: north east corner from street, tower

**File number (CNB):** 433.1

Address: 342 Meeting

Print: X

Negative:

Description: north side

**File number (CNB):** 433.2

Address: 342 Meeting

Print: X

Negative:

Description: full view of ne corner

**File number (CNB):** 433.3

Address: 342 Meeting

Print: X

Negative:

Description: E side

**File number (CNB):** 433.4

Address: 342 Meeting

Print: X

Negative:

Description: tower and cupola

**File number (CNB):** 433.5

Address: 342 Meeting

Print: X

Negative:

Description: central door detail

**File number (CNB):** 433.6

Address: 342 Meeting

Print: X

Negative:

Description: south side window detail

**File number (CNB):** 434

Address: 350 Meeting

Print: X

Negative:

Description: east side

**File number (CNB):** 434 (1)

Address: 350 Meeting

Print:

Negative: X

Description: Eastside

**File number (CNB):** 434 (2)

Address: 350 Meeting

Print:

Negative: X

Description: Eastside

**File number (CNB):** 435

Address: 350 Meeting

Print: X

Negative:

Description: Rotunda

**File number (CNB):** 436

Address: 350 Meeting

Print: X

Negative:

Description: southwest corner

**File number (CNB):** 437

Address: 350 Meeting

Print: X

Negative:

Description: southeast corner/side view

**File number (CNB):** 438

Address: 350 Meeting

Print: X

Negative:

Description: Northeast corner

**File number (CNB):** 439

Address: 350 Meeting

Print: X

Negative:

Description: full east side façade

**File number (CNB):** 439.1

Address: 350 Meeting

Print: X

Negative:

Description: north side from street

**File number (CNB):** 439.2

Address: 350 Meeting

Print: X

Negative:

Description: NW corner from street

**File number (CNB):** 439.4 (1)

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at floor. Note temporary bracing

**File number (CNB):** 439.4 (2) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at floor. Note temporary bracing

**File number (CNB):** 439.4a (1)

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing mid-point to landing

**File number (CNB):** 439.4a (2) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing mid-point to landing

**File number (CNB):** 439.4a (3) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing mid-point to landing

**File number (CNB):** 439.4b (1)

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing to 2nd flr

**File number (CNB):** 439.4b (2) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing to 2nd flr

**File number (CNB):** 439.4b (3) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing to 2nd flr

**File number (CNB):** 439.4c (1)

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing, landing to 2nd flr, looking into stair hall. Note temporary vertical bracing

**File number (CNB):** 439.4c (2) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing, landing to 2nd flr, looking into stair hall. Note temporary vertical bracing

**File number (CNB):** 439.4c (3) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing, landing to 2nd flr, looking into stair hall. Note temporary vertical bracing

**File number (CNB):** 439.4d (1)

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing from 2nd flr

**File number (CNB):** 439.4d (2) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing from 2nd flr

**File number (CNB):** 439.4d (3) small

Address: 350 Meeting

Print:

Negative: X

Description: 1st flr - stair framing at landing from 2nd flr

**File number (CNB):** 439.4e (1)

Address: 350 Meeting

Print:

Negative: X

Description: Stair framing from landing up to 2nd flr

**File number (CNB):** 439.4e (2) small

Address: 350 Meeting

Print:

Negative: X

Description: Stair framing from landing up to 2nd flr

**File number (CNB):** 440

Address: 17 Chalmers

Print: X

Negative: X

Description: Northside

**File number (CNB):** 441

Address: 17 Chalmers

Print: X

Negative: X

Description: Southeast side

**File number (CNB):** 442



Address: 552 East Bay

Print: X

Negative:

Description: NW corner

**File number (CNB): 422.1**

Address: 552 East Bay

Print: X

Negative:

Description: s side loading dock detail

**File number (CNB): 443**

Address: 552 East Bay

Print: X

Negative:

Description: sw corner

**File number (CNB): 444**

Address: 552 East Bay

Print: X

Negative:

Description: NW corner

**File number (CNB): 445**

Address: 552 East Bay

Print: X

Negative:

Description: s side loading dock detail

**File number (CNB): 446**

Address: 635 East Bay

Print: X

Negative:

Description: House SE corner

**File number (CNB): 446.1**

Address: 635 East Bay

Print: X

Negative:

Description: complex E side

**File number (CNB): 446.2**

Address: 635 East Bay

Print: X

Negative:

Description: NE corner of complex

**File number (CNB): 446.3**

Address: 635 East Bay

Print: X

Negative:

Description: complex W side

**File number (CNB): 446.4**

Address: 635 East Bay

Print: X

Negative:

Description: " N side

**File number (CNB): 446.5**

Address: 635 East Bay

Print: X

Negative:

Description: house N side

**File number (CNB): 446.6**

Address: 635 East Bay

Print: X

Negative:

Description: " NW corner from N dependency

**File number (CNB): 446.7**

Address: 635 East Bay

Print: X

Negative:

Description: " SW corner

**File number (CNB): 446.8**

Address: 635 East Bay

Print: X

Negative:

Description: N dependency NE corner

**File number (CNB): 446.9**

Address: 635 East Bay

Print: X

Negative:

Description: " " SE corner

**File number (CNB): 446.10**

Address: 635 East Bay

Print: X

Negative:

Description: House, W side cupola and pediment

**File number (CNB): 446.11**

Address: 635 East Bay

Print: X

Negative:

Description: house, N side cupola and pediment

**File number (CNB): 446.12**

Address: 635 East Bay

Print:

Negative: X

Description: House - northeast corner

**File number (CNB): 447**

Address: 6 Gibbes

Print: X

Negative:

Description: sw corner

**File number (CNB): 448**

Address: 6 Gibbes

Print: X

Negative:

Description: se corner

**File number (CNB): 449**

Address: 6 Gibbes

Print: X

Negative:

Description: s side 1st flr cornice

**File number (CNB): 450**

Address: 6 Gibbes

Print: X

Negative:

Description: s side roof cornice

**File number (CNB): 451**

Address: 6 Gibbes

Print: X

Negative:

Description: s side ground flr entry

**File number (CNB): 452**

Address: 6 Gibbes

Print: X

Negative:

Description: s side ground flr entry E

**File number (CNB): 453**

Address: 14 Green

Print: X

Negative:

Description: entry gates do not appear to be original

**File number (CNB): 454**

Address: 31 Legare

Print: X

Negative:

Description: Front façade

**File number (CNB): 455**

Address: 31 Legare

Print: X

Negative:

Description: front and right corner

**File number (CNB): 456**

Address: 31 Legare

Print: X

Negative:

Description: back/right side view & kitchen

**File number (CNB): 457**

Address: 31 Legare

Print: X

Negative:

Description: Kitchen & laundry?

**File number (CNB): 458**

Address: 31 Legare

Print: X

Negative:

Description: carriage house/stables?

**File number (CNB): 459**

Address: 31 Legare

Print: X

Negative:

Description: Kitchen and living quarters

**File number (CNB): 460**

Address: 31 Legare

Print: X

Negative:

Description: stable from rear

**File number (CNB): 461**

Address: 82-86 Broad

Print: X

Negative:

Description: E side

**File number (CNB): 461.1**

Address: 82-86 Broad

Print:

Negative: X

Description: from southeast

**File number (CNB): 462**

Address: 82-86 Broad

Print: X

Negative:

Description: w side console

**File number (CNB): 463**

Address: 82-86 Broad

Print: X

Negative:

Description: s side columns

**File number (CNB): 464**

Address: 82-86 Broad

Print: X

Negative:

Description: s side columns

**File number (CNB): 464.1**

Address: 82-86 Broad

Print:

Negative: X

Description: Southside, 2nd floor, niche detail

**File number (CNB): 465**

Address: 60 Montagu

Print: X

Negative:

Description: SE side from street

**File number (CNB): 465.1**

Address: 60 Montagu

Print:

Negative: X

Description: House - southeast side

**File number (CNB): 465.2**

Address: 60 Montagu

Print:

Negative: X

Description: House- southeast side, east portico

**File number (CNB): 466**

Address: 60 Montagu

Print: X

Negative:

Description: east side

**File number (CNB): 466.1**

Address: 60 Montagu

Print:

Negative: X

Description: House- eastside

**File number (CNB): 467**

Address: 60 Montagu

Print: X

Negative:

Description: west side

**File number (CNB): 468**

Address: 60 Montagu

Print: X

Negative:

Description: ground flr iron work

**File number (CNB):** 468.1 (1)

Address: 60 Montagu

Print:

Negative: X

Description: House- southside, entry steps

**File number (CNB):** 468.1 (2)

Address: 60 Montagu

Print:

Negative: X

Description: House- southside, entry steps

**File number (CNB):** 468.1 (3)

Address: 60 Montagu

Print:

Negative: X

Description: House- southside, entry steps

**File number (CNB):** 468.2

Address: 60 Montagu

Print:

Negative: X

Description: House- southside, steps and railing detail showing foot scraper

**File number (CNB):** 468.3

Address: 60 Montagu

Print:

Negative: X

Description: Southside- cast iron balusters with stone cap on stucco wall and wood handrail

**File number (CNB):** 469

Address: 60 Montagu

Print: X

Negative:

Description: front door detail, cornice and tracery

**File number (CNB):** 470

Address: 60 Montagu

Print: X

Negative:

Description: column capitals and cornice

**File number (CNB):** 471

Address: 60 Montagu

Print: X

Negative:

Description: gate and porch (north side?)

**File number (CNB): 471.1**

Address: 60 Montagu

Print:

Negative: X

Description: House - northeast corner, iron garden fence & gate, c 1851

**File number (CNB): 472.1**

Address: 60 Montagu

Print:

Negative: X

Description: Southeast portico from southeast

**File number (CNB): 472**

Address: 60 Montagu

Print: X

Negative:

Description: iron work detail on east side porch

**File number (CNB): 472.2**

Address: 60 Montagu

Print:

Negative: X

Description: Southeast portico from east

**File number (CNB): 473**

Address: 60 Montagu

Print: X

Negative:

Description: street gate, iron work

**File number (CNB): 473.1**

Address: 60 Montagu

Print:

Negative: X

Description: Detail, ironwork in gates, c.1851

**File number (CNB): 473.2**

Address: 60 Montagu

Print:

Negative: X

Description: 1st floor hall, looking northwest into stair hall

**File number (CNB): 473.3**

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- hall, cornice and screen, pilaster cap

**File number (CNB): 473.4**

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- stair hall, looking west

**File number (CNB):** 473.5

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room looking northwest

**File number (CNB):** 473.6

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room chimney piece

**File number (CNB):** 473.7

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room mantel

**File number (CNB):** 473.7 (2)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room mantel

**File number (CNB):** 473.7 (3)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room mantel

**File number (CNB):** 473.8

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room, cornice at chimney piece

**File number (CNB):** 473.9

Address: 60 Montagu

Print:

Negative: X

Description: House - 1st flr, southeast room, east wall cornice

**File number (CNB):** 473.10 (1)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room, ceiling ornament, same for hall and southwest room

**File number (CNB):** 473.10 (2)

Address: 60 Montagu

Print:



Negative: X

Description: 1st flr- southeast room, ceiling ornament, same for hall and southwest room

**File number (CNB):** 473.10 (3)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southeast room, ceiling ornament, same for hall and southwest room

**File number (CNB):** 473.11

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southwest room looking northeast

**File number (CNB):** 473.12 (1)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southwest room mantel

**File number (CNB):** 473.12 (2)

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southwest room mantel

**File number (CNB):** 473.13

Address: 60 Montagu

Print:

Negative: X

Description: House - 1st flr, southwest room, west wall cornice

**File number (CNB):** 473.14

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- southwest room cornice at chimney piece

**File number (CNB):** 473.15

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- northeast room chimney piece

**File number (CNB):** 473.16

Address: 60 Montagu

Print:

Negative: X

Description: House - 1st flr, northeast room, mantle

**File number (CNB):** 473.17

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- northeast room cornice at chimney piece

**File number (CNB):** 473.18

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- northwest room mantel

**File number (CNB):** 473.19

Address: 60 Montagu

Print:

Negative: X

Description: 1st flr- northwest room cornice at chimney piece

**File number (CNB):** 473.20

Address: 60 Montagu

Print:

Negative: X

Description: House - 2nd flr, hall, south end, cornice

**File number (CNB):** 473.21

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southeast room chimney piece

**File number (CNB):** 473.22

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southeast room mantel

**File number (CNB):** 473.23

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southeast room cornice and over mantel crosette at chimney piece

**File number (CNB):** 473.24

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southwest room chimney piece

**File number (CNB):** 473.25

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southwest room mantel

**File number (CNB):** 473.26

Address: 60 Montagu

Print:

Negative: X

Description: House - 2nd flr, southwest room, cast iron fireplace enclosure

**File number (CNB):** 473.27

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- southwest room cornice and over mantel crosette at chimney piece

**File number (CNB):** 473.28

Address: 60 Montagu

Print:

Negative: X

Description: House - 2nd flr, northwest room, mantle. Northeast room, same

**File number (CNB):** 473.29

Address: 60 Montagu

Print:

Negative: X

Description: 2nd flr- hall, stair landing; note position of ascending stairs on floor

**File number (CNB):** 473.30

Address: 60 Montagu

Print:

Negative: X

Description: House - 2nd flr, northwest room, cornice at chimney piece. Northeast room, same

**File number (CNB):** 474

Address: 60 Montagu

Print: X

Negative:

Description: carriage house/stables?

**File number (CNB):** 475

Address: 60 Montagu

Print: X

Negative:

Description: side view of carriage house

**File number (CNB):** 476

Address: 60 Montagu

Print: X

Negative:

Description: street view of carriage house

**File number (CNB):** 477

Address: 60 Montagu

Print: X

Negative:

Description: Back of kitchen

**File number (CNB): 478**

Address: 60 Montagu

Print: X

Negative:

Description: front of kitchen

**File number (CNB): 479**

Address: 5 Queen

Print: X

Negative:

Description: right façade

**File number (CNB): 480**

Address: 5 Queen

Print: X

Negative:

Description: left side façade

**File number (CNB): 481**

Address: 5 Queen

Print: X

Negative:

Description: close up of brickwork on front door of L side

**File number (CNB): 481.1**

Address: 5 Queen

Print: X

Negative:

Description: view of l side arcade/brick work

**File number (CNB): 482**

Address: 8 South Battery

Print: X

Negative:

Description: front façade from right

**File number (CNB): 483**

Address: 8 South Battery

Print: X

Negative:

Description: front façade from left

**File number (CNB): 483.1 (1) H**

Address: 8 South Battery

Print:

Negative: X

Description: c.1768 House - southside stair railing after 1830

**File number (CNB): 483.1 (2) V**

Address: 8 South Battery

Print:

Negative: X

Description: House - southside stair railing after 1830

**File number (CNB):** 483.3

Address: 8 South Battery

Print:

Negative: X

Description: House- southside stair railing, bottom newell

**File number (CNB):** 484

Address: 8 South Battery

Print: X

Negative:

Description: street view of rear right

**File number (CNB):** 485

Address: 8 South Battery

Print: X

Negative:

Description: rear from yard

**File number (CNB):** 486

Address: 8 South Battery

Print: X

Negative:

Description: left side/front from street

**File number (CNB):** 487

Address: 8 South Battery

Print: X

Negative:

Description: stable

**File number (CNB):** 488

Address: 8 South Battery

Print: X

Negative:

Description: brick wall and gates

**File number (CNB):** 488.1

Address: 8 South Battery

Print: X

Negative:

Description: window detail

**File number (CNB):** 489

Address: 20 South Battery

Print: X

Negative:

Description: s side gates (ironwork)

**File number (CNB):** 489.1

Address: 20 South Battery

Print:

Negative: X

Description: Southside

**File number (CNB): 490**

Address: 20 South Battery

Print: X

Negative:

Description: Kitchen and living quarters

**File number (CNB): 491**

Address: 20 South Battery

Print: X

Negative:

Description: main entrance of front of house

**File number (CNB): 492**

Address: 20 South Battery

Print: X

Negative:

Description: right side of main house

**File number (CNB): 493**

Address: 26 South Battery

Print: X

Negative:

Description: garage left side of house

**File number (CNB): 494**

Address: 26 South Battery

Print: X

Negative:

Description: ^^

**File number (CNB): 495**

Address: 26 South Battery

Print: X

Negative:

Description: front of house

**File number (CNB): 496**

Address: 26 South Battery

Print: X

Negative:

Description: iron gate and front foor

**File number (CNB): 496.1**

Address: 26 South Battery

Print: X

Negative:

Description: door cornice detail

**File number (CNB): 497**

Address: 32 South Battery

Print: X  
Negative:  
Description: front left corner of house  
**File number (CNB): 498**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: iron gate to house detail  
**File number (CNB): 499**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: iron gate to drive detail  
**File number (CNB): 500**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: cupola  
**File number (CNB): 501**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: kitchen  
**File number (CNB): 502**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: kitchen/garage  
**File number (CNB): 503**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: back quarters  
**File number (CNB): 504**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: rear yard  
**File number (CNB): 504.1**  
Address: 32 South Battery  
Print: X  
Negative:  
Description: detail of door  
**File number (CNB): 505**

Address: 49 South Battery

Print: X

Negative:

Description: rear right side from street

**File number (CNB): 506**

Address: 49 South Battery

Print: X

Negative:

Description: right side from street

**File number (CNB): 507**

Address: 49 South Battery

Print: X

Negative:

Description: pediment detail

**File number (CNB): 508**

Address: 56 South Battery

Print: X

Negative:

Description: front front street, iron balustrade

**File number (CNB): 509**

Address: 56 South Battery

Print: X

Negative:

Description: iron work, balcony

**File number (CNB): 509.1**

Address: 56 South Battery

Print: X

Negative:

Description: front entrance and steps

**File number (CNB): 509.2**

Address: 56 South Battery

Print:

Negative: X

Description: House- southeast side, balcony and support bracket detail

**File number (CNB): 510**

Address: 266 St. Margaret

Print: X

Negative: X

Description: Lowndes Grove; westside

**File number (CNB): 511**

Address: 266 St. Margaret

Print: X

Negative: X

Description: Lowndes Grove; northside



**File number (CNB): 512**

Address: 266 St. Margaret

Print: X

Negative: X

Description: Lowndes Grove; eastside, west end

**File number (CNB): 513**

Address: 266 St. Margaret

Print: X

Negative: X

Description: Lowndes Grove; southside, west end

**File number (CNB): 514**

Address: 179 Rutledge

Print: X

Negative:

Description: front view from street

**File number (CNB): 515**

Address: 179 Rutledge

Print: X

Negative:

Description: rear left view from yard

**File number (CNB): 516**

Address: 179 Rutledge

Print: X

Negative:

Description: right side view

**File number (CNB): 517**

Address: 179 Rutledge

Print: X

Negative:

Description: left side view (porches)

**File number (CNB): 518**

Address: 179 Rutledge

Print: X

Negative:

Description: steps and front door, pediment

**File number (CNB): 518.1**

Address: 179 Rutledge

Print: X

Negative:

Description: pediment detail

**File number (CNB): 519**

Address: 179 Rutledge

Print: X

Negative:

Description: rear, kitchen?

**File number (CNB): 520**

Address: 185 Rutledge

Print: X

Negative:

Description: back and side corner of house

**File number (CNB): 521**

Address: 185 Rutledge

Print: X

Negative:

Description: front side

**File number (CNB): 522**

Address: 185 Rutledge

Print: X

Negative:

Description: front and left

**File number (CNB): 523**

Address: 185 Rutledge

Print: X

Negative:

Description: 2nd story detail

**File number (CNB): 524**

Address: 185 Rutledge

Print: X

Negative:

Description: exterior cornice detail

**File number (CNB): 525**

Address: 89 Smith

Print:

Negative: X

Description: House- southeast side

**File number (CNB): 525.1 (1)**

Address: 89 Smith

Print:

Negative: X

Description: House- southside bay

**File number (CNB): 525.1 (2)**

Address: 89 Smith

Print:

Negative: X

Description: House- southside bay

**File number (CNB): 525.1 (3)**

Address: 89 Smith

Print:

Negative: X

Description: House- southside bay

**File number (CNB):** 525.2

Address: 89 Smith

Print:

Negative: X

Description: House- southside bay direct

**File number (CNB):** 525.3

Address: 89 Smith

Print:

Negative: X

Description: House- southside bay, detail

**File number (CNB):** 525.4

Address: 89 Smith

Print:

Negative: X

Description: House- eastside entry

**File number (CNB):** 525.5

Address: 89 Smith

Print:

Negative: X

Description: House- 1st floor, southeast room, south wall

**File number (CNB):** 525.6

Address: 89 Smith

Print:

Negative: X

Description: House- 1st floor, southeast room, south wall niche

**File number (CNB):** 525.7 (1)

Address: 89 Smith

Print:

Negative: X

Description: House- 1st floor, southeast room, south wall niche ceiling

**File number (CNB):** 525.7 (2)

Address: 89 Smith

Print:

Negative: X

Description: House- 1st floor, southeast room, south wall niche ceiling

**File number (CNB):** 525.8

Address: 89 Smith

Print:

Negative: X

Description: House- 1st floor, southeast room, south wall niche wall

**File number (CNB):** 525.9

Address: 89 Smith

Print:  
Negative: X  
Description: House- 1st floor, southeast room, ceiling ornament  
**File number (CNB): 526**  
Address: 81 Rutledge  
Print: X  
Negative:  
Description: front left corner of house  
**File number (CNB): 527**  
Address: 81 Rutledge  
Print: X  
Negative:  
Description: rear right side from street  
**File number (CNB): 528**  
Address: 81 Rutledge  
Print: X  
Negative:  
Description: ground flr entry  
**File number (CNB): 528.1**  
Address: 81 Rutledge  
Print:  
Negative: X  
Description: House- eastside door grille  
**File number (CNB): 528.1 (2)**  
Address: 81 Rutledge  
Print:  
Negative: X  
Description: House- eastside door grille  
**File number (CNB): 529**  
Address: 81 Rutledge  
Print: X  
Negative:  
Description: 1st flr window balcony  
**File number (CNB): 529.1 (1)**  
Address: 81 Rutledge  
Print:  
Negative: X  
Description: House- 1st floor balcony ceiling  
**File number (CNB): 529.1 (2)**  
Address: 81 Rutledge  
Print:  
Negative: X  
Description: House- 1st floor balcony ceiling  
**File number (CNB): 529.1 (3)**

Address: 81 Rutledge

Print:

Negative: X

Description: House- 1st floor balcony ceiling

**File number (CNB):** 530

Address: 81 Rutledge

Print: X

Negative:

Description: window detail 2nd flr

**File number (CNB):** 531

Address: 81 Rutledge

Print: X

Negative:

Description: blind window detail, attic

**File number (CNB):** 532

Address: 81 Rutledge

Print: X

Negative:

Description: ground flr window, iron work detail

**File number (CNB):** 532.1 (1)

Address: 81 Rutledge

Print:

Negative: X

Description: House- southside, balcony railing, 1st and 2nd floors with wood railing

**File number (CNB):** 532.1 (2)

Address: 81 Rutledge

Print:

Negative: X

Description: House- southside, balcony railing, 1st and 2nd floors, with wood railing

**File number (CNB):** 532.1 (3)

Address: 81 Rutledge

Print:

Negative: X

Description: House- southside, balcony railing, 1st and 2nd floor, with wood railing

**File number (CNB):** 532.2

Address: 81 Rutledge

Print:

Negative: X

Description: House- eastside, 1/2 carriage gate. Other gate same, except initial "g" in lieu of "s" by FJ

Ortmann (Bragg) after 1905 sale of house to G. Sottile

**File number (CNB):** 533

Address: 93 Rutledge

Print: X

Negative:

Description: front right side

**File number (CNB):** 534 (1)

Address: 93 Rutledge

Print: X

Negative:

Description: full left side view from street

**File number (CNB):** 534 (2)

Address: 93 Rutledge

Print: X

Negative:

Description: left, front side view

**File number (CNB):** 535.1

Address: 93 Rutledge

Print:

Negative: X

Description: House- southside, cast iron stairs, Champion Iron Co., Kenton Ohio, no date

**File number (CNB):** 536

Address: 93 Rutledge

Print: X

Negative:

Description: front door, pediment

**File number (CNB):** 537

Address: 93 Rutledge

Print: X

Negative:

Description: 2nd flr window, corbels

**File number (CNB):** 538

Address: 93 Rutledge

Print: X

Negative:

Description: column cap and architrave detail

**File number (CNB):** 539

Address: 93 Rutledge

Print: X

Negative:

Description: window frame detail

**File number (CNB):** 540

Address: 93 Rutledge

Print: X

Negative:

Description: corbel, window detail

**File number (CNB):** 540.1

Address: 93 Rutledge

Print:

Negative: X

Description: House- southside, 2nd floor, balcony railing with wood handrail and bottom rail

**File number (CNB):** 540.2

Address: 93 Rutledge

Print:

Negative: X

Description: House- southside, carriage gate, one of two pair, one at this site, the other (the one photographed) at 28 Montague, the old dependency

**File number (CNB):** 541

Address: 94 Rutledge

Print: X

Negative:

Description: street view of front portico

**File number (CNB):** 542

Address: 94 Rutledge

Print: X

Negative:

Description: side view, wall view

**File number (CNB):** 543

Address: 94 Rutledge

Print: X

Negative:

Description: mid shot view of portico and right façade

**File number (CNB):** 544

Address: 94 Rutledge

Print: X

Negative:

Description: rear view

**File number (CNB):** 545 (1)

Address: 94 Rutledge

Print: X

Negative: X

Description: West entry

**File number (CNB):** 545 (2)

Address: 94 Rutledge

Print:

Negative: X

Description: West entry

**File number (CNB):** 545.1 (1)

Address: 94 Rutledge

Print: X

Negative: X

Description: Westside entry gate

**File number (CNB):** 545.1 (2)

Address: 94 Rutledge  
Print:  
Negative: X  
Description: Westside entry gate  
**File number (CNB):** 545.1 (3)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: Westside entry gate  
**File number (CNB):** 545.1 (4)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: Westside entry gate  
**File number (CNB):** 545.1 (5)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: Westside entry gate  
**File number (CNB):** 545.1 (6)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: Westside entry gate  
**File number (CNB):** 545.2  
Address: 94 Rutledge  
Print: X  
Negative: X  
Description: Westside entry, door hood  
**File number (CNB):** 545.3  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: House- entry railing, west side  
**File number (CNB):** 545.4 (1)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: House- westside, fence detail  
**File number (CNB):** 545.4 (2)  
Address: 94 Rutledge  
Print:  
Negative: X  
Description: House- westside, fence detail



**File number (CNB): 545.5**

Address: 94 Rutledge

Print:

Negative: X

Description: House- balcony detail; probably from earlier bldg, as it is not in character with other ironwork or house

**File number (CNB): 546**

Address: 94 Rutledge

Print: X

Negative:

Description: kitchen

**File number (CNB): 547**

Address: 94 Rutledge

Print: X

Negative:

Description: column caps and entablature of portico

**File number (CNB): 548**

Address: 95 Rutledge

Print: X

Negative:

Description: front entry and left side

**File number (CNB): 549**

Address: 95 Rutledge

Print: X

Negative:

Description: entry and right side

**File number (CNB): 549.1**

Address: 95 Rutledge

Print: X

Negative:

Description: gabled 3rd flr window detail

**File number (CNB): 550**

Address: 101 Rutledge

Print: X

Negative:

Description: similar style, front façade

**File number (CNB): 551**

Address: 34 Smith

Print: X

Negative:

Description: entry from street

**File number (CNB): 552**

Address: 34 Smith

Print: X

Negative: X

Description: Entry

**File number (CNB):** 552.1 (1)

Address: 34 Smith

Print:

Negative: X

Description: House- entry railing

**File number (CNB):** 552.1 (2)

Address: 34 Smith

Print:

Negative: X

Description: House- entry railing

**File number (CNB):** 552.2

Address: 34 Smith

Print:

Negative: X

Description: House- stair railing

**File number (CNB):** 552.3

Address: 34 Smith

Print:

Negative: X

Description: House- railing, cast iron urn

**File number (CNB):** 553

Address: 64 South Battery

Print:

Negative: X

Description: c.1772, William Gibbes; southwest corner; c.1800 major refilling, Sarah Smith; front entry steps and ironwork c.1800

**File number (CNB):** 553.1

Address: 64 South Battery

Print: X

Negative: X

Description: House- southside

**File number (CNB):** 553.2

Address: 64 South Battery

Print: X

Negative: X

Description: House- southeast side, roof detail

**File number (CNB):** 554

Address: 64 South Battery

Print: X

Negative:

Description: front door detail, pediment and framing

**File number (CNB):** 554.1 (1)

Address: 64 South Battery

Print: X

Negative: X

Description: House- southside entry

**File number (CNB):** 554.1 (2)

Address: 64 South Battery

Print:

Negative: X

Description: House- southside entry

**File number (CNB):** 554.2

Address: 64 South Battery

Print: X

Negative:

Description: 2nd flr winfow detal and pediment

**File number (CNB):** 554.2

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, pediment and 2nd floor, window detail (crosette)

**File number (CNB):** 554.3

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, stair railing, foot scraper and newal (note uneven hand turned twists)

**File number (CNB):** 555

Address: 64 South Battery

Print: X

Negative:

Description: gate/fence from street

**File number (CNB):** 555.1 (1) H

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, carriage and pass gates detail; Iron panels c. 1928; see Curtis, pg 28

**File number (CNB):** 555.1 (2) V

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, carriage and pass gates detail; Iron panels c. 1928; see Curtis, pg 28

**File number (CNB):** 555.2

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, carriage gate; Iron panel detail

**File number (CNB):** 555.3

Address: 64 South Battery

Print:

Negative: X

Description: House- southside, pass gate, iron panel detail

**File number (CNB):** 556

Address: 64 South Battery

Print: X

Negative:

Description: kitchen/garage

**File number (CNB):** 557

Address: 64 South Battery

Print: X

Negative:

Description: corbel detail

**File number (CNB):** 557.1

Address: 64 South Battery

Print: X

Negative:

Description: window

**File number (CNB):** 557.2

Address: 64 South Battery

Print: X

Negative:

Description: window

**File number (CNB):** 557.3

Address: 64 South Battery

Print: X

Negative:

Description: front entry and left side

**File number (CNB):** 557.4

Address: 64 South Battery

Print: X

Negative:

Description: stair to entry and iron balustrade

**File number (CNB):** 557.5

Address: 64 South Battery

Print: X

Negative:

Description: side view

**File number (CNB):** 557.6

Address: 64 South Battery

Print: X

Negative:

Description: kitchen

**File number (CNB):** 557.7

Address: 64 South Battery

Print: X

Negative:

Description: top down view of kitchen in back of complex

**File number (CNB):** 557.8

Address: 64 South Battery

Print: X

Negative:

Description: garage doors - attached to kitchen

**File number (CNB):** 557.9

Address: 64 South Battery

Print: X

Negative:

Description: rear view of entrance to quarters above garage

**File number (CNB):** 557.10

Address: 64 South Battery

Print: X

Negative:

Description: privy

**File number (CNB):** 557.11

Address: 64 South Battery

Print: X

Negative:

Description: interior front door/frame

**File number (CNB):** 557.12

Address: 64 South Battery

Print: X

Negative:

Description: entry hall and 1st flr stair

**File number (CNB):** 557.13

Address: 64 South Battery

Print: X

Negative:

Description: painted wall and detail of door on left in front hall

**File number (CNB):** 557.14

Address: 64 South Battery

Print: X

Negative:

Description: column cap detail in front hall before stairs

**File number (CNB):** 557.15

Address: 64 South Battery

Print: X

Negative:

Description: detail of 1st flr stairs

**File number (CNB):** 557.16

Address: 64 South Battery

Print: X

Negative:

Description: balustrade detail woodwork

**File number (CNB):** 557.17

Address: 64 South Battery

Print: X

Negative:

Description: 2nd floor landing window detail

**File number (CNB):** 557.18

Address: 64 South Battery

Print: X

Negative:

Description: 2nd flr room, 2 doors & fireplace

**File number (CNB):** 557.19

Address: 64 South Battery

Print: X

Negative:

Description: mantel detail, relief design

**File number (CNB):** 557.20

Address: 64 South Battery

Print: X

Negative:

Description: window looking across hall into opposite room

**File number (CNB):** 557.21

Address: 64 South Battery

Print: X

Negative:

Description: opposite room

**File number (CNB):** 557.22

Address: 64 South Battery

Print: X

Negative:

Description: mantel detail, relief design

**File number (CNB):** 557.23

Address: 64 South Battery

Print: X

Negative:

Description: mantel detail, relief design

**File number (CNB):** 557.24

Address: 64 South Battery

Print: X

Negative:

Description: cornice and door frame detail

**File number (CNB):** 557.25

Address: 64 South Battery

Print: X

Negative:

Description: cornice and crownmolding detail

**File number (CNB):** 557.26

Address: 64 South Battery

Print: X

Negative:

Description: opposite view of same room

**File number (CNB):** 557.27

Address: 64 South Battery

Print: X

Negative:

Description: dining room

**File number (CNB):** 557.28

Address: 64 South Battery

Print: X

Negative:

Description: mantel detail, relief design

**File number (CNB):** 557.29

Address: 64 South Battery

Print: X

Negative:

Description: mantel detail, relief design

**File number (CNB):** 557.30

Address: 64 South Battery

Print:

Negative: X

Description: House- 1st floor hall, looking northwest

**File number (CNB):** 557.31

Address: 64 South Battery

Print:

Negative: X

Description: House- 1st floor hall, stair newell

**File number (CNB):** 557.32

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor hall, looking northwest

**File number (CNB):** 557.33

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast corner, north wall

**File number (CNB):** 557.34

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, northwest wall, looking into southwest room

**File number (CNB):** 557.35

Address: 64 South Battery

Print:

Negative: X

Description: House- southeast room, north wall door to hall

**File number (CNB):** 557.36

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, west wall, door into southwest room

**File number (CNB):** 557.37

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, north wall chimney piece

**File number (CNB):** 557.38

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, north wall, mantle

**File number (CNB):** 557.39

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, north wall, cornice detail at chimney piece

**File number (CNB):** 557.40

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, ceiling at east end

**File number (CNB):** 557.40 (2)

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, ceiling at east end



**File number (CNB):** 557.41

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southeast room, ceiling at west end

**File number (CNB):** 557.42

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southwest corner, north wall

**File number (CNB):** 557.43

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southwest room, north wall chimney piece

**File number (CNB):** 557.44

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southwest wall, cornice detail at chimney piece

**File number (CNB):** 557.45

Address: 64 South Battery

Print:

Negative: X

Description: House- 2nd floor, southwest room, east wall, looking into southeast room

**File number (CNB):** 558

Address: 68 South Battery

Print: X

Negative:

Description: side view

**File number (CNB):** 559

Address: 68 South Battery

Print: X

Negative:

Description: side view from yard

**File number (CNB):** 560

Address: 68 South Battery

Print: X

Negative:

Description: wall/railing detail (ironwork)

**File number (CNB):** 561

Address: 68 South Battery

Print: X

Negative:

Description: gate detail ironwork

**File number (CNB): 562**

Address: 68 South Battery

Print: X

Negative:

Description: ground floor entry and 1st flr balustrade ironwork

**File number (CNB): 563**

Address: 68 South Battery

Print: X

Negative:

Description: interior mantel and mirror

**File number (CNB): 564**

Address: 68 South Battery

Print: X

Negative:

Description: cornice and door frame detail

**File number (CNB): 565**

Address: 68 South Battery

Print: X

Negative:

Description: view of parlor from living room

**File number (CNB): 566**

Address: 68 South Battery

Print: X

Negative:

Description: view of living room

**File number (CNB): 567**

Address: 68 South Battery

Print: X

Negative:

Description: dinning room

**File number (CNB): 568**

Address: 68 South Battery

Print: X

Negative:

Description: kitchen, back house

**File number (CNB): 569**

Address: 14 Thomas

Print: X

Negative: X

Description: St. Mark's Episc. Church c. 1887; southwest corner

**File number (CNB): 570**

Address: 14 Thomas

Print: X

Negative: X

Description: St. Mark's Episc. Church c. 1887; west side

**File number (CNB):** 571

Address: 54 Tradd

Print: X

Negative:

Description: front view from street

**File number (CNB):** 571.1

Address: 54 Tradd

Print:

Negative: X

Description: House- entry gate

**File number (CNB):** 571.2

Address: 54 Tradd

Print:

Negative: X

Description: House- southside, 2nd floor balcony, formerly on State Street (Frost), probably before Revolution

**File number (CNB):** 572

Address: 54 Tradd

Print: X

Negative:

Description: rear 1st flr entry

**File number (CNB):** 573

Address: 54 Tradd

Print: X

Negative:

Description: side view from yard

**File number (CNB):** 574

Address: 70 Tradd

Print: X

Negative:

Description: front view from street

**File number (CNB):** 575

Address: 70 Tradd

Print: X

Negative:

Description: front right view

**File number (CNB):** 576

Address: 70 Tradd

Print: X

Negative:

Description: left view of porch

**File number (CNB):** 577

Address: 70 Tradd  
Print: X  
Negative:  
Description: left rear view of porches  
**File number (CNB): 578**  
Address: 70 Tradd  
Print: X  
Negative:  
Description: main entry detail  
**File number (CNB): 579**  
Address: 70 Tradd  
Print: X  
Negative:  
Description: view of roof and surrounding  
**File number (CNB): 579 +-**  
Address: 70 Tradd  
Print: X  
Negative:  
Description: arcade  
**File number (CNB): 579.1**  
Address: 70 Tradd  
Print: X  
Negative: X  
Description: House- eastside, north end  
**File number (CNB): 580**  
Address: 70 Tradd  
Print: X  
Negative:  
Description: backyard  
**File number (CNB): 581**  
Address: 70 Tradd  
Print: X  
Negative:  
Description: rear entry  
**File number (CNB): 582**  
Address: 106 Tradd  
Print: X  
Negative:  
Description: front entry  
**File number (CNB): 583 +-**  
Address: 106 Tradd  
Print: X  
Negative:  
Description: right side from street

**File number (CNB): 583**

Address: 106 Tradd

Print: X

Negative:

Description: rear and right side

**File number (CNB): 583.1**

Address: 106 Tradd

Print: X

Negative:

Description: left and rear

**File number (CNB): 584 +-**

Address: 106 Tradd

Print: X

Negative:

Description: main door

**File number (CNB): 584.1**

Address: 106 Tradd

Print:

Negative: X

Description: House- southside, west railing on stoop, eastside same, c. 1935, made from old fencing replaced by brick wall. An earlier 19th century railing is directly behind this one.

**File number (CNB): 584.2 (1) small**

Address: 106 Tradd

Print:

Negative: X

Description: House- entry stoop, foot scraper pre-dating railings

**File number (CNB): 584.2 (2) double small**

Address: 106 Tradd

Print:

Negative: X

Description: House- entry stoop, foot scraper pre-dating railings

**File number (CNB): 585**

Address: 106 Tradd

Print: X

Negative:

Description: gate and wall to rear

**File number (CNB): 586**

Address: 106 Tradd

Print: X

Negative:

Description: yard and left façade

**File number (CNB): 586.1**

Address: 106 Tradd

Print: X

Negative:

Description: rear of house

**File number (CNB):** 586.2

Address: 106 Tradd

Print: X

Negative:

Description: front, blocked by tree

**File number (CNB):** 586.3

Address: 106 Tradd

Print: X

Negative:

Description: front door detail

**File number (CNB):** 586.4

Address: 106 Tradd

Print: X

Negative:

Description: mid flr window detail with pediment

**File number (CNB):** 586.5

Address: 106 Tradd

Print: X

Negative:

Description: top flr detail with cornice

**File number (CNB):** 586.6

Address: 106 Tradd

Print: X

Negative:

Description: roof, gabled dormer window

**File number (CNB):** 586.8

Address: 106 Tradd

Print:

Negative: X

Description: House- eastside, Orange St, carriage gates with iron picket overthrow

**File number (CNB):** 586.9

Address: 106 Tradd

Print:

Negative: X

Description: House- eastside, pass gate

**File number (CNB):** 586.10 (1)

Address: 106 Tradd

Print:

Negative: X

Description: House- north yard, hitching post

**File number (CNB):** 586.10 (2) small

Address: 106 Tradd

Print:

Negative: X

Description: House- north yard, hitching post

**File number (CNB): 587**

Address: 172 Tradd

Print: X

Negative:

Description: window detail

**File number (CNB): 588**

Address: 172 Tradd

Print: X

Negative:

Description: portico from street

**File number (CNB): 589**

Address: 172 Tradd

Print: X

Negative:

Description: right corner of porticogate and front entry detail

**File number (CNB): 589.1**

Address: 172 Tradd

Print: X

Negative:

Description: front door in portico detail

**File number (CNB): 589.2**

Address: 172 Tradd

Print: X

Negative:

Description: column cap detail

**File number (CNB): 589.3**

Address: 172 Tradd

Print:

Negative: X

Description: House- column cap detail

**File number (CNB): 589.4**

Address: 172 Tradd

Print:

Negative: X

Description: House- southside, balcony

**File number (CNB): 589.5**

Address: 172 Tradd

Print:

Negative: X

Description: House- eastside balcony

**File number (CNB): 590**

Address: 196 Tradd  
Print: X  
Negative:  
Description: front façade (reniassance style)  
**File number (CNB):** 591

Address: 196 Tradd  
Print: X  
Negative:  
Description: front and right façade  
**File number (CNB):** 592

Address: 60 Wentworth  
Print: X  
Negative:  
Description: front portico  
**File number (CNB):** 593 +-

Address: 60 Wentworth  
Print: X  
Negative:  
Description: front and left view  
**File number (CNB):** 593

Address: 60 Wentworth  
Print: X  
Negative:  
Description: ^  
**File number (CNB):** 594

Address: 60 Wentworth  
Print: X  
Negative:  
Description: right side facing front  
**File number (CNB):** 594 +-

Address: 60 Wentworth  
Print: X  
Negative:  
Description: left side facing front  
**File number (CNB):** 594.1

Address: 60 Wentworth  
Print: X  
Negative:  
Description:  
**File number (CNB):** 594.2

Address: 60 Wentworth  
Print: X  
Negative:  
Description: gate detail to yard from front



**File number (CNB): 595**

Address: 100 Wentworth

Print: X

Negative:

Description: front right of entry and steeple

**File number (CNB): 596**

Address: 100 Wentworth

Print: X

Negative:

Description: front left of entry and steeple

**File number (CNB): 597**

Address: 100 Wentworth

Print: X

Negative:

Description: rear view of left side and steeple

**File number (CNB): 598**

Address: 100 Wentworth

Print: X

Negative:

Description: archivolted entry central door

**File number (CNB): 599**

Address: 100 Wentworth

Print: X

Negative:

Description: spire detail

**File number (CNB): 600**

Address: 141 Wentworth

Print: X

Negative:

Description: front entry

**File number (CNB): 601**

Address: 147 Wentworth

Print: X

Negative:

Description: rear view

**File number (CNB): 601.1**

Address: 147 Wentworth

Print:

Negative: X

Description: House- northside, dormer and roof railing

**File number (CNB): 602**

Address: 147 Wentworth

Print: X

Negative:

Description: side view

**File number (CNB):** 602.1

Address: 147 Wentworth

Print:

Negative: X

Description: House- northwest corner, showing former carriage house (beyond frame house to left) to east of main house

**File number (CNB):** 602.2

Address: 147 Wentworth

Print:

Negative: X

Description: House- westside, typical terra-cotta cotton boll

**File number (CNB):** 603

Address: 147 Wentworth

Print: X

Negative:

Description: side view from across the street

**File number (CNB):** 604

Address: 147 Wentworth

Print: X

Negative:

Description: rear and side view

**File number (CNB):** 605

Address: 147 Wentworth

Print: X

Negative:

Description: further right rear and side view

**File number (CNB):** 606

Address: 147 Wentworth

Print: X

Negative:

Description: stairway to main entry

**File number (CNB):** 606.1

Address: 147 Wentworth

Print:

Negative: X

Description: House- northside, double pass gate and railing, carriage gate similar

**File number (CNB):** 606.2 (1)

Address: 147 Wentworth

Print:

Negative: X

Description: House- northside stoop railing

**File number (CNB):** 606.2 (2)

Address: 147 Wentworth

Print:

Negative: X

Description: House- northside stoop railing

**File number (CNB):** 606.2 (3)

Address: 147 Wentworth

Print:

Negative: X

Description: House- northside stoop railing

**File number (CNB):** 607

Address: 147 Wentworth

Print: X

Negative:

Description: detail of central stairway

**File number (CNB):** 608

Address: 147 Wentworth

Print: X

Negative:

Description: cupola

**File number (CNB):** 609

Address: 147 Wentworth

Print: X

Negative:

Description: carriage house

**File number (CNB):** 610

Address: 2 Amherst

Print: X

Negative: X

Description: Eastside, east gable and rectangular wing c.1840

**File number (CNB):** 611

Address: 2 Amherst

Print: X

Negative:

Description: front view of porches from street

**File number (CNB):** 612

Address: 2 Amherst

Print: X

Negative:

Description: view of side and rear from right

**File number (CNB):** 612 (1)

Address: 2 Amherst

Print:

Negative: X

Description: Northeast corner, rectangular wing c.1840, also east gable

**File number (CNB):** 612 (2)

Address: 2 Amherst

Print:

Negative: X

Description: Northeast corner, rectangular wing c.1840, also east gable

**File number (CNB):** 612 (3)

Address: 2 Amherst

Print:

Negative: X

Description: Northeast corner, rectangular wing c.1840, also east gable

**File number (CNB):** 613

Address: 2 Amherst

Print: X

Negative: X

Description: Northwest corner, stair tower

**File number (CNB):** 614

Address: 2 Amherst

Print: X

Negative: X

Description: Southwest corner, west and east gables c.1840; original roof hip on hip; original house 1 room on each of 3 floors with stair tower on north side

**File number (CNB):** 614.1

Address: 2 Amherst

Print:

Negative: X

Description: Ground floor, southwest wall

**File number (CNB):** 614.2

Address: 2 Amherst

Print: X

Negative: X

Description: Ground floor fireplace

**File number (CNB):** 614.3

Address: 2 Amherst

Print: X

Negative: X

Description: Ground floor cornice

**File number (CNB):** 614.4

Address: 2 Amherst

Print: X

Negative: X

Description: 1st flr- west end, one room in original house this floor

**File number (CNB):** 614.5

Address: 2 Amherst

Print:

Negative: X

Description: 1st flr- fireplace

**File number (CNB):** 614.6

Address: 2 Amherst

Print: X

Negative: X

Description: 1st flr- door and chimney closets

**File number (CNB):** 614.7

Address: 2 Amherst

Print: X

Negative: X

Description: 2nd flr- west, west end two rooms, now on this original floor; doubtful original

**File number (CNB):** 614.8

Address: 2 Amherst

Print: X

Negative:

Description: arch window frame stair from attic

**File number (CNB):** 614.9

Address: 2 Amherst

Print: X

Negative: X

Description: Stair hall from attic

**File number (CNB):** 614.10

Address: 2 Amherst

Print: X

Negative:

Description: ^^

**File number (CNB):** 615

Address: 108 Beaufain

Print: X

Negative:

Description: House S die

**File number (CNB):** 616

Address: 108 Beaufain

Print: X

Negative:

Description: " N side

**File number (CNB):** 617

Address: 108 Beaufain

Print: X

Negative:

Description: W side

**File number (CNB):** 618

Address: 108 Beaufain

Print: X

Negative:

Description: 1st flr E room looking S

**File number (CNB):** 619

Address: 108 Beaufain

Print: X

Negative:

Description: "" "" N wall detail

**File number (CNB):** 620

Address: 108 Beaufain

Print: X

Negative:

Description: "" looking N

**File number (CNB):** 621

Address: 108 Beaufain

Print: X

Negative:

Description: unidentified dependency & kitchen W side

**File number (CNB):** 622

Address: 108 Beaufain

Print: X

Negative:

Description: " SW corner

**File number (CNB):** 623

Address: 108 Beaufain

Print: X

Negative:

Description: Kitchen SE corner

**File number (CNB):** 624

Address: 108 Beaufain

Print: X

Negative:

Description: " 1st flr S room looking E

**File number (CNB):** 625

Address: 108 Beaufain

Print: X

Negative:

Description: " " " N room looking S

**File number (CNB):** 626

Address: 48 Elizabeth

Print: X

Negative:

Description: House pediemtn, console 3rd flr cornice

**File number (CNB):** 626.1

Address: 48 Elizabeth

Print: X

Negative:

Description: w fence on elizabeth st

**File number (CNB):** 626.2

Address: 48 Elizabeth

Print: X

Negative:

Description: N rear fence & gate on S side of mary Street

**File number (CNB):** 626.3

Address: 48 Elizabeth

Print: X

Negative:

Description: SW sides, showing entire W side of complex ( r to l: house, gallery, carriage house & stable, courtyard wall)

**File number (CNB):** 626.4

Address: 48 Elizabeth

Print: X

Negative:

Description: S Side: John Robinson c1817

**File number (CNB):** 626.5

Address: 48 Elizabeth

Print: X

Negative:

Description: SE sides, brick detail of pier terminal

**File number (CNB):** 626.6

Address: 48 Elizabeth

Print: X

Negative:

Description: N side carriage house and stable on right, kitchen and laundry on left

**File number (CNB):** 626.7

Address: 48 Elizabeth

Print: X

Negative:

Description: w side c 1858 gallery on left

**File number (CNB):** 626.8

Address: 48 Elizabeth

Print: X

Negative:

Description: s side 1st flr triple wdw exterior shutter and architrave (typical for all trip 1st flr wdw)

**File number (CNB):** 626.9

Address: 48 Elizabeth

Print: X

Negative:

Description: s side portico detail and door to 2nd flrr hall

**File number (CNB):** 626.10

Address: 48 Elizabeth

Print: X

Negative:

Description: s side portico - entry to 2nd flr hall

**File number (CNB):** 626.11

Address: 48 Elizabeth

Print: X

Negative:

Description: n side entry to 1st flr 1817

**File number (CNB):** 626.12

Address: 48 Elizabeth

Print: X

Negative:

Description: W side entry note original window arch over keystone 1858

**File number (CNB):** 626.13

Address: 48 Elizabeth

Print: X

Negative:

Description: 1st flr NW room entry from street looking E

**File number (CNB):** 626.14

Address: 48 Elizabeth

Print: X

Negative:

Description: 1st flr NW room entry from st - railing

**File number (CNB):** 626.15

Address: 48 Elizabeth

Print: X

Negative:

Description: " " " " "ceiling looking W

**File number (CNB):** 626.16

Address: 48 Elizabeth

Print: X

Negative:

Description: 1st flr NW gallery E wall

**File number (CNB):** 626.17

Address: 48 Elizabeth

Print: X

Negative:

Description: " " looking NW

**File number (CNB):** 626.18

Address: 48 Elizabeth

Print: X

Negative:



Description: " " cornice

**File number (CNB):** 626.19

Address: 48 Elizabeth

Print: X

Negative:

Description: " SW room lloking SE into SE room

**File number (CNB):** 626.20

Address: 48 Elizabeth

Print: X

Negative:

Description: " " double doors case looking E into SE room

**File number (CNB):** 626.21

Address: 48 Elizabeth

Print: X

Negative:

Description: " " mantel

**File number (CNB):** 626.22

Address: 48 Elizabeth

Print: X

Negative:

Description: " " ceiling ornament

**File number (CNB):** 626.23

Address: 48 Elizabeth

Print: X

Negative:

Description: " SE room looking NW to SW room

**File number (CNB):** 626.24

Address: 48 Elizabeth

Print: X

Negative:

Description: " " cornice

**File number (CNB):** 626.25

Address: 48 Elizabeth

Print: X

Negative:

Description: " " typical door and case

**File number (CNB):** 626.26

Address: 48 Elizabeth

Print: X

Negative:

Description: " E room E wall

**File number (CNB):** 626.27

Address: 48 Elizabeth

Print: X

Negative:

Description: " " ceiling ornament

**File number (CNB):** 626.28

Address: 48 Elizabeth

Print: X

Negative:

Description: " " mantel

**File number (CNB):** 626.29

Address: 48 Elizabeth

Print: X

Negative:

Description: " " cornice and overmantel mirror frame

**File number (CNB):** 626.30

Address: 48 Elizabeth

Print: X

Negative:

Description: 1st flr N central stairs looking up 1835

**File number (CNB):** 626.31

Address: 48 Elizabeth

Print: X

Negative: X

Description: 1st flr- north central stair hall, looking south to 1817 hall arch

**File number (CNB):** 626.32

Address: 48 Elizabeth

Print: X

Negative:

Description: 2nd flr hall looking N to stair hall stairs 1835

**File number (CNB):** 626.33

Address: 48 Elizabeth

Print: X

Negative:

Description: 2nd flr hall ceiling ornament

**File number (CNB):** 626.34

Address: 48 Elizabeth

Print: X

Negative:

Description: " SE room N & E walls

**File number (CNB):** 626.35

Address: 48 Elizabeth

Print: X

Negative:

Description: " " mantel

**File number (CNB):** 626.36

Address: 48 Elizabeth

Print: X

Negative:

Description: " SW rooms N wall

**File number (CNB):** 626.37

Address: 48 Elizabeth

Print: X

Negative:

Description: " " E & S walls

**File number (CNB):** 626.38

Address: 48 Elizabeth

Print: X

Negative:

Description: " NE rooms mantel w cast iron liner

**File number (CNB):** 626.39

Address: 48 Elizabeth

Print: X

Negative:

Description: " E room E wall

**File number (CNB):** 626.40

Address: 48 Elizabeth

Print: X

Negative:

Description: " " W wall

**File number (CNB):** 626.41

Address: 48 Elizabeth

Print: X

Negative:

Description: " " mantel

**File number (CNB):** 626.42

Address: 48 Elizabeth

Print: X

Negative:

Description: " " cornice

**File number (CNB):** 626.43

Address: 48 Elizabeth

Print: X

Negative: 333

Description: 3rd flr hall looking S note ceiling

**File number (CNB):** 626.44

Address: 48 Elizabeth

Print: X

Negative:

Description: 3rd flr hall looking N

**File number (CNB):** 626.45

Address: 48 Elizabeth

Print: X

Negative:

Description: 3rd flr N central stairhall ceiling ornament

**File number (CNB):** 626.46

Address: 48 Elizabeth

Print: X

Negative:

Description: 3rd flr SE room N wall

**File number (CNB):** 626.47

Address: 48 Elizabeth

Print: X

Negative:

Description: 3rd flr E wing (one of two identical rooms) NE wall

**File number (CNB):** 626.48

Address: 48 Elizabeth

Print: X

Negative:

Description: courtyard looking N from N side entry

**File number (CNB):** 626.49

Address: 48 Elizabeth

Print: X

Negative:

Description: " N wall from S

**File number (CNB):** 626.50

Address: 48 Elizabeth

Print: X

Negative:

Description: " Cow shed at front right, carriage house and stable on right

**File number (CNB):** 626.51

Address: 48 Elizabeth

Print: X

Negative:

Description: carriage house and stable E side

**File number (CNB):** 626.52

Address: 48 Elizabeth

Print: X

Negative:

Description: carriage house and stable N side

**File number (CNB):** 626.53

Address: 48 Elizabeth

Print: X

Negative:

Description: " " W side

**File number (CNB): 626.54**

Address: 48 Elizabeth

Print: X

Negative:

Description: " " typical 2nd flr window no sash behind wood shutter

**File number (CNB): 626.55**

Address: 48 Elizabeth

Print: X

Negative:

Description: carriage house and stable ground dlr

**File number (CNB): 626.56**

Address: 48 Elizabeth

Print: X

Negative:

Description: kitchena dn laundry W side

**File number (CNB): 626.57**

Address: 48 Elizabeth

Print: X

Negative:

Description: kitchen and laundry N side

**File number (CNB): 626.58**

Address: 48 Elizabeth

Print: X

Negative:

Description: Privy SE sides

**File number (CNB): 626.59**

Address: 48 Elizabeth

Print: X

Negative:

Description: cow shed SE sides

**File number (CNB): 626.60**

Address: 48 Elizabeth

Print:

Negative: X

Description: House- entry, westside, from photograph, c. 1920-30

**File number (CNB): 627**

Address: 8 Judith

Print: X

Negative:

Description: kitchen N side

**File number (CNB): 628**

Address: 8 Judith

Print: X

Negative:

Description: " NW corner  
**File number (CNB):** 629.1

Address: 8 Judith

Print: X

Negative:

Description: " W side

**File number (CNB):** 630

Address: 14 Lamboll

Print: X

Negative:

Description: SE corner

**File number (CNB):** 631

Address: 14 Lamboll

Print: X

Negative:

Description: SE entry detail

**File number (CNB):** 632

Address: 14 Lamboll

Print: X

Negative:

Description: portico cornice detail

**File number (CNB):** 633

Address: 14 Lamboll

Print: X

Negative:

Description: roof detail

**File number (CNB):** 634

Address: 19 King

Print: X

Negative:

Description: see 353 - Kitch, carriage house & rooms between 1851 house could have originally belonged to 19 King

**File number (CNB):** 635

Address: 19 King

Print: X

Negative:

Description: front view of entry from street

**File number (CNB):** 636

Address: 55 King

Print: X

Negative:

Description: carriage house?

**File number (CNB):** 637

Address: 55 King

Print: X

Negative: X

Description: House- privy, southeast corner

**File number (CNB): 638**

Address: 55 King

Print: X

Negative: X

Description: House- privy, southeast corner

**File number (CNB): 639**

Address: 55 King

Print: X

Negative: X

Description: House- slave quarters, southeast corner

**File number (CNB): 639.1**

Address: 55 King

Print:

Negative: X

Description: House- northeast corner

**File number (CNB): 639.2**

Address: 55 King

Print:

Negative: X

Description: House- southeast corner

**File number (CNB): 639.3**

Address: 55 King

Print:

Negative: X

Description: House- southside

**File number (CNB): 639.4**

Address: 55 King

Print:

Negative: X

Description: House- southside and dependencies showing connecting link, 20th c.

**File number (CNB): 640**

Address: 8 Legare

Print: X

Negative:

Description: irongate entry

**File number (CNB): 640.1**

Address: 8 Legare

Print:

Negative: X

Description: House- gate detail

**File number (CNB): 641**

Address: 8 Legare

Print: X

Negative:

Description: iron gate entry to driveway

**File number (CNB):** 642

Address: 14 Legare

Print: X

Negative:

Description: ^^

**File number (CNB):** 642.1

Address: 14 Legare

Print:

Negative: X

Description: House- pass and carriage gates, wood with iron inserts and overthrow

**File number (CNB):** 642.2

Address: 14 Legare

Print:

Negative: X

Description: House- westside railing and pilaster

**File number (CNB):** 643.2 (1)

Address: 14 Legare

Print:

Negative: X

Description: House- west entry, north panel detail

**File number (CNB):** 642.2 (2)

Address: 14 Legare

Print:

Negative: X

Description: House- west entry, north panel detail

**File number (CNB):** 642.2 (3)

Address: 14 Legare

Print:

Negative: X

Description: House- west entry, north panel detail

**File number (CNB):** 643

Address: 14 Legare

Print: X

Negative:

Description: entry way detail

**File number (CNB):** 643.1

Address: 14 Legare

Print: X

Negative:

Description: postamounts to left of 3rd gate (642)



**File number (CNB):** 643.3 (1)

Address: 14 Legare

Print:

Negative: X

Description: House- west entry, south panel detail

**File number (CNB):** 643.3 (2)

Address: 14 Legare

Print:

Negative: X

Description: House- west entry, south panel detail

**File number (CNB):** 643.4

Address: 14 Legare

Print:

Negative: X

Description: House- southside, 19th C., plant tree, cypress, column, and wrought iron hardware

**File number (CNB):** 643.5 (1)

Address: 14 Legare

Print:

Negative: X

Description: House- hitching post, cast iron

**File number (CNB):** 643.5 (2)

Address: 14 Legare

Print:

Negative: X

Description: House- hitching post, cast iron

**File number (CNB):** 644

Address: 14 Legare

Print: X

Negative:

Description: entry from street

**File number (CNB):** 645

Address: 14 Legare

Print: X

Negative:

Description: porch and entry from yard

**File number (CNB):** 646

Address: 14 Legare

Print: X

Negative:

Description: view of rear and side of house, and kitchen

**File number (CNB):** 647

Address: 14 Legare

Print: X

Negative:

Description: view from yard of porches

**File number (CNB): 648**

Address: 14 Legare

Print: X

Negative:

Description: guest house

**File number (CNB): 649**

Address: 16 Meeting

Print: X

Negative:

Description: 2nd street entry

**File number (CNB): 649.1**

Address: 16 Meeting

Print:

Negative: X

Description: House- entry gates and fencing, original to house

**File number (CNB): 649.2**

Address: 16 Meeting

Print:

Negative: X

Description: House- carriage gate and fencing

**File number (CNB): 650**

Address: 16 Meeting

Print: X

Negative:

Description: detail of 2nd entry way

**File number (CNB): 651**

Address: 16 Meeting

Print: X

Negative:

Description: entablature and capitals

**File number (CNB): 652**

Address: 16 Meeting

Print: X

Negative:

Description: 2nd story window detail - keystone

**File number (CNB): 653**

Address: 16 Meeting

Print: X

Negative:

Description: pediment detail

**File number (CNB): 654**

Address: 16 Meeting

Print: X

Negative:

Description: side view from street

**File number (CNB): 655**

Address: 51 Meeting

Print: X

Negative:

Description: postamount

**File number (CNB): 656**

Address: 51 Meeting

Print: X

Negative:

Description: entry from street, including wall n gate

**File number (CNB): 657**

Address: 51 Meeting

Print: X

Negative:

Description: front door detail

**File number (CNB): 658**

Address: 51 Meeting

Print: X

Negative:

Description: iron railing details (NR)

**File number (CNB): 659**

Address: 51 Meeting

Print: X

Negative:

Description: side view

**File number (CNB): 660**

Address: 51 Meeting

Print: X

Negative:

Description: side/rear view

**File number (CNB): 660.1**

Address: 51 Meeting

Print: X

Negative:

Description: detail of 1st flr window, lunette

**File number (CNB): 660.2**

Address: 51 Meeting

Print: X

Negative:

Description: 2nd flr window detail

**File number (CNB): 660.3**

Address: 51 Meeting

Print: X

Negative:

Description:

**File number (CNB): 661**

Address: 51 Meeting

Print: X

Negative:

Description: rear side

**File number (CNB): 662**

Address: 51 Meeting

Print: X

Negative:

Description: kitchen

**File number (CNB): 663**

Address: 4 Orange

Print: X

Negative:

Description: front right view of entry

**File number (CNB): 664**

Address: 4 Orange

Print: X

Negative:

Description: exterior roof detail

**File number (CNB): 665**

Address: 4 Orange

Print: X

Negative:

Description: living room - fireplace/mantel

**File number (CNB): 666**

Address: 4 Orange

Print: X

Negative:

Description: fireplace pediment detail

**File number (CNB): 667**

Address: 4 Orange

Print: X

Negative:

Description: mantel detail

**File number (CNB): 668**

Address: 4 Orange

Print: X

Negative:

Description: dining room

**File number (CNB): 669**

Address: 4 Orange  
Print: X  
Negative:  
Description: mantel detail  
**File number (CNB): 670**  
Address: 4 Orange  
Print: X  
Negative:  
Description: parlor  
**File number (CNB): 671**  
Address: 4 Orange  
Print: X  
Negative:  
Description: mantel detail  
**File number (CNB): 672**  
Address: 4 Orange  
Print: X  
Negative:  
Description: den/ sitting room  
**File number (CNB): 673**  
Address: 4 Orange  
Print: X  
Negative:  
Description: exterior view  
**File number (CNB): 674**  
Address: 4 Orange  
Print: X  
Negative:  
Description: kitchen mantel  
**File number (CNB): 675**  
Address: 4 Orange  
Print: X  
Negative:  
Description: workshop fireplace  
**File number (CNB): 676**  
Address: 9-11 Orange  
Print: X  
Negative:  
Description: front and left side  
**File number (CNB): 677**  
Address: 11 Orange  
Print: X  
Negative:  
Description: corner roof cornice

**File number (CNB): 678**

Address: 138 Wentworth

Print: X

Negative:

Description: front entry from gate

**File number (CNB): 678.1**

Address: 138 Wentworth

Print: X

Negative: X

Description: House- east carriage gate, west same. Not original

**File number (CNB): 679 +-**

Address: 138 Wentworth

Print: X

Negative:

Description: Front door

**File number (CNB): 679**

Address: 138 Wentworth

Print: X

Negative:

Description: Front door

**File number (CNB): 679 +-**

Address: 138 Wentworth

Print: X

Negative:

Description: Front door

**File number (CNB): 680**

Address: 138 Wentworth

Print: X

Negative:

Description: front door

**File number (CNB): 681**

Address: 138 Wentworth

Print: X

Negative:

Description: ceramic decoration and iron balustrade

**File number (CNB): 682**

Address: 138 Wentworth

Print: X

Negative:

Description: capitals and entablature detail

**File number (CNB): 683**

Address: 138 Wentworth

Print: X

Negative:

Description: courtyard doors

**File number (CNB): 684**

Address: 138 Wentworth

Print: X

Negative:

Description: fountain and side view

**File number (CNB): 685**

Address: 138 Wentworth

Print: X

Negative:

Description: rear view

**File number (CNB): 686**

Address: 138 Wentworth

Print: X

Negative:

Description: close up of hexagon structure

**File number (CNB): 687**

Address: 138 Wentworth

Print: X

Negative:

Description: rear side ^

**File number (CNB): 688**

Address: 138 Wentworth

Print: X

Negative:

Description: close up of iron work

**File number (CNB): 688.1i (1)**

Address: 138 Wentworth

Print:

Negative: X

Description: Southeast side

**File number (CNB): 688.1i (2)**

Address: 138 Wentworth

Print:

Negative: X

Description: Southeast side

**File number (CNB): 688.1i (3)**

Address: 138 Wentworth

Print:

Negative: X

Description: Southeast side

**File number (CNB): 689**

Address: 13 Pitt

Print: X

Negative: X

Description: House- westside brick cornice

**File number (CNB):** 690

Address: 88 Broad

Print: X

Negative: X

Description: Southside entry

**File number (CNB):** 690.1

Address: 88 Broad

Print:

Negative: X

Description: Southside entry with frontispiece removed

**File number (CNB):** 690.2

Address: 88 Broad

Print:

Negative: X

Description: Painted brickwood behind removed frontispiece

**File number (CNB):** 691

Address: 72 Tradd

Print: X

Negative: X

Description: Frothingham-McNeill Tenament; southeast corner; Jerkin head on gambrel roof

**File number (CNB):** 692

Address: 72 Tradd

Print: X

Negative:

Description: barn style structure from side and rear

**File number (CNB):** 693

Address: 126 Tradd

Print: X

Negative:

Description: front and left side entry

**File number (CNB):** 693.1

Address: 126 Tradd

Print:

Negative: X

Description: House- carriage gate by Ortman (Bragg)

**File number (CNB):** 694

Address: 126 Tradd

Print: X

Negative:

Description: right and front

**File number (CNB):** 695

Address: 126 Tradd



Print: X  
Negative:  
Description: kitchen/laundry  
**File number (CNB): 696**  
Address: 126 Tradd  
Print: X  
Negative:  
Description: rear view of kitchen  
**File number (CNB): 697**  
Address: 126 Tradd  
Print: X  
Negative:  
Description: kitchen hearth  
**File number (CNB): 698**  
Address: 126 Tradd  
Print: X  
Negative:  
Description: 2nd hearth  
**File number (CNB): 699**  
Address: 54 Queen  
Print: X  
Negative:  
Description: rearer view  
**File number (CNB): 700**  
Address: 54 Queen  
Print: X  
Negative:  
Description: drawing room  
**File number (CNB): 701**  
Address: 54 Queen  
Print: X  
Negative:  
Description: opposite view of room  
**File number (CNB): 702**  
Address: Auldbrass Plantation  
Print: X  
Negative:  
Description: Beaufort County  
**File number (CNB): 703**  
Address: Auldbrass Plantation  
Print: X  
Negative:  
Description: Beaufort County  
**File number (CNB): 704**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 705**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 706**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 707**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 708**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 709**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 710**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 711**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 712**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 713**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 714**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 714 +-**

Address: Auldbrass Plantation

Print: X

Negative:

Description: Beaufort County

**File number (CNB): 715**

Address: 89 Beaufain

Print: X

Negative:

Description: entry detail. Stone floor case in frame

**File number (CNB): 715.1**

Address: 89 Beaufain

Print: X

Negative:

Description: NW corner

**File number (CNB): 715.2**

Address: 89 Beaufain

Print: X

Negative:

Description: N side

**File number (CNB): 716**

Address: 75 Church

Print: X

Negative: X

Description: 75 Church stables c.1810-16; 77 Church house and shop c.1819

**File number (CNB): 716.1**

Address: 77 Church

Print: X

Negative: X

Description: East and North sides

**File number (CNB): 717**

Address: 143-145 Church

Print: X

Negative: X

Description: Pirate House; east side

**File number (CNB):** 717.1

Address: 143-145 Church

Print: X

Negative: X

Description: East side- roof, dormer, and chimney detail; cornice new

**File number (CNB):** 718

Address: 43 Wentworth

Print: X

Negative:

Description: front entry portico

**File number (CNB):** 718.1

Address: 43 Wentworth

Print: X

Negative: X

Description: St. Andrews Lutheran Church c.1840; west side

**File number (CNB):** 718.2

Address: 43 Wentworth

Print: X

Negative:

Description: iron gate entry

**File number (CNB):** 718.3

Address: 43 Wentworth

Print:

Negative: X

Description: House- northside, pass gate

**File number (CNB):** 718.3 (2)

Address: 43 Wentworth

Print:

Negative: X

Description: House- northside pass gate

**File number (CNB):** 718.3 (3)

Address: 43 Wentworth

Print:

Negative: X

Description: House- northside pass gate

**File number (CNB):** 719

Address: 89 Hasell

Print: X

Negative:

Description: front entry portico from street

**File number (CNB):** 719.1

Address: 89 Hasell

Print: X

Negative:

Description: right corner view

**File number (CNB):** 719.2

Address: 89 Hasell

Print: X

Negative:

Description: gate

**File number (CNB):** 719.3 (1)

Address: 89 Hasell

Print:

Negative: X

Description: St. Mary's Church- westside

**File number (CNB):** 719.3 (2)

Address: 89 Hasell

Print:

Negative: X

Description: St. Mary's Church- westside

**File number (CNB):** 720

Address: 90 Hasell

Print: X

Negative:

Description: portico and pediment

**File number (CNB):** 720.1

Address: 90 Hasell

Print: X

Negative:

Description: right side

**File number (CNB):** 720.2

Address: 90 Hasell

Print: X

Negative:

Description: front right corner

**File number (CNB):** 720.3

Address: 90 Hasell

Print: X

Negative:

Description: irongate entry

**File number (CNB):** 720.4

Address: 90 Hasell

Print: X

Negative:

Description: window detail

**File number (CNB):** 720.5

Address: 90 Hasell

Print: X

Negative:

Description: entablature detail

**File number (CNB):** 720.6

Address: 90 Hasell

Print: X

Negative:

Description: column and door detail

**File number (CNB):** 720.7

Address: 90 Hasell

Print: X

Negative:

Description: candle post on postamount

**File number (CNB):** 720.8

Address: 90 Hasell

Print: X

Negative:

Description: rear view

**File number (CNB):** 720.9

Address: 90 Hasell

Print: X

Negative:

Description: west facing view of interior

**File number (CNB):** 720.10

Address: 90 Hasell

Print: X

Negative:

Description: east facing view of interior

**File number (CNB):** 720.11

Address: 90 Hasell

Print: X

Negative:

Description: ceiling detail

**File number (CNB):** 720.12

Address: 90 Hasell

Print: X

Negative:

Description: ceiling detail

**File number (CNB):** 720.13

Address: 90 Hasell

Print: X

Negative:

Description: altar detail

**File number (CNB):** 720.14

Address: 90 Hasell

Print: X

Negative:

Description: apse

**File number (CNB):** 720.15

Address: 90 Hasell

Print:

Negative: X

Description: Kahal Kadosh Bethelohim- southside, east end of fencing, pass gate, c. 1794

**File number (CNB):** 721

Address: 409 King

Print: X

Negative:

Description: front and right façade

**File number (CNB):** 721.1

Address: 409 King

Print: X

Negative:

Description: left façade

**File number (CNB):** 721.2

Address: 409 King

Print: X

Negative:

Description: front right entry

**File number (CNB):** 722

Address: 105 Meeting

Print: X

Negative:

Description: front entry portico

**File number (CNB):** 722.1

Address: 105 Meeting

Print: X

Negative:

Description: gate, iron work

**File number (CNB):** 722.2

Address: 105 Meeting

Print: X

Negative:

Description: gate entry iron work

**File number (CNB):** 722.3

Address: 105 Meeting

Print: X

Negative:

Description: main doors

**File number (CNB): 722.4**

Address: 105 Meeting

Print: X

Negative:

Description: dome view

**File number (CNB): 722.5**

Address: 105 Meeting

Print: X

Negative:

Description: dome view

**File number (CNB): 722.6**

Address: 105 Meeting

Print: X

Negative:

Description: general space, columns

**File number (CNB): 722.7**

Address: 105 Meeting

Print: X

Negative:

Description: door way

**File number (CNB): 722.8**

Address: 105 Meeting

Print: X

Negative:

Description: marble mantel

**File number (CNB): 722.9**

Address: 105 Meeting

Print: X

Negative:

Description: double door open post and lintel looking into central room

**File number (CNB): 722.10**

Address: 105 Meeting

Print: X

Negative:

Description: ball room with small stage

**File number (CNB): 722.11**

Address: 105 Meeting

Print: X

Negative:

Description: candelier detail

**File number (CNB): 722.12**

Address: 105 Meeting

Print:

Negative: X



Description: North carriage gate, eastside, south gate same

**File number (CNB):** 722.13 (1)

Address: 105 Meeting

Print:

Negative: X

Description: Eastside- railing and gate braces

**File number (CNB):** 722.13 (2)

Address: 105 Meeting

Print:

Negative: X

Description: Eastside- railing and gate braces

**File number (CNB):** 722.13 (3)

Address: 105 Meeting

Print:

Negative: X

Description: Eastside- railing and gate braces

**File number (CNB):** 723

Address: 90 Meeting

Print: X

Negative:

Description: front gate on street

**File number (CNB):** 723.1

Address: 90 Meeting

Print: X

Negative:

Description: 2 view of gate

**File number (CNB):** 723.2

Address: 90 Meeting

Print: X

Negative:

Description: open gate

**File number (CNB):** 723.3 (1) V

Address: 90 Meeting

Print:

Negative: X

Description: Washington Park- gate and railing braces

**File number (CNB):** 723.3 (2) H

Address: 90 Meeting

Print:

Negative: X

Description: Washington Park- gate and railing braces

**File number (CNB):** 723.4 (1)

Address: 90 Meeting

Print:

Negative: X  
Description: Washington Park- south carriage gate  
**File number (CNB):** 723.4 (2)  
Address: 90 Meeting  
Print:  
Negative: X  
Description: Washington Park- south carriage gate  
**File number (CNB):** 723.4 (3)  
Address: 90 Meeting  
Print:  
Negative: X  
Description: Washington Park- south carriage gate  
**File number (CNB):** 723.5  
Address: 90 Meeting  
Print:  
Negative: X  
Description: Washington Park- Henry Timrod bust  
**File number (CNB):** 724  
Address: 135 Meeting  
Print: X  
Negative:  
Description: large gate entry  
**File number (CNB):** 724.1  
Address: 135 Meeting  
Print: X  
Negative:  
Description: second view of gate  
**File number (CNB):** 724.2  
Address: 135 Meeting  
Print: X  
Negative:  
Description: both gates in front of structure  
**File number (CNB):** 724.3  
Address: 135 Meeting  
Print:  
Negative: X  
Description: West railing, north gate from east  
**File number (CNB):** 724.4  
Address: 135 Meeting  
Print:  
Negative: X  
Description: West railing, north gate from north  
**File number (CNB):** 724.5  
Address: 135 Meeting

Print:

Negative: X

Description: Eastside- fencing from Old Artillery Hall, c. 1847, southside Wentworth between Meeting and King, moved 1955

**File number (CNB):** 724.6

Address: 135 Meeting

Print:

Negative: X

Description: Westside- railing and gate braces

**File number (CNB):** 725

Address: 188 Meeting

Print: X

Negative:

Description: public market main entry

**File number (CNB):** 725 +-

Address: 188 Meeting

Print: X

Negative:

Description: detail of double staircase

**File number (CNB):** 725 +-

Address: 188 Meeting

Print: X

Negative:

Description: detail of staircase ironwork

**File number (CNB):** 725.1

Address: 188 Meeting

Print: X

Negative:

Description: right façade

**File number (CNB):** 725.2

Address: 188 Meeting

Print: X

Negative:

Description: right side down the stree

**File number (CNB):** 725.3

Address: 188 Meeting

Print: X

Negative:

Description: rear view of market

**File number (CNB):** 725.4

Address: 188 Meeting

Print: X

Negative:

Description: 2nd market

**File number (CNB): 725.5**

Address: 188 Meeting

Print: X

Negative:

Description: 3rd market

**File number (CNB): 725.6**

Address: 188 Meeting

Print: X

Negative:

Description: end of market

**File number (CNB): 725.7**

Address: 188 Meeting

Print: X

Negative:

Description: left side front view down the street

**File number (CNB): 725.8**

Address: 188 Meeting

Print: X

Negative:

Description: pediment detail,

**File number (CNB): 725.11**

Address: 188 Meeting

Print: X

Negative:

Description: lamp post ironwork detail

**File number (CNB): 725.12**

Address: 188 Meeting

Print: X

Negative:

Description: ironwork detail

**File number (CNB): 726**

Address: 172 Rutledge

Print: X

Negative:

Description: front view

**File number (CNB): 726.1**

Address: 172 Rutledge

Print: X

Negative:

Description: front view from right

**File number (CNB): 726.2**

Address: 172 Rutledge

Print: X

Negative:

Description: pediment and chimney detail

**File number (CNB):** 726.3

Address: 172 Rutledge

Print: X

Negative:

Description: pointed arch window attic detail

**File number (CNB):** 726.4

Address: 172 Rutledge

Print: X

Negative:

Description: front door, lunette window detail

**File number (CNB):** 726.5

Address: 172 Rutledge

Print: X

Negative:

Description: pediment, right corner detail

**File number (CNB):** 726.6

Address: 172 Rutledge

Print: X

Negative:

Description: second flr balcony iron balustrade detail

**File number (CNB):** 726.7

Address: 172 Rutledge

Print: X

Negative:

Description: balcony detail

**File number (CNB):** 726.8

Address: 172 Rutledge

Print: X

Negative:

Description: cornice detail

**File number (CNB):** 726.9

Address: 172 Rutledge

Print: X

Negative:

Description: ceiling medallion detail

**File number (CNB):** 726.10

Address: 172 Rutledge

Print: X

Negative:

Description: left side view

**File number (CNB):** 726.11

Address: 172 Rutledge

Print: X

Negative:

Description: simliar view

**File number (CNB):** 726.12

Address: 172 Rutledge

Print: X

Negative:

Description: entablature over windows

**File number (CNB):** 726.13

Address: 172 Rutledge

Print: X

Negative:

Description: arcade

**File number (CNB):** 726.14

Address: 172 Rutledge

Print: X

Negative:

Description: iron work and shutter detail

**File number (CNB):** 726.15

Address: 172 Rutledge

Print: X

Negative:

Description: rear street view

**File number (CNB):** 726.16

Address: 172 Rutledge

Print: X

Negative:

Description: exterior non-entry view

**File number (CNB):** 726.17

Address: 172 Rutledge

Print: X

Negative:

Description: exterior non-entry view

**File number (CNB):** 726.18

Address: 172 Rutledge

Print: X

Negative:

Description: exterior non-entry view

**File number (CNB):** 726.19

Address: 172 Rutledge

Print: X

Negative:

Description: exterior non-entry view

**File number (CNB):** 726.20

Address: 172 Rutledge

Print: X  
Negative:  
Description: exterior non-entry view  
**File number (CNB):** 726.21  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: iron work  
**File number (CNB):** 726.22  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: ground flr entrance and foyer  
**File number (CNB):** 726.23  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: entry way door setail  
**File number (CNB):** 726.24  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: stairwell, cantelever  
**File number (CNB):** 726.25  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: looking up into cupola/skylight  
**File number (CNB):** 726.26  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: living room and mantel  
**File number (CNB):** 726.27  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: detail to left of 1st entry way closed door  
**File number (CNB):** 726.28  
Address: 172 Rutledge  
Print: X  
Negative:  
Description: ^^^ open door  
**File number (CNB):** 726.29

Address: 172 Rutledge

Print: X

Negative:

Description: view of 1st flr entry way from stairs

**File number (CNB):** 726.30

Address: 172 Rutledge

Print: X

Negative:

Description: second floor landing and door ways

**File number (CNB):** 726.31

Address: 172 Rutledge

Print: X

Negative:

Description: second floor view of stairs to third flr

**File number (CNB):** 726.32

Address: 172 Rutledge

Print: X

Negative:

Description: view of second floor landing and doors, decorated cielings and walls

**File number (CNB):** 726.33

Address: 172 Rutledge

Print: X

Negative:

Description: view of stairs going up

**File number (CNB):** 726.34

Address: 172 Rutledge

Print: X

Negative:

Description: room off of stair well to right view of oval space, door and portait

**File number (CNB):** 726.35

Address: 172 Rutledge

Print: X

Negative:

Description: ceiling medallion detail

**File number (CNB):** 726.36

Address: 172 Rutledge

Print: X

Negative:

Description: doorway detail and decoration

**File number (CNB):** 726.37

Address: 172 Rutledge

Print: X

Negative:

Description: sunroom, off main room



**File number (CNB): 726.38**

Address: 172 Rutledge

Print: X

Negative:

Description: main room looking into sunroom (left)

**File number (CNB): 726.39**

Address: 172 Rutledge

Print: X

Negative:

Description: doorframe detail and cornice

**File number (CNB): 726.40**

Address: 172 Rutledge

Print: X

Negative:

Description: marble mantel

**File number (CNB): 726.41**

Address: 172 Rutledge

Print: X

Negative:

Description: relief decorated mantel

**File number (CNB): 726.42**

Address: 172 Rutledge

Print: X

Negative:

Description: quad wide doors close, mantel and central door

**File number (CNB): 726.43**

Address: 172 Rutledge

Print: X

Negative:

Description: 3rd flr landing and arch way

**File number (CNB): 726.44**

Address: 172 Rutledge

Print: X

Negative:

Description: ceiling detail

**File number (CNB): 726.45**

Address: 172 Rutledge

Print: X

Negative:

Description: view of the stair wall from hall

**File number (CNB): 726.46**

Address: 172 Rutledge

Print: X

Negative:

Description: dooframe detail

**File number (CNB):** 726.47

Address: 172 Rutledge

Print: X

Negative:

Description: living room

**File number (CNB):** 726.48

Address: 172 Rutledge

Print: X

Negative:

Description: ceiling detail, square

**File number (CNB):** 726.49

Address: 172 Rutledge

Print: X

Negative:

Description: stairwell to top flor

**File number (CNB):** 726.50

Address: 172 Rutledge

Print: X

Negative:

Description: door was under springing arch

**File number (CNB):** 726.51

Address: 172 Rutledge

Print: X

Negative:

Description: another room and mantel

**File number (CNB):** 726.52

Address: 172 Rutledge

Print: X

Negative:

Description: opposite view of room

**File number (CNB):** 726.53

Address: 172 Rutledge

Print: X

Negative:

Description: skylight above central staircase

**File number (CNB):** 726.54

Address: 172 Rutledge

Print: X

Negative:

Description: dinning room/hall

**File number (CNB):** 726.55

Address: 172 Rutledge

Print: X

Negative:

Description: dinning hall with view onto porch

**File number (CNB):** 726.56

Address: 172 Rutledge

Print: X

Negative:

Description: mirror

**File number (CNB):** 726.57

Address: 172 Rutledge

Print: X

Negative:

Description: mantel and angel reliefs

**File number (CNB):** 726.58

Address: 172 Rutledge

Print: X

Negative:

Description: doorknob detail

**File number (CNB):** 726.59 (1)

Address: 172 Rutledge

Print:

Negative: X

Description: Northside- one half old carriage gate, placed here 1980, originally on Rutledge, then moved, c. 1880 to Smith. Attributed to lusti by Bragg and thus of c. 1850 work. Bottom panel of lattice removed. See Curtis "Gateways and Doorways of Charleston" 1926

**File number (CNB):** 726.59 (2)

Address: 172 Rutledge

Print:

Negative: X

Description: Northside- one half old carriage gate, placed here 1980, originally on Rutledge, then moved, c. 1880 to Smith. Attributed to lusti by Bragg and thus of c. 1850 work. Bottom panel of lattice removed. See Curtis "Gateways and Doorways of Charleston" 1926

**File number (CNB):** 726.59 (3)

Address: 172 Rutledge

Print:

Negative: X

Description: Northside- one half old carriage gate, placed here 1980, originally on Rutledge, then moved, c. 1880 to Smith. Attributed to lusti by Bragg and thus of c. 1850 work. Bottom panel of lattice removed. See Curtis "Gateways and Doorways of Charleston" 1926

**File number (CNB):** 726.59 (4)

Address: 172 Rutledge

Print:

Negative: X

Description: Northside- one half old carriage gate, placed here 1980, originally on Rutledge, then moved, c. 1880 to Smith. Attributed to lusti by Bragg and thus of c. 1850 work. Bottom panel of lattice

removed. See Curtis "Gateways and Doorways of Charleston" 1926

**File number (CNB):** 726.59 (5)

Address: 172 Rutledge

Print:

Negative: X

Description: Northside- one half old carriage gate, placed here 1980, originally on Rutledge, then moved, c. 1880 to Smith. Attributed to Justi by Bragg and thus of c. 1850 work. Bottom panel of lattice removed. See Curtis "Gateways and Doorways of Charleston" 1926

**File number (CNB):** 726.6

Address: 172 Rutledge

Print:

Negative: X

Description: Iron gate and fencing, c. 1880. "Charleston Iron Works" on cast iron gate threshold; Cast iron wall cap under railing

**File number (CNB):** 727

Address: 39 South Battery

Print: X

Negative:

Description:

**File number (CNB):** 727.1

Address: 39 South Battery

Print: X

Negative:

Description:

**File number (CNB):** 727.2

Address: 39 South Battery

Print: X

Negative:

Description:

**File number (CNB):** 727.3

Address: 39 South Battery

Print: X

Negative:

Description:

**File number (CNB):** 728

Address: 18 Bull

Print: X

Negative:

Description: SE side all window dorr and wall arched of rubbed and gauged red brick. Walls of brown brick, stucco on wall understairs not original

**File number (CNB):** 728.1

Address: 18 Bull

Print: X

Negative:

Description: w side

**File number (CNB): 728.2**

Address: 18 Bull

Print: X

Negative:

Description: n side. New terrace 1970 - not line of former porch roof & joist seats

**File number (CNB): 728.3**

Address: 18 Bull

Print: X

Negative:

Description: s side. Ground flr entry

**File number (CNB): 728.4**

Address: 18 Bull

Print: X

Negative:

Description: s side 1st flr entry

**File number (CNB): 728.5**

Address: 18 Bull

Print: X

Negative:

Description: s side 2nd flr center bay and attac fan window

**File number (CNB): 728.6**

Address: 18 Bull

Print: X

Negative:

Description: entry gate & fence, eastm s side w gates same except opposite hand

**File number (CNB): 728.7**

Address: 18 Bull

Print: X

Negative:

Description: s side carraige house

**File number (CNB): 728.8**

Address: 18 Bull

Print: X

Negative:

Description: w side carriage house

**File number (CNB): 728.9**

Address: 18 Bull

Print: X

Negative:

Description: se side office

**File number (CNB): 728.10**

Address: 18 Bull

Print: X

Negative:

Description: sw side office (note brick cornice)

**File number (CNB):** 728.11

Address: 18 Bull

Print: X

Negative:

Description: 1st flr hall entry

**File number (CNB):** 728.12

Address: 18 Bull

Print: X

Negative:

Description: ^ looking N to stair hall

**File number (CNB):** 728.13

Address: 18 Bull

Print: X

Negative:

Description: ^^ arch detail, pilaster cap and cornice

**File number (CNB):** 728.14

Address: 18 Bull

Print: X

Negative:

Description: 1st flr stair hall late door to basement showing original open stair well wainscot running behind door jamb under stair soffitt (see also 286 Calhoun, 281.6)

**File number (CNB):** 728.15

Address: 18 Bull

Print: X

Negative:

Description: 1st floor stair hall ceiling

**File number (CNB):** 728.16

Address: 18 Bull

Print: X

Negative:

Description: 1st floor SW room N wall

**File number (CNB):** 728.17

Address: 18 Bull

Print: X

Negative:

Description: ^ mantel detail - added 1970

**File number (CNB):** 728.18

Address: 18 Bull

Print: X

Negative:

Description: 1st flr view from SW room showing mid 19th c arches

**File number (CNB):** 128.19

Address: 18 Bull

Print: X

Negative:

Description: 1st flr SE room N wall

**File number (CNB):** 728.20

Address: 18 Bull

Print: X

Negative:

Description: 1st flr SE room mantle detail

**File number (CNB):** 728.21

Address: 18 Bull

Print: X

Negative:

Description: 1st flr NW room S wall

**File number (CNB):** 728.22

Address: 18 Bull

Print: X

Negative:

Description: 1st flr NW room mantel detail

**File number (CNB):** 728.23

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr stair hall, landing freize & balustrade looking S

**File number (CNB):** 728.24

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr stair hall looking w

**File number (CNB):** 728.25

Address: 18 Bull

Print: X

Negative:

Description: 2nd ^ ceiling from s center room

**File number (CNB):** 728.26

Address: 18 Bull

Print: X

Negative:

Description: 2nd ^^ landing looking NE

**File number (CNB):** 728.27

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr center room, door to SW room (typical center room door, cornice and wainscot)

**File number (CNB): 728.28**

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr S center room, door, entablature and cornice detail

**File number (CNB): 728.29**

Address: 18 Bull

Print: X

Negative:

Description: end flr SE room N wall

**File number (CNB): 728.30**

Address: 18 Bull

Print: X

Negative:

Description: 2nd ^ mantel detail (appears to be original)

**File number (CNB): 728.31**

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr SE room, window case (door case same) and waiscot detail

**File number (CNB): 728.32**

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr SE room cornice detail

**File number (CNB): 728.33**

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr SW room N wall

**File number (CNB): 728.34**

Address: 18 Bull

Print: X

Negative:

Description: 2nd ^ mantel detail (typical interior paneling of shutter, shutter bar, and recessed spandrel throughout the house)

**File number (CNB): 728.35**

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr SW room, mantel detail appears to be original but some ornament missing

**File number (CNB): 728.36**

Address: 18 Bull

Print: X



Negative:

Description: 2nd flr SW room cornice detail

**File number (CNB):** 728.37

Address: 18 Bull

Print: X

Negative:

Description: 2nd flr nw room S wall

**File number (CNB):** 728.38

Address: 18 Bull

Print: X

Negative:

Description: 2nd ^ mantel detail

**File number (CNB):** 728.39

Address: 18 Bull

Print: X

Negative:

Description: s side, stoop railing assumed original to house

**File number (CNB):** 729

Address: 222 Calhoun

Print: X

Negative:

Description: s side

**File number (CNB):** 729.1

Address: 222 Calhoun

Print: X

Negative:

Description: se side

**File number (CNB):** 729.2

Address: 222 Calhoun

Print: X

Negative:

Description: portico and entablature % column cap detail

**File number (CNB):** 730

Address: 126 Coming

Print: X

Negative:

Description: w side

**File number (CNB):** 730.1

Address: 126 Coming

Print: X

Negative:

Description: s side

**File number (CNB):** 730.2

Address: 126 Coming

Print: X

Negative:

Description: e side

**File number (CNB):** 730.3

Address: 126 Coming

Print: X

Negative:

Description: n side

**File number (CNB):** 730.4

Address: 126 Coming

Print: X

Negative:

Description: portico, w side

**File number (CNB):** 730.5

Address: 126 Coming

Print: X

Negative:

Description: centry entry door, W side

**File number (CNB):** 730.6

Address: 126 Coming

Print: X

Negative:

Description: minor entry doors to balcony, w side

**File number (CNB):** 730.7

Address: 126 Coming

Print: X

Negative:

Description: tower detail from SE

**File number (CNB):** 730.8

Address: 126 Coming

Print: X

Negative:

Description: s side windows on tower base

**File number (CNB):** 730.9

Address: 126 Coming

Print: X

Negative:

Description: nace looking se

**File number (CNB):** 730.10

Address: 126 Coming

Print: X

Negative:

Description: nace looking w

**File number (CNB):** 730.11

Address: 126 Coming

Print: X

Negative:

Description: altar apse

**File number (CNB):** 730.12

Address: 126 Coming

Print: X

Negative:

Description: altar apse-pilaster cap and cornice

**File number (CNB):** 730.13

Address: 126 Coming

Print: X

Negative:

Description: altar apse-table and nuch tabernacles

**File number (CNB):** 730.14

Address: 126 Coming

Print: X

Negative:

Description: altar from original st luck's church (see #342-344)

**File number (CNB):** 730.15

Address: 126 Coming

Print: X

Negative:

Description: nave, balcony col cap and cornice

**File number (CNB):** 730.16

Address: 126 Coming

Print: X

Negative:

Description: organ, bates case, 1853, from balcony

**File number (CNB):** 730.17

Address: 126 Coming

Print: X

Negative:

Description: organ ^ nace

**File number (CNB):** 730.18

Address: 126 Coming

Print: X

Negative:

Description: cemetery, Johnson Mausoleum S side

**File number (CNB):** 730.19

Address: 126 Coming

Print: X

Negative:

Description: cemetery ^ entablature and column capital

**File number (CNB): 730.20**

Address: 126 Coming

Print:

Negative: X

Description: Westside- double pass gate, compare 57 Meeting

**File number (CNB): 730.21**

Address: 126 Coming

Print:

Negative: X

Description: Westside- railing and gate braces

**File number (CNB): 731**

Address: 6 Glebe

Print:

Negative: X

Description: s side

**File number (CNB): 731.1**

Address: 6 Glebe

Print:

Negative: X

Description: w side

**File number (CNB): 731.2**

Address: 6 Glebe

Print:

Negative: X

Description: n side

**File number (CNB): 731.3**

Address: 6 Glebe

Print:

Negative: X

Description: e side

**File number (CNB): 731.4**

Address: 6 Glebe

Print:

Negative: X

Description: s entry stairs

**File number (CNB): 731.5**

Address: 6 Glebe

Print:

Negative: X

Description: s entry

**File number (CNB): 731.6**

Address: 6 Glebe

Print:

Negative: X

Description: 1st flr hall looking s

**File number (CNB):** 731.7

Address: 6 Glebe

Print:

Negative: X

Description: 1st flr hall looking n

**File number (CNB):** 731.8

Address: 6 Glebe

Print:

Negative: X

Description: 1st flr sw room w wall - typical window wall

**File number (CNB):** 731.9

Address: 6 Glebe

Print:

Negative: X

Description: 1st flr sw room e wall, typical paneling of house (except NE room 1st floor)

**File number (CNB):** 731.10

Address: 6 Glebe

Print:

Negative: X

Description: 1st flr se room n wall

**File number (CNB):** 731.11

Address: 6 Glebe

Print:

Negative: X

Description: typical 1st floor mantel except NE room

**File number (CNB):** 731.12

Address: 6 Glebe

Print:

Negative: X

Description: typical 1st flr cornice & 2nd flr hall

**File number (CNB):** 731.13

Address: 6 Glebe

Print:

Negative: X

Description: 1st floor NE room S wall

**File number (CNB):** 731.14

Address: 6 Glebe

Print:

Negative: X

Description: 2nd flr SE room N wall

**File number (CNB):** 731.15

Address: 6 Glebe

Print:

Negative: X

Description: 2nd flr SE room N wall

**File number (CNB):** 731.16

Address: 6 Glebe

Print:

Negative: X

Description: 2nd flr SeE cornice detail (typical in all rooms except hall)

**File number (CNB):** 732

Address: 7 Glebe

Print:

Negative: X

Description: typical 2nd mantel

**File number (CNB):** 732.1

Address: 7 Glebe

Print:

Negative: X

Description: e side

**File number (CNB):** 732.2

Address: 7 Glebe

Print:

Negative: X

Description: NE side

**File number (CNB):** 733

Address: 243 King

Print:

Negative: X

Description: E side

**File number (CNB):** 733.1

Address: 243 King

Print:

Negative: X

Description: N Side

**File number (CNB):** 734

Address: 405 King

Print:

Negative: X

Description: E side

**File number (CNB):** 734.1

Address: 405 King

Print:

Negative: X

Description: Sunday School building (left) c 1909, office building (right) 1961 E side

**File number (CNB):** 734.2

Address: 405 King

Print:

Negative: X

Description: NW side

**File number (CNB):** 734.3

Address: 405 King

Print:

Negative: X

Description: Sunday School e side entry

**File number (CNB):** 734.4

Address: 405 King

Print:

Negative: X

Description: e side, center entry

**File number (CNB):** 734.5

Address: 405 King

Print:

Negative: X

Description: e side tower detail at belfry

**File number (CNB):** 735

Address: 456 King

Print:

Negative: X

Description: N Side

**File number (CNB):** 735.1

Address: 456 King

Print:

Negative: X

Description: sw original fence & gates removed (1930) and are now behind 135 meeting st

**File number (CNB):** 735.2

Address: 456 King

Print:

Negative: X

Description: w side ground floor entry

**File number (CNB):** 735.3

Address: 456 King

Print:

Negative: X

Description: w side 1st floor patio

**File number (CNB):** 735.4

Address: 456 King

Print:

Negative: X

Description: s side

**File number (CNB):** 735.5

Address: 456 King

Print:

Negative: X

Description: sw corner portico detail

**File number (CNB):** 735.6

Address: 456 King

Print:

Negative: X

Description: e side of the house

**File number (CNB):** 735.7

Address: 456 King

Print:

Negative: X

Description: dependency s side

**File number (CNB):** 735.8

Address: 456 King

Print:

Negative: X

Description: carriage house, w side

**File number (CNB):** 735.9

Address: 456 King

Print:

Negative: X

Description: 1st floor portico to entry hall s side, note jib doors under window

**File number (CNB):** 735.10

Address: 456 King

Print:

Negative: X

Description: ground floor, stair hall

**File number (CNB):** 735.11

Address: 456 King

Print:

Negative: X

Description: gr flr hall ceiling

**File number (CNB):** 735.12

Address: 456 King

Print:

Negative: X

Description: 1st flr hall ceiling

**File number (CNB):** 735.13

Address: 456 King

Print:

Negative: X

Description: 1st flr stair hall door to portico



**File number (CNB): 735.14**

Address: 456 King

Print:

Negative: X

Description: 1st flr w room n wall

**File number (CNB): 735.15**

Address: 456 King

Print:

Negative: X

Description: 1st floor w room, e&s walls, looking into hall

**File number (CNB): 735.16**

Address: 456 King

Print:

Negative: X

Description: 1st flr w room, e wall, false foor, pass door to same hall

**File number (CNB): 735.17**

Address: 456 King

Print:

Negative: X

Description: 1st flr w room, chimney piece, mantel new - original sent to DC 1930

**File number (CNB): 735.18**

Address: 456 King

Print:

Negative: X

Description: 1st flr w room, cornice

**File number (CNB): 735.19**

Address: 456 King

Print:

Negative: X

Description: 1st flr w room, ceiling ornament

**File number (CNB): 735.20**

Address: 456 King

Print:

Negative: X

Description: 1st flr ballroom looking SE

**File number (CNB): 735.21**

Address: 456 King

Print:

Negative: X

Description: 1st flr ballroom typical window

**File number (CNB): 735.22**

Address: 456 King

Print:

Negative: X

Description: 1st flr ballroom cornice, window architrave

**File number (CNB):** 735.23

Address: 456 King

Print:

Negative: X

Description: 1st flr ballroom ceiling ornament

**File number (CNB):** 735.24

Address: 456 King

Print:

Negative: X

Description: 1st flr hall ceiling

**File number (CNB):** 735.25

Address: 456 King

Print:

Negative: X

Description: discarded original mantel, placement unknown

**File number (CNB):** 736

Address: 289 Meeting

Print: X

Negative:

Description: Masonic Temple, front from street

**File number (CNB):** 736.1

Address: 289 Meeting

Print: X

Negative:

Description: side viwe from street

**File number (CNB):** 737

Address: 20 Montagu

Print: X

Negative:

Description: front street view

**File number (CNB):** 737.1

Address: 20 Montagu

Print: X

Negative:

Description: view of porch from street (left)

**File number (CNB):** 737.2

Address: 20 Montagu

Print: X

Negative:

Description: right side from street

**File number (CNB):** 737.3

Address: 20 Montagu

Print: X

Negative:

Description: front door detail

**File number (CNB):** 737.4

Address: 20 Montagu

Print: X

Negative:

Description: balcony column and cornice detail

**File number (CNB):** 737.5

Address: 20 Montagu

Print: X

Negative:

Description: rear view of complex from street

**File number (CNB):** 738.1

Address: 57 Pitt

Print: X

Negative: X

Description: Bethel Methodist Church c.1853; north side (south side same)

**File number (CNB):** 739 (1)

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; south side

**File number (CNB):** 739 (2)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; south side

**File number (CNB):** 739 (3)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; south side

**File number (CNB):** 739.1

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; east side

**File number (CNB):** 739.2

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; west side; note stepped entasis of pilasters and lack of 5 pilaster caps

**File number (CNB):** 739.3

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; south side door and frontis piece

**File number (CNB):** 739.4 (1)

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; south side door entablature

**File number (CNB):** 739.4 (2)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; south side door entablature

**File number (CNB):** 739.4 (3)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; south side door entablature

**File number (CNB):** 739.5 (1)

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; column cap and cornice detail

**File number (CNB):** 739.5 (2)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; column cap and cornice detail

**File number (CNB):** 739.5 (3)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; column cap and cornice detail

**File number (CNB):** 739.6

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; Nave, looking North

**File number (CNB):** 739.7 (1)

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; Nave, looking South

**File number (CNB):** 739.7 (2)

Address: 68 Spring

Print:

Negative: X

Description: St. James (United) Methodist Church c.1858; Nave, looking South

**File number (CNB):** 739.8

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; balcony railing and supporting cast iron column

**File number (CNB):** 739.9

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; Reredos

**File number (CNB):** 739.10

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; Reredos, entablature, and column cap

**File number (CNB):** 739.11

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; Reredos, crown of arch and dove of peace

**File number (CNB):** 739.12

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858;pulpit

**File number (CNB):** 739.13

Address: 68 Spring

Print: X

Negative: X

Description: St. James (United) Methodist Church c.1858; original organ pipes, polychrome; organ has disappeared; no identification on pipies

**File number (CNB):** 740

Address: 128 Wentworth

Print: X

Negative:

Description: front left corner from street

**File number (CNB):** 740.1

Address: 128 Wentworth

Print: X

Negative:

Description: central entry from steps

**File number (CNB):** 741

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: main entrance

**File number (CNB):** 741.1

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: left side of the house

**File number (CNB):** 741.2

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: back side

**File number (CNB):** 741.3

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: right side from street

**File number (CNB):** 741.4

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: chimney detail

**File number (CNB):** 741.5

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: front doors detail

**File number (CNB):** 741.6

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: cornice and column detail from porch

**File number (CNB):** 741.7

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: foundation and railing detail (porch)

**File number (CNB):** 741.8

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: interior living room

**File number (CNB):** 741.9

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 741.10

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: dado/wainscotting woodwork detail

**File number (CNB):** 741.11

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: mantel detail, post and lintel form

**File number (CNB):** 741.12

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: door detail

**File number (CNB):** 741.13

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: cornice and window architrave detail

**File number (CNB):** 741.14

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: hall landing and 2 door ways

**File number (CNB):** 741.15

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: balustrade on second floor landing

**File number (CNB):** 741.16

Address: Berkeley Co. Lawson's Pond

Print: X

Negative:

Description: window in stairwell

**File number (CNB):** 741.17

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Northside- showing original porch railing

**File number (CNB):** 741.18 (1)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Northwest sides

**File number (CNB):** 741.18 (2)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Northwest sides

**File number (CNB):** 741.19 (1)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Northeast corner, porch cornice

**File number (CNB):** 741.19 (2)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Northeast corner, porch cornice

**File number (CNB):** 741.20 (1)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Porch column base and railing detail

**File number (CNB):** 741.20 (2)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Porch column base and railing detail

**File number (CNB):** 741.21 (1)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X

Description: Porch ceiling

**File number (CNB):** 741.21 (2)

Address: Berkeley Co. Lawson's Pond

Print:

Negative: X



Description: Porch ceiling

**File number (CNB):** 742

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: front right corner of house from yard

**File number (CNB):** 742.1

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: left side of house

**File number (CNB):** 742.2

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: rear view

**File number (CNB):** 742.3

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: right side from street

**File number (CNB):** 742.4

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: front door

**File number (CNB):** 742.5

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: window on porch, detail of shutters

**File number (CNB):** 742.6

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: dinning room mantel

**File number (CNB):** 742.7

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 742.8

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 742.9

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: cornice detail

**File number (CNB):** 742.10

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: living room looking into entrance hall

**File number (CNB):** 742.11

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: hall way, view into doorway and closed wood door

**File number (CNB):** 742.12

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: detail of mantel in living room

**File number (CNB):** 742.13

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: cornice detail

**File number (CNB):** 723.14

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: corner cubbard detail

**File number (CNB):** 742.15

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: cornice above door detail (keystone)

**File number (CNB):** 742.16

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 742.17

Address: Berkeley Co. Lewisfield

Print: X

Negative:

Description: main stairs

**File number (CNB): 743**

Address: Berkeley Co. Loch Dhu

Print: X

Negative:

Description: front viwe of house (east side)

**File number (CNB): 743**

Address: Berkeley Co. Loch Dhu

Print:

Negative: X

Description: Southside- date on chimney 1812; near NE corner of intersection of state hwy 6 and county road 59

**File number (CNB): 743.1**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: West side

**File number (CNB): 743.2**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: Northeast side; late addition on north side c.1950

**File number (CNB): 743.3**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: South side double entry to southeast and southwest rooms; no hall at front of house, only between rear (north) rooms, a common feature in this particular area

**File number (CNB): 743.4**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southwest room, north wall

**File number (CNB): 743.5**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southwest room, chimney piece

**File number (CNB): 743.6**

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southwest room cornice

**File number (CNB):** 743.7

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southwest room, door to portico; on exterior walls, wainscot stiles are centered under window architraves

**File number (CNB):** 743.8

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southeast room, north wall; doors, wainscot, and base are painted to imitate wood, slightly grained; wainscot panel has 1/4 - 3/8" painted mould with quarter-round corners; wainscot stiles on exterior walls are centered under window architraves

**File number (CNB):** 743.9

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southeast room chimney piece

**File number (CNB):** 743.10

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- southeast room, cornice

**File number (CNB):** 743.11

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: 1st flr- northeast room chimney piece

**File number (CNB):** 743.12

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: Kitchen- southeast side

**File number (CNB):** 743.13

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: Smokehouse- southwest side

**File number (CNB):** 743.14

Address: Berkeley Co. Loch Dhu

Print: X

Negative: X

Description: Barn- southeast side

**File number (CNB): 744**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Approach road from west, looking east

**File number (CNB): 744.1 (1)**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Approach road at west side of house, looking west

**File number (CNB): 744.1 (2)**

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Approach road at west side of house, looking west

**File number (CNB): 744.1 (3)**

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Approach road at west side of house, looking west

**File number (CNB): 744.2**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Southside; Thomas Broughton c.1714; off old US 52 south of Monck's Corner

**File number (CNB): 744.3**

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southwest side

**File number (CNB): 744.4**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: West side, looking north; note water table of tile which copies original brick, a few pieces of which remain

**File number (CNB): 744.5**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: North side; shed roof c.1930, brick face dormer not original with house, date unknown; door in right side pavilion not original

**File number (CNB): 744.6 (1)**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: East side

**File number (CNB):** 744.6 (2)

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: East side

**File number (CNB):** 744.7 (1)

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Southside- entry

**File number (CNB):** 744.7 (2)

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southside- entry

**File number (CNB):** 744.8 (1)

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Southside entry, pediment detail; ornament reputedly a copy of original found in attic during 1920 restoration

**File number (CNB):** 744.8 (2)

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southside entry, pediment detail; ornament reputedly a copy of original found in attic during 1920 restoration

**File number (CNB):** 744.8 (3)

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southside entry, pediment detail; ornament reputedly a copy of original found in attic during 1920 restoration

**File number (CNB):** 744.9

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: North side- entry and stair hall dormer; this dormer not original to house; note Flemish bond brickwork vs. English bond of house; shed roof and entry to basement at right c.1930

**File number (CNB):** 744.10

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: North side, northwest corner room, entry; northeast corner room same

**File number (CNB):** 744.11

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: West side, 3 different types of window trim, raking brick cornice and 2nd floor string course

**File number (CNB):** 744.12

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: West side, details; chimney, brick, cornices, and corner room roof

**File number (CNB):** 744.13

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Typical corner room weather vane, 4 thus; note date which has not been proved or disproved

**File number (CNB):** 744.14

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: Southeast corner room- typical for all four thus

**File number (CNB):** 744.15 (1)

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: 1st flr- southeast room, northwest walls; all woodwork c.1800

**File number (CNB):** 744.15 (2)

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: 1st flr- southeast room, northwest walls; all woodwork c.1800

**File number (CNB):** 744.16

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: 1st flr- southeast room mantel c.1800

**File number (CNB):** 744.17

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative: X

Description: 1st flr- southeast room, entry from south

**File number (CNB): 744.18**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: cornice detail

**File number (CNB): 744.19**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: parlor wall and mantel

**File number (CNB): 744.20**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: mantel detail

**File number (CNB): 744.21**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: living room wall and mantel

**File number (CNB): 744.22**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: mantel detail

**File number (CNB): 744.23**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: cornice detail

**File number (CNB): 744.24**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: breakfast room

**File number (CNB): 744.25**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: 1st flr front hall facing front

**File number (CNB): 744.26**

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:



Description: front hall facing rear

**File number (CNB):** 744.27

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: bedroom view, wall and mantel

**File number (CNB):** 744.28

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: first flr detail of stairs and sideboard

**File number (CNB):** 744.29

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: 2nd bedroom wall and mantel

**File number (CNB):** 744.30

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 744.31

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: original structure photos

**File number (CNB):** 744.32

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: ^

**File number (CNB):** 744.33

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: ^^

**File number (CNB):** 744.34

Address: Berkeley Co. Mulberry Plantation

Print: X

Negative:

Description: ^^^

**File number (CNB):** 744.45

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southside, c. 1920-30, From Bishop and Mrs. C.F. Allison collection

**File number (CNB):** 744.46

Address: Berkeley Co. Mulberry Plantation

Print:

Negative: X

Description: Southside- from collection of Bishop and Mrs. C.F. Allison

**File number (CNB):** 745

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: front view

**File number (CNB):** 745.1

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: side

**File number (CNB):** 745.2

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: rear

**File number (CNB):** 745.3

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: side

**File number (CNB):** 745.4

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: porch detail

**File number (CNB):** 745.5

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: exterior cornice

**File number (CNB):** 745.6

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: living room wall and mantel

**File number (CNB):** 745.7

Address: Berkeley Co. Stephen Williams

Print: X

Negative:

Description: living room view to back door

**File number (CNB):** 746

Address: Cassina Point

Print: X

Negative:

Description: front view, georgian style - gabled dormer

**File number (CNB):** 746.1

Address: Cassina Point

Print: X

Negative:

Description: side view

**File number (CNB):** 746.2

Address: Cassina Point

Print: X

Negative:

Description: rear

**File number (CNB):** 746.3

Address: Cassina Point

Print: X

Negative:

Description: side view

**File number (CNB):** 746.4

Address: Cassina Point

Print: X

Negative:

Description: front doors

**File number (CNB):** 746.5

Address: Cassina Point

Print: X

Negative:

Description: living room front front hall

**File number (CNB):** 746.6

Address: Cassina Point

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 746.7

Address: Cassina Point

Print: X

Negative:

Description: stairway and front hall

**File number (CNB):** 746.8

Address: Cassina Point

Print: X

Negative:

Description: 2nd flr landing

**File number (CNB):** 747

Address: Edisto Island Presby Church

Print: X

Negative:

Description: front view, including cupola

**File number (CNB):** 747.1

Address: Edisto Island Presby Church

Print: X

Negative:

Description: detail of window and entrance

**File number (CNB):** 747.2

Address: Edisto Island Presby Church

Print: X

Negative:

Description: entablature and cornice detail

**File number (CNB):** 747.3

Address: Edisto Island Presby Church

Print: X

Negative:

Description: cupola

**File number (CNB):** 747.4

Address: Edisto Island Presby Church

Print: X

Negative:

Description: rear from cemetery

**File number (CNB):** 747.5

Address: Edisto Island Presby Church

Print: X

Negative:

Description: side from front left

**File number (CNB):** 747.6

Address: Edisto Island Presby Church

Print: X

Negative:

Description: side from cemetery

**File number (CNB):** 747.7

Address: Edisto Island Presby Church

Print: X

Negative:

Description: 2nd building

**File number (CNB): 748**

Address: Oak Island

Print: X

Negative:

Description: rear

**File number (CNB): 748.1**

Address: Oak Island

Print: X

Negative:

Description: side view

**File number (CNB): 748.2**

Address: Oak Island

Print: X

Negative:

Description: side view

**File number (CNB): 748.3**

Address: Oak Island

Print: X

Negative:

Description: front

**File number (CNB): 748.4**

Address: Oak Island

Print: X

Negative:

Description: front porch

**File number (CNB): 748.5**

Address: Oak Island

Print: X

Negative:

Description: front door detail

**File number (CNB): 748.6**

Address: Oak Island

Print: X

Negative:

Description: 2nd flr window and shutters

**File number (CNB): 748.7**

Address: Oak Island

Print: X

Negative:

Description: 1st flr front hall

**File number (CNB): 748.8**

Address: Oak Island

Print: X

Negative:

Description: parlor wall and mantel

**File number (CNB):** 748.9

Address: Oak Island

Print: X

Negative:

Description: view from parlor into front hall and dining room

**File number (CNB):** 748.10

Address: Oak Island

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 748.11

Address: Oak Island

Print: X

Negative:

Description: cornice and window frame detail

**File number (CNB):** 748.12

Address: Oak Island

Print: X

Negative:

Description: door way post and lintel detail

**File number (CNB):** 748.13

Address: Oak Island

Print: X

Negative:

Description: breakfast room wall and mantel

**File number (CNB):** 748.14

Address: Oak Island

Print: X

Negative: X

Description: cornice detail

**File number (CNB):** 748.15

Address: Oak Island

Print: X

Negative: X

Description: 1st fl- north stair hall, looking north to added stair hall beyond

**File number (CNB):** 748.16

Address: Oak Island

Print: X

Negative: X

Description: Stair landing, looking south to 2nd floor hall and twin doors to 1st floor south entry hall

**File number (CNB):** 748.17

Address: Oak Island

Print: X

Negative: X

Description: 2nd flr- north stair hall, looking north to added stir hall beyond

**File number (CNB):** 744.18

Address: Oak Island

Print:

Negative: X

Description: 1st flr- southeast room cornice

**File number (CNB):** 749

Address: Prospect Hill

Print: X

Negative: X

Description: South side; Ephraim Baynard c.1790; two miles west state hwy 174 on county road 1308 extended

**File number (CNB):** 749.1

Address: Prospect Hill

Print: X

Negative: X

Description: East side

**File number (CNB):** 749.2

Address: Prospect Hill

Print: X

Negative: X

Description: North side

**File number (CNB):** 749.3

Address: Prospect Hill

Print: X

Negative: X

Description: Northwest side

**File number (CNB):** 749.4

Address: Prospect Hill

Print: X

Negative: X

Description: Ground floor, south side entry and window

**File number (CNB):** 749.5

Address: Prospect Hill

Print: X

Negative: X

Description: South side, 1st floor entry

**File number (CNB):** 749.6

Address: Prospect Hill

Print: X

Negative: X

Description: Southside- 1st floor window detail; key block has been removed from east, north, and west side windows

**File number (CNB):** 749.7 (1)

Address: Prospect Hill

Print: X

Negative: X

Description: Southeast corner portico and house; cornice detail; solid wood columns

**File number (CNB):** 749.7 (2)

Address: Prospect Hill

Print:

Negative: X

Description: Southeast corner portico and house; cornice detail; solid wood columns

**File number (CNB):** 749.8

Address: Prospect Hill

Print: X

Negative: X

Description: South side- 2nd flr central window

**File number (CNB):** 750

Address: William Seabrook (Dodge) Plantation

Print: X

Negative: X

Description: Entry gates looking south from west side of house

**File number (CNB):** 750.1

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: c.1810; South side; 1 mile east state hwy 174 on county road 768, beyond Oak Island

**File number (CNB):** 750.2

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: Southeast side

**File number (CNB):** 750.3

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: East side- elevator shaft projection, brick refrigerator house and ground floor; entry shed after 1930; west side similar without additions and windows in lieu of elevator shaft

**File number (CNB):** 750.4

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: North side; 1st flr enclosed porches c.1929

**File number (CNB):** 750.5

Address: William Seabrook (Dodge) Plantation

Print:



Negative: X

Description: Northwest corner; northeast corner same

**File number (CNB):** 750.6

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: Southwest side

**File number (CNB):** 750.7

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side portico, pediment

**File number (CNB):** 750.8

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side, dormer and portico details

**File number (CNB):** 750.9

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side portico, 1st flr cornice

**File number (CNB):** 750.10

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side- 1st flr portico, iron railing cipher of builder (W.S.) c.1810

**File number (CNB):** 750.11 (1)

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side entry

**File number (CNB):** 750.11 (2)

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side entry

**File number (CNB):** 750.12

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: South side- 2nd flr portico entry

**File number (CNB):** 750.13

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: East side- 2nd flr cornice; note handling of ovolo crown mould of ranking cornice at flare of roof line

**File number (CNB):** 750.14

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: East side- window in gable; west side same

**File number (CNB):** 750.15

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall, looking north to stair hall

**File number (CNB):** 750.16

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall, looking south to entry

**File number (CNB):** 750.17

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr stair hall, looking northwest

**File number (CNB):** 750.18 (1)

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall, door to southwest room; door to southeast room same

**File number (CNB):** 750.18 (2)

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall, door to southwest room; door to southeast room same

**File number (CNB):** 750.18 (3)

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall, door to southwest room; door to southeast room same

**File number (CNB):** 750.19

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr hall- cornice detail

**File number (CNB): 750.20**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr- southeast room, north wall; corner cabinet new, elevator door at right, formerly window; southwest room similar

**File number (CNB): 750.21**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr- southeast room mantel detail; southwest room same

**File number (CNB): 750.22**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr- southeast room cornice detail; southwest room same

**File number (CNB): 750.23 (1)**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 1st flr- southeast and southwest rooms; typical window spandrel and wainscot

**File number (CNB): 750.23 (2)**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- southeast and southwest rooms; typical window spandrel and wainscot

**File number (CNB): 750.23 (3)**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 3rd flr- southeast and southwest rooms; typical window spandrel and wainscot

**File number (CNB): 750.24**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- stair hall and hall, looking south from landing

**File number (CNB): 750.25**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- stair hall, looking north

**File number (CNB): 750.26**

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- southeast room, north wall; door at left shows typical hallside of all 2nd floor doors; southwest room similar

**File number (CNB):** 750.27

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- southeast room, mantel; typical for 2nd floor rooms and northwest room 1st floor

**File number (CNB):** 750.28

Address: William Seabrook (Dodge) Plantation

Print:

Negative:

Description: 2nd flr- southwest and southeast rooms; cornice detail

**File number (CNB):** 750.29

Address: William Seabrook (Dodge) Plantation

Print:

Negative: X

Description: 2nd flr- typical window spandrel, wainscot cap, and marbelized base

**File number (CNB):** 751

Address: Seaside

Print:

Negative: X

Description: William Edings pre-1776; southeast side; portico roof supports post-1949; north of Edisto beach town, off state hwy 174

**File number (CNB):** 751.1

Address: Seaside

Print: X

Negative: X

Description: Southwest side; portico roof supports post-1949

**File number (CNB):** 751.2

Address: Seaside

Print: X

Negative: X

Description: North side; frame addition on west end with exposed rafters c.1900; other frame portion is enclosed porch, date unknown

**File number (CNB):** 751.3 (1)

Address: Seaside

Print: X

Negative: X

Description: East side

**File number (CNB):** 751.3 (2)

Address: Seaside

Print:

Negative: X

Description: East side

**File number (CNB):** 751.4

Address: Seaside

Print: X

Negative: X

Description: South side- entry; stoop, railing, and column post-1949

**File number (CNB):** 751.5

Address: Seaside

Print: X

Negative: X

Description: North side- stoop and entry date unknown, portico floor removed after 1949

**File number (CNB):** 751.6

Address: Seaside

Print: X

Negative: X

Description: 1st flr- hall, looking north to enclosed north side porch

**File number (CNB):** 751.7

Address: Seaside

Print: X

Negative: X

Description: 1st flr- hall, above wainscot next to door to southwest room; paint layers on plaster, note wood graining in corner of wainscot and door case and other areas upon close examination- this graining is the 1st coat of paint on the plaster

**File number (CNB):** 751.8

Address: Seaside

Print: X

Negative: X

Description: 1st flr- southwest room, west wall; bookcases and door installed in original window locations

**File number (CNB):** 751.9 (1)

Address: Seaside

Print: X

Negative: X

Description: 1st flr- southwest room, west wall, mantel

**File number (CNB):** 751.9 (2)

Address: Seaside

Print:

Negative: X

Description: 2nd flr- southwest room, west wall, mantel

**File number (CNB):** 751.1

Address: Seaside

Print: X

Negative: X

Description: 1st flr- southwest room, cornice at chimney piece

**File number (CNB): 751.11**

Address: Seaside

Print: X

Negative: X

Description: 1st flr- southeast room, east wall

**File number (CNB): 751.12**

Address: Seaside

Print: X

Negative: X

Description: 2nd flr- southwest room, chimney piece; southeast room same

**File number (CNB): 752**

Address: Summit

Print: X

Negative: X

Description: c.1816, Mrs. Susanna Wilkinson; original clapboards run full/side of house on all sides; on Swington Creek of Toogoodoo River, 6 miles south of Adam's Run

**File number (CNB): 752.1**

Address: Summit

Print: X

Negative: X

Description: East side

**File number (CNB): 751.2**

Address: Summit

Print: X

Negative:

Description:

**File number (CNB): 752.3**

Address: Summit

Print: X

Negative: X

Description: Southeast cornice and framing detail; note "V" gutter hanger

**File number (CNB): 752.4**

Address: Summit

Print: X

Negative: X

Description: West side

**File number (CNB): 752.5**

Address: Summit

Print: X

Negative: X

Description: West side- Fdn detail showing at left stuccoed and scored tabby pier, and at right bare tabby pier

**File number (CNB): 752.6**

Address: Summit

Print: X

Negative: X

Description: 1st flr- hall, looking north; stair landing in center of hall to accommodate single room depth on 2nd floor

**File number (CNB):** 752.7 (1)

Address: Summit

Print: X

Negative: X

Description: 1st flr- southeast room, north wall

**File number (CNB):** 752.7 (2)

Address: Summit

Print:

Negative: X

Description: 2nd flr- southeast room, north wall

**File number (CNB):** 752.8

Address: Summit

Print: X

Negative: X

Description: 1st flr- southwest room, north wall

**File number (CNB):** 752.9

Address: Summit

Print: X

Negative: X

Description: 1st flr- southwest room, mantel detail

**File number (CNB):** 753

Address: Sunnyside

Print: X

Negative: X

Description: South side; Townsend Mikell c.1875; 1 mile west State Hwy 174 on county road 767

**File number (CNB):** 753.1

Address: Sunnyside

Print: X

Negative: X

Description: West side

**File number (CNB):** 753.2

Address: Sunnyside

Print: X

Negative: X

Description: Northwest side

**File number (CNB):** 753.3

Address: Sunnyside

Print: X

Negative: X

Description: East side

**File number (CNB):** 753.4

Address: Sunnyside

Print: X

Negative: X

Description: Southeast corner roof and dormer detail

**File number (CNB):** 753.5

Address: Sunnyside

Print: X

Negative: X

Description: Cupola from southeast

**File number (CNB):** 753.6

Address: Sunnyside

Print: X

Negative: X

Description: 1st flr- entry from portico; note patterned glass

**File number (CNB):** 753.7

Address: Sunnyside

Print: X

Negative: X

Description: 1st flr- entry hall floor, local labor parquetry

**File number (CNB):** 753.8

Address: Sunnyside

Print: X

Negative:

Description: ceiling detail and mantel

**File number (CNB):** 753.9

Address: Sunnyside

Print: X

Negative:

Description: dining room from hallway

**File number (CNB):** 753.10

Address: Sunnyside

Print: X

Negative:

Description: privy

**File number (CNB):** 753.11

Address: Sunnyside

Print: X

Negative:

Description: 2nd view of privy

**File number (CNB):** 753.12

Address: Sunnyside

Print: X

Negative: X



Description: Barn, from northwest

**File number (CNB):** 753.13

Address: Sunnyside

Print: X

Negative: X

Description: Cotton gin, tabby foundation ruins

**File number (CNB):** 755

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: c.1804, Capt. Peter Gaillard; south side; house originally rested on brick piers. They have been removed and brick foundation walls installed c.1960; exposed brick chimneys c.1940, when original chimneys collapsed during 1 1/2 mile move (on north side of

**File number (CNB):** 755.1

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: East side

**File number (CNB):** 755.2

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: North side

**File number (CNB):** 755.3

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: West side

**File number (CNB):** 755.4

Address: Orangeburg Co. The Rocks

Print: X

Negative:

Description:

**File number (CNB):** 755.5

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: North side, windows over stair landing

**File number (CNB):** 755.6

Address: Orangeburg Co. The Rocks

Print:

Negative:

Description:

**File number (CNB):** 755.6

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: South side, 1st floor, entry to southeast and southwest rooms; no hall on south side of house

**File number (CNB):** 755.7 (1)

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 1st flr- southeast room, north wall; door at left enters into stair hall; southwest room identical except opposite hand

**File number (CNB):** 755.7 (2)

Address: Orangeburg Co. The Rocks

Print:

Negative: X

Description: 1st flr- southeast room, north wall; door at left enters into stair hall; southwest room identical except opposite hand

**File number (CNB):** 755.8

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 1st flr- southeast room, chimney piece

**File number (CNB):** 755.9

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 1st flr- southeast room, detail of cornice and overmantel

**File number (CNB):** 755.10

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 1st flr- southeast room, wainscot detail showing return of window architrave

**File number (CNB):** 755.11

Address: Orangeburg Co. The Rocks

Print:

Negative:

Description:

**File number (CNB):** 755.11

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 1st flr- stair hall, west and north walls; note head room cut out in 2nd floor landing

**File number (CNB):** 755.12

Address: Orangeburg Co. The Rocks

Print:

Negative:

Description:

**File number (CNB):** 755.12

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: North end of hall- stair landing showing door and side panels which open into space under north side center porch area roof

**File number (CNB):** 755.13

Address: Orangeburg Co. The Rocks

Print:

Negative:

Description:

**File number (CNB):** 755.13

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 2nd flr- stair landing

**File number (CNB):** 755.14

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: 2nd flr- northwest room, south wall; typical 2nd floor room

**File number (CNB):** 755.15

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: House servant's quarters, northeast side

**File number (CNB):** 755.16

Address: Orangeburg Co. The Rocks

Print: X

Negative: X

Description: Smokehouse, southeast side

**File number (CNB):** 756

Address: 328 Meeting

Print: X

Negative: X

Description: Citadel Square Baptist Church c.1856; west side

**File number (CNB):** 756.1

Address: 328 Meeting

Print: X

Negative: X

Description: Citadel Square Baptist Church c.1856; north side

**File number (CNB): 756.2**

Address: 328 Meeting

Print: X

Negative: X

Description: Citadel Square Baptist Church c.1856; south side

**File number (CNB): 756.3 (1)**

Address: 328 Meeting

Print: X

Negative: X

Description: Citadel Square Baptist Church c.1856; west side doors

**File number (CNB): 756.3 (2)**

Address: 328 Meeting

Print:

Negative: X

Description: Citadel Square Baptist Church c.1856; west side doors

**File number (CNB): 756.4**

Address: 328 Meeting

Print: X

Negative: X

Description: Citadel Square Baptist Church c.1856; west side clerestorey windows

**File number (CNB): 756.5**

Address: 328 Meeting

Print:

Negative: X

Description: West side fencing

**File number (CNB): 757**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, west side

**File number (CNB): 757.1**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, southwest side

**File number (CNB): 757.2**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, south side

**File number (CNB): 757.3**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, east side

**File number (CNB):** 757.4

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, northeast side

**File number (CNB):** 757.5

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, west side- entry, pilaster, and cornice detail; typical also of north and south entries

**File number (CNB):** 757.6

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, south side, architect contractor cipher on southwest corner

**File number (CNB):** 757.7

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, south side, architect contractor cipher on right hand door jamb

**File number (CNB):** 757.8 (1)

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, east side, venetian window detail

**File number (CNB):** 757.8 (2)

Address: Berkeley Co. St. Stephens Church

Print:

Negative: X

Description: (Episcopal), c.1767, east side, venetian window detail

**File number (CNB):** 757.9

Address: Berkeley Co. St. Stephens Church

Print: X

Negative:

Description:

**File number (CNB):** 757.9 (1)

Address: Berkeley Co. St. Stephens Church

Print:

Negative: X

Description: (Episcopal), c.1767, east side, brick mason's cipher, Wambaw Lodge of Freemasons, a blue lodge

**File number (CNB):** 757.9 (2)

Address: Berkeley Co. St. Stephens Church

Print:

Negative: X

Description: (Episcopal), c.1767, east side, brick mason's cipher, Wambaw Lodge of Freemasons, a blue lodge

**File number (CNB): 757.10**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, Nave, looking east

**File number (CNB): 757.11**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, Nave looking west

**File number (CNB): 757.12**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, alter and reredos

**File number (CNB): 757.13 (1)**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, Reredos detail at venetian window

**File number (CNB): 757.13 (2)**

Address: Berkeley Co. St. Stephens Church

Print:

Negative: X

Description: (Episcopal), c.1767, Reredos detail at venetian window

**File number (CNB): 757.14**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, Reredos detail at entablature and pilaster cap

**File number (CNB): 757.15**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, pulpit

**File number (CNB): 757.16**

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, pulpit tester soffitt

**File number (CNB):** 757.17 (1)

Address: Berkeley Co. St. Stephens Church

Print: X

Negative: X

Description: (Episcopal), c.1767, cornice between cove and flat ceilings

**File number (CNB):** 757.17 (2)

Address: Berkeley Co. St. Stephens Church

Print:

Negative: X

Description: (Episcopal), c.1767, cornice between cove and flat ceilings

**File number (CNB):** 758

Address: 36 Hasell

Print: X

Negative: X

Description: South side entry; unfortunate restoration of pilaster shafts with square flutes in lieu of half round

**File number (CNB):** 759

Address: 52 Hasell

Print: X

Negative:

Description: entry

**File number (CNB):** 760

Address: 54 Hasell

Print: X

Negative:

Description: s side E (right) stairs & entry c 1940. W entry c 1940 to replace victorian enframement

**File number (CNB):** 760 (1)

Address: 54 Hasell

Print:

Negative: X

Description: street view

**File number (CNB):** 760 (2)

Address: 54 Hasell

Print:

Negative: X

Description: street view

**File number (CNB):** 760 (3)

Address: 54 Hasell

Print:

Negative: X

Description: street view

**File number (CNB):** 760.1

Address: 54 Hasell

Print: X  
Negative: X  
Description: Westside  
**File number (CNB):** 760.2  
Address: 54 Hasell  
Print:  
Negative: X  
Description: East pass gate  
**File number (CNB):** 760.3 (1)  
Address: 54 Hasell  
Print:  
Negative: X  
Description: Stair railing, c. 1941  
**File number (CNB):** 760.3 (2)  
Address: 54 Hasell  
Print:  
Negative: X  
Description: Stair railing, c. 1941  
**File number (CNB):** 762  
Address: 54 Hasell  
Print: X  
Negative:  
Description: s side formerly dpenedency of 54 Hasell  
**File number (CNB):** 763  
Address: 58 Hasell  
Print: X  
Negative:  
Description: SW side formerlu dependency of 54 Hasell  
**File number (CNB):** 764  
Address: 60 Hasell  
Print: X  
Negative:  
Description: s side  
**File number (CNB):** 764.1  
Address: 60 Hasell  
Print: X  
Negative:  
Description: NE side  
**File number (CNB):** 764.2  
Address: 60 Hasell  
Print: X  
Negative:  
Description: s side, fencing and pass gate detail  
**File number (CNB):** 764.3



Address: 60 Hasell

Print: X

Negative:

Description: s side, ground floor entry

**File number (CNB):** 764.4

Address: 60 Hasell

Print: X

Negative:

Description: s side detail of column cap and entablature

**File number (CNB):** 764.5

Address: 60 Hasell

Print: X

Negative:

Description: s side ornament on columns and entry door

**File number (CNB):** 764.6

Address: 60 Hasell

Print: X

Negative:

Description: gr flr hall looking N

**File number (CNB):** 764.7

Address: 60 Hasell

Print: X

Negative:

Description: gr flr SE room looking NE (SW room similar except opposite

**File number (CNB):** 764.8

Address: 60 Hasell

Print: X

Negative:

Description: gr flr SE room mantel; SW room same

**File number (CNB):** 764.9

Address: 60 Hasell

Print: X

Negative:

Description: gr flr SE room cornice (SW same)

**File number (CNB):** 764.10

Address: 60 Hasell

Print: X

Negative: X

Description: Dependency, southwest corner

**File number (CNB):** 764.11

Address: 60 Hasell

Print:

Negative: X

Description: Carriage gate

**File number (CNB): 765**

Address: 62 Hasell

Print:

Negative: X

Description: s side

**File number (CNB): 765.1**

Address: 62 Hasell

Print:

Negative: X

Description: NE side

**File number (CNB): 766**

Address: 64 Hasell

Print:

Negative: X

Description: s side

**File number (CNB): 766.1**

Address: 64 Hasell

Print:

Negative: X

Description: SW side

**File number (CNB): 766.2**

Address: 64 Hasell

Print:

Negative: X

Description: n side house, w side dependency

**File number (CNB): 766.3**

Address: 64 Hasell

Print:

Negative: X

Description: n side dependency; frame addition on left new, also garage doors

**File number (CNB): 766.4**

Address: 64 Hasell

Print:

Negative: X

Description: s side iron fence; pass gate detail assumed original to house

**File number (CNB): 766.5**

Address: 64 Hasell

Print:

Negative: X

Description: s side entry

**File number (CNB): 766.6**

Address: 64 Hasell

Print:

Negative: X

Description: s side entry; stair railing

**File number (CNB):** 766.7

Address: 64 Hasell

Print:

Negative: X

Description: 1st flr endtry, portico to hall

**File number (CNB):** 766.8

Address: 64 Hasell

Print:

Negative: X

Description: 2nd flr portico to hall door ornament; 1st flr same

**File number (CNB):** 766.9

Address: 64 Hasell

Print:

Negative: X

Description: house & dependency n side

**File number (CNB):** 766.10

Address: 64 Hasell

Print: X

Negative: X

Description: House and dependency, northside

**File number (CNB):** 766.11

Address: 64 Hasell

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 767

Address: 78 East Bay

Print: X

Negative:

Description: w side

**File number (CNB):** 767.1

Address: 78 East Bay

Print: X

Negative:

Description: s side

**File number (CNB):** 767.2

Address: 78 East Bay

Print: X

Negative:

Description: e side ground & 1st flr porticos not original

**File number (CNB):** 767.3

Address: 78 East Bay

Print: X

Negative:

Description: n side door canopy, 20th c

**File number (CNB):** 768

Address: 95-103 East Bay

Print: X

Negative:

Description: e side garage doors & iron work not original

**File number (CNB):** 768.1

Address: 95-103 East Bay

Print: X

Negative:

Description: pilaster cornice, eg and dart moulding originally ran across thru pilaster on #103

**File number (CNB):** 769

Address: 801 Bay

Print: X

Negative:

Description: Front Entrance from street, Georgian/Classicismized Colonial style

**File number (CNB):** 769.1

Address: 801 Bay

Print: X

Negative:

Description: front and right side view

**File number (CNB):** 769.2

Address: 801 Bay

Print: X

Negative:

Description: rear view from street

**File number (CNB):** 769.3

Address: 801 Bay

Print: X

Negative:

Description: left side and rear view from street

**File number (CNB):** 769.4

Address: 801 Bay

Print: x

Negative:

Description: close up of second story (front) balcony, pediment

**File number (CNB):** 769.5

Address: 801 Bay

Print: x

Negative:

Description: raised entrance, close up of front door and porch

**File number (CNB):** 769.6

Address: 801 Bay

Print: X

Negative:

Description: door frame, decorated cornice

**File number (CNB):** 769.7

Address: 801 Bay

Print: X

Negative:

Description: detail of main archway behind stairwell

**File number (CNB):** 769.8

Address: 801 Bay

Print: X

Negative:

Description: full frontal view of central stairwell, 1st floor

**File number (CNB):** 769.9

Address: 801 Bay

Print: X

Negative:

Description: detail of the balustrade (woodwork)

**File number (CNB):** 769.10

Address: 801 Bay

Print: X

Negative:

Description: 1st flr living room, mantel and 2 doorframes

**File number (CNB):** 769.11

Address: 801 Bay

Print: X

Negative:

Description: detail of cornice and upper mantel

**File number (CNB):** 769.12

Address: 801 Bay

Print: X

Negative:

Description: detail of fireplace and mantel

**File number (CNB):** 769.13

Address: 801 Bay

Print: X

Negative:

Description: 2nd room fireplace/mantel

**File number (CNB):** 769.14

Address: 801 Bay

Print: X

Negative:

Description: detail of 2nd room cornice

**File number (CNB):** 769.15

Address: 801 Bay

Print: X

Negative:

Description: detail of 2nd room mantel

**File number (CNB):** 769.16

Address: 801 Bay

Print: X

Negative:

Description: 3rd mantel / wall

**File number (CNB):** 769.17

Address: 801 Bay

Print: X

Negative:

Description: 3rd mantel detail

**File number (CNB):** 769.18

Address: 801 Bay

Print: X

Negative:

Description: 4th mantel and wall

**File number (CNB):** 769.19

Address: 801 Bay

Print: X

Negative:

Description: 4th mantel detail

**File number (CNB):** 769.20

Address: 801 Bay

Print: X

Negative:

Description: view from the stairs of the second floor landing

**File number (CNB):** 769.21

Address: 801 Bay

Print: X

Negative:

Description: view from the landing of the stairs and window

**File number (CNB):** 769.22

Address: 801 Bay

Print: X

Negative:

Description: cornice detail (2nd floor room)

**File number (CNB):** 769.23

Address: 801 Bay

Print: X

Negative:

Description: 2nd flr room looking towards rear

**File number (CNB): 769.24**

Address: 801 Bay

Print: X

Negative:

Description: 2nd flr room looking towards front

**File number (CNB): 769.25**

Address: 801 Bay

Print: X

Negative:

Description: mantel and wall detail

**File number (CNB): 769.26**

Address: 801 Bay

Print: X

Negative:

Description: cornice detail (2nd floor room)

**File number (CNB): 769.27**

Address: 801 Bay

Print: X

Negative:

Description: mantel detail - relief within frieze

**File number (CNB): 768.28**

Address: 801 Bay

Print: X

Negative:

Description: door frame, decorated cornice

**File number (CNB): 769.29**

Address: 801 Bay

Print: X

Negative:

Description: full view of wall and mantel 2nd floor (marbel framing)

**File number (CNB): 769.30**

Address: 801 Bay

Print: X

Negative:

Description: view into first room from 2nd on 2nd flr

**File number (CNB): 769.31**

Address: 801 Bay

Print: X

Negative:

Description: cornice detail (2nd floor room)

**File number (CNB): 769.32**

Address: 801 Bay

Print: X

Negative:

Description: bedroom view, wall and mantel

**File number (CNB): 769.33**

Address: 801 Bay

Print: X

Negative:

Description: detail of mantel, marble framing relief within frieze

**File number (CNB): 769.34**

Address: 801 Bay

Print: X

Negative:

Description: mantel in repair detail

**File number (CNB): 769.35**

Address: 801 Bay

Print: X

Negative:

Description: photo of original structure with confederate gaurds out front

**File number (CNB): 770**

Address: 802-806 Bay

Print: X

Negative:

Description: Belk - Simpson CO - store front and left side street view

**File number (CNB): 770.1**

Address: 802-806 Bay

Print: X

Negative:

Description: window and shutter detail

**File number (CNB): 770.2**

Address: 802-806 Bay

Print: X

Negative:

Description: view of the stairs

**File number (CNB): 770.3**

Address: 802-806 Bay

Print: X

Negative:

Description: 2nd view of stairs

**File number (CNB): 770.4**

Address: 802-806 Bay

Print: X

Negative:

Description: 3rd view of stairs looking up to ceiling

**File number (CNB): 770.5**

Address: 802-806 Bay

Print: X



Negative:

Description: detail of ceiling

**File number (CNB):** 771

Address: 1201 Bay

Print: X

Negative:

Description: front view of house, central steps leading to front porch

**File number (CNB):** 771.1

Address: 1201 Bay

Print: X

Negative:

Description: left side front view from yard

**File number (CNB):** 771.2

Address: 1201 Bay

Print: X

Negative:

Description: detail of front door

**File number (CNB):** 771.2

Address: 1201 Bay

Print: X

Negative:

Description: right side view

**File number (CNB):** 771.3

Address: 1201 Bay

Print: X

Negative:

Description: leftside full view

**File number (CNB):** 771.4

Address: 1201 Bay

Print: X

Negative:

Description: foyer entrance, archway

**File number (CNB):** 771.5

Address: 1201 Bay

Print: X

Negative:

Description: detail of stairs from 1st floor

**File number (CNB):** 771.6

Address: 1201 Bay

Print: X

Negative:

Description: living room view, wall and mantel

**File number (CNB):** 771.7

Address: 1201 Bay

Print: X  
Negative:  
Description: detail of mantel, marble framing relief within frieze  
**File number (CNB):** 771.8  
Address: 1201 Bay  
Print: X  
Negative:  
Description: bedroom view, wall and mantel  
**File number (CNB):** 771.9  
Address: 1201 Bay  
Print: X  
Negative:  
Description: second flr landing and archway  
**File number (CNB):** 772.10  
Address: 1201 Bay  
Print: X  
Negative:  
Description: mantel detail  
**File number (CNB):** 771.11  
Address: 1201 Bay  
Print: X  
Negative:  
Description: second detail of mantel  
**File number (CNB):** 771.12  
Address: 1201 Bay  
Print: X  
Negative:  
Description: ceiling detail  
**File number (CNB):** 772  
Address: 1207 Bay  
Print: X  
Negative:  
Description: front view, double porch colonade  
**File number (CNB):** 772.1  
Address: 1207 Bay  
Print: X  
Negative:  
Description: side view  
**File number (CNB):** 772.2  
Address: 1207 Bay  
Print: X  
Negative:  
Description: rear view  
**File number (CNB):** 772.3

Address: 1207 Bay

Print: X

Negative:

Description: detail of front door

**File number (CNB): 772.4**

Address: 1207 Bay

Print: X

Negative:

Description: exterior detail, pediment above window

**File number (CNB): 772.5**

Address: 1207 Bay

Print: X

Negative:

Description: front hall and stairs

**File number (CNB): 772.6**

Address: 1207 Bay

Print: X

Negative:

Description: dinner room, wall and mantel

**File number (CNB): 772.7**

Address: 1207 Bay

Print: X

Negative:

Description: window detail and sideboard

**File number (CNB): 772.8**

Address: 1207 Bay

Print: X

Negative:

Description: mantel and wall detail

**File number (CNB): 772.9**

Address: 1207 Bay

Print: X

Negative:

Description: mantel detail

**File number (CNB): 772.10**

Address: 1207 Bay

Print: X

Negative:

Description: cornice detail

**File number (CNB): 772.11**

Address: 1207 Bay

Print: X

Negative:

Description: office/parlor space, view of wall and mantel

**File number (CNB): 772.12**

Address: 1207 Bay

Print: X

Negative:

Description: view of 1st and 2nd flr from middle of stairs

**File number (CNB): 772.13**

Address: 1207 Bay

Print: X

Negative:

Description: 2nd flr cornice detail

**File number (CNB): 772.14**

Address: 1207 Bay

Print: X

Negative:

Description: Dado/baseboard detail

**File number (CNB): 772.15**

Address: 1207 Bay

Print: X

Negative:

Description: another parlor room, wall detail

**File number (CNB): 772.16**

Address: 1207 Bay

Print: X

Negative:

Description: wall and mantel

**File number (CNB): 772.17**

Address: 1207 Bay

Print: X

Negative:

Description: wall and mantel

**File number (CNB): 772.18**

Address: 1207 Bay

Print: X

Negative:

Description: cornice detail

**File number (CNB): 773**

Address: 1211 Bay

Print: X

Negative:

Description: front view

**File number (CNB): 773.1**

Address: 1211 Bay

Print: X

Negative:

Description: side view

**File number (CNB):** 773.2

Address: 1211 Bay

Print: X

Negative:

Description: rear

**File number (CNB):** 773.3

Address: 1211 Bay

Print: X

Negative:

Description: side view

**File number (CNB):** 773.4

Address: 1211 Bay

Print: X

Negative:

Description: front door detail

**File number (CNB):** 773.5

Address: 1211 Bay

Print: X

Negative:

Description: window detail

**File number (CNB):** 773.6

Address: 1211 Bay

Print: X

Negative:

Description: window detail

**File number (CNB):** 773.7

Address: 1211 Bay

Print: X

Negative:

Description: upper porch detail

**File number (CNB):** 773.8

Address: 1211 Bay

Print: X

Negative:

Description: interior view of the front door

**File number (CNB):** 773.9

Address: 1211 Bay

Print: X

Negative:

Description: entry way and stairs

**File number (CNB):** 773.10

Address: 1211 Bay

Print: X

Negative:

Description: side view of stairs

**File number (CNB):** 773.11

Address: 1211 Bay

Print: X

Negative:

Description: living room view, wall and mantel

**File number (CNB):** 773.12

Address: 1211 Bay

Print: X

Negative:

Description: close up of mantel, relief work

**File number (CNB):** 773.13

Address: 1211 Bay

Print: X

Negative:

Description: wall and mantel

**File number (CNB):** 773.14

Address: 1211 Bay

Print: X

Negative:

Description: close up mantel

**File number (CNB):** 773.15

Address: 1211 Bay

Print: X

Negative:

Description: view of room, facing stairs

**File number (CNB):** 773.16

Address: 1211 Bay

Print: X

Negative:

Description: dinner room, wall and mantel

**File number (CNB):** 773.17

Address: 1211 Bay

Print: X

Negative:

Description: cornice detail on mantel

**File number (CNB):** 773.18

Address: 1211 Bay

Print: X

Negative:

Description: side mantel

**File number (CNB):** 773.19

Address: 1211 Bay

Print: X

Negative:

Description:

**File number (CNB):** 773.20

Address: 1211 Bay

Print: X

Negative:

Description: central mantelsecond floor landing,

**File number (CNB):** 773.21

Address: 1211 Bay

Print: X

Negative:

Description: bed room wall and mantel

**File number (CNB):** 773.22

Address: 1211 Bay

Print: X

Negative:

Description: opposite view of room

**File number (CNB):** 773.23

Address: 1211 Bay

Print: X

Negative:

Description: detail of mantel

**File number (CNB):** 773.24

Address: 1211 Bay

Print: X

Negative:

Description: mantel detail

**File number (CNB):** 773.25

Address: 1211 Bay

Print: X

Negative:

Description: cornice detail

**File number (CNB):** 773.26

Address: 1211 Bay

Print: X

Negative:

Description: upper mantel/wall detail

**File number (CNB):** 773.27

Address: 1211 Bay

Print: X

Negative:

Description: bedroom view

**File number (CNB):** 773.28

Address: 1211 Bay  
Print: X  
Negative:  
Description: mantel detail  
**File number (CNB): 774**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: front view  
**File number (CNB): 774.1**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: side  
**File number (CNB): 774.2**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: side  
**File number (CNB): 774.3**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: side  
**File number (CNB): 774.4**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: 2nd flr balcony detail  
**File number (CNB): 774.5**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: front door detail  
**File number (CNB): 774.6**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: porch detail  
**File number (CNB): 774.7**  
Address: 411 Bayard  
Print: X  
Negative:  
Description: stairwell and 1st flr hall way



**File number (CNB): 774.8**

Address: 411 Bayard

Print: X

Negative:

Description: living room wall and mantel

**File number (CNB): 774.9**

Address: 411 Bayard

Print: X

Negative:

Description: living room looking towards stairs

**File number (CNB): 774.10**

Address: 411 Bayard

Print: X

Negative:

Description: cornice/ceiling detail

**File number (CNB): 774.11**

Address: 411 Bayard

Print: X

Negative:

Description: mantel detail

**File number (CNB): 774.12**

Address: 411 Bayard

Print: X

Negative:

Description: kitchen seating, woodwork

**File number (CNB): 775**

Address: 600 Charles

Print: X

Negative:

Description: street view, Baptist Church

**File number (CNB): 775.1**

Address: 600 Charles

Print: X

Negative:

Description: detail of main entrance

**File number (CNB): 775.2**

Address: 600 Charles

Print: X

Negative:

Description: left side view

**File number (CNB): 775.3**

Address: 600 Charles

Print: X

Negative:

Description: detail of pilaster and entablature

**File number (CNB):** 775.4

Address: 600 Charles

Print: X

Negative:

Description: interiors facing alter

**File number (CNB):** 775.6

Address: 600 Charles

Print: X

Negative:

Description: interior facing entrance

**File number (CNB):** 775.7

Address: 600 Charles

Print: X

Negative:

Description: alter detail

**File number (CNB):** 775.8

Address: 600 Charles

Print: X

Negative:

Description: balcony entablature detail

**File number (CNB):** 775.9

Address: 600 Charles

Print: X

Negative:

Description: ceiling decoration detail

**File number (CNB):** 775.10

Address: 600 Charles

Print: X

Negative:

Description: cornice and ceiling detail

**File number (CNB):** 775.11

Address: 600 Charles

Print: X

Negative:

Description: ceiling decoration detail

**File number (CNB):** 775.12

Address: 600 Charles

Print: X

Negative:

Description: ceiling decoration detail

**File number (CNB):** 776

Address: 501 Church

Print: x

Negative:

Description: Front Entrance - Scottish nondenominational /presbyterian?

**File number (CNB):** 776.1

Address: 501 Church

Print: x

Negative:

Description: view of steeple

**File number (CNB):** 776.2

Address: 501 Church

Print: x

Negative:

Description: side view of front

**File number (CNB):** 776.3

Address: 501 Church

Print: x

Negative:

Description: full side view

**File number (CNB):** 776.4

Address: 501 Church

Print: x

Negative:

Description: side view

**File number (CNB):** 776.5

Address: 501 Church

Print: x

Negative:

Description: opposite side from graveyard

**File number (CNB):** 776.6

Address: 501 Church

Print: x

Negative:

Description: photo of original brick structure

**File number (CNB):** 776.7

Address: 501 Church

Print: x

Negative:

Description: iron gate into private section of cemetery

**File number (CNB):** 776.8

Address: 501 Church

Print: x

Negative:

Description: interior

**File number (CNB):** 776.9

Address: 501 Church

Print: x  
Negative:  
Description: interior facing alter  
**File number (CNB):** 776.10  
Address: 501 Church  
Print: x  
Negative:  
Description: detail of apse  
**File number (CNB):** 776.11  
Address: 501 Church  
Print: x  
Negative:  
Description: detail of alter  
**File number (CNB):** 776.12  
Address: 501 Church  
Print: x  
Negative:  
Description: detail of column, and balcony entablature  
**File number (CNB):** 776.13  
Address: 501 Church  
Print: x  
Negative:  
Description: central ceiling detail  
**File number (CNB):** 776.14  
Address: 501 Church  
Print: x  
Negative:  
Description: column and cornice detail  
**File number (CNB):** 777  
Address: 411 Craven  
Print: x  
Negative:  
Description: 3/4 view of entrance  
**File number (CNB):** 777.1  
Address: 411 Craven  
Print: x  
Negative:  
Description: opposite side view of entrance  
**File number (CNB):** 777.2  
Address: 411 Craven  
Print: x  
Negative:  
Description: long shot view of side/rear  
**File number (CNB):** 777.3

Address: 411 Craven

Print: x

Negative:

Description: ^

**File number (CNB): 777.4**

Address: 411 Craven

Print: x

Negative:

Description: mid shot of rear

**File number (CNB): 777.5**

Address: 411 Craven

Print: x

Negative:

Description: mid shot of side and rear

**File number (CNB): 777.6**

Address: 411 Craven

Print: x

Negative:

Description: mid shot of front and side

**File number (CNB): 777.7**

Address: 411 Craven

Print: x

Negative:

Description: close up of column cap detail and entablature

**File number (CNB): 777.8**

Address: 411 Craven

Print: x

Negative:

Description: window dado detail

**File number (CNB): 777.9**

Address: 411 Craven

Print: x

Negative:

Description: front door interior

**File number (CNB): 777.10**

Address: 411 Craven

Print: x

Negative:

Description: view of both stairs

**File number (CNB): 777.11**

Address: 411 Craven

Print: x

Negative:

Description: living room, wall and mantel

**File number (CNB): 777.12**

Address: 411 Craven

Print: x

Negative:

Description: mantel detail, tile work

**File number (CNB): 777.13**

Address: 411 Craven

Print: x

Negative:

Description: 2nd room view, wall and mantel

**File number (CNB): 777.14**

Address: 411 Craven

Print: x

Negative:

Description: mantel detail, wood relief

**File number (CNB): 777.15**

Address: 411 Craven

Print: x

Negative:

Description: cornice detail

**File number (CNB): 778**

Address: 713 Craven

Print: x

Negative:

Description: front view from street

**File number (CNB): 778.1**

Address: 713 Craven

Print: x

Negative:

Description: side view from street

**File number (CNB): 778.2**

Address: 713 Craven

Print: x

Negative:

Description: pointed arch into auto courtyard

**File number (CNB): 778.3**

Address: 713 Craven

Print: x

Negative:

Description: entrance façade

**File number (CNB): 778.4**

Address: 713 Craven

Print: x

Negative:

Description: courtyard view facing the road

**File number (CNB): 779**

Address: 901 Craven

Print: x

Negative:

Description: full front view

**File number (CNB): 779.1**

Address: 901 Craven

Print: x

Negative:

Description: side

**File number (CNB): 779.2**

Address: 901 Craven

Print: x

Negative:

Description: rear

**File number (CNB): 779.3**

Address: 901 Craven

Print: x

Negative:

Description: side

**File number (CNB): 779.4**

Address: 901 Craven

Print: x

Negative:

Description: front door and balustrade detail

**File number (CNB): 779.5**

Address: 901 Craven

Print: x

Negative:

Description: front door framing

**File number (CNB): 779.6**

Address: 901 Craven

Print: x

Negative:

Description: stairwell and 1st flr hall way

**File number (CNB): 779.7**

Address: 901 Craven

Print: x

Negative:

Description: 2nd flr landing

**File number (CNB): 779.8**

Address: 901 Craven

Print: x

Negative:

Description: 2nd flr balcony doorway

**File number (CNB):** 780

Address: 1009 Craven

Print: x

Negative:

Description: Front entrance view, classicized Georgian style

**File number (CNB):** 780.1

Address: 1009 Craven

Print: x

Negative:

Description: side view

**File number (CNB):** 780.2

Address: 1009 Craven

Print: x

Negative:

Description: rear

**File number (CNB):** 780.3

Address: 1009 Craven

Print: x

Negative:

Description: side

**File number (CNB):** 780.4

Address: 1009 Craven

Print: x

Negative:

Description: window dado detail

**File number (CNB):** 780.5

Address: 1009 Craven

Print: x

Negative:

Description: front door

**File number (CNB):** 780.6

Address: 1009 Craven

Print: x

Negative:

Description: front porch

**File number (CNB):** 780.7

Address: 1009 Craven

Print: x

Negative:

Description: entrance hall and decorative archway

**File number (CNB):** 780.8

Address: 1009 Craven



Print: x

Negative:

Description: living room, wall and mantel

**File number (CNB):** 780.9

Address: 1009 Craven

Print: x

Negative:

Description: mantel detail, classical relief decoration

**File number (CNB):** 780.10

Address: 1009 Craven

Print: x

Negative:

Description: detail of relief

**File number (CNB):** 780.11

Address: 1009 Craven

Print: x

Negative:

Description: cornice detail

**File number (CNB):** 780.12

Address: 1009 Craven

Print: x

Negative:

Description: 2nd room wall and mantel detail

**File number (CNB):** 780.13

Address: 1009 Craven

Print: x

Negative:

Description: mantel detail also relief

**File number (CNB):** 780.14

Address: 1009 Craven

Print: x

Negative:

Description: close of relief

**File number (CNB):** 780.15

Address: 1009 Craven

Print: x

Negative:

Description: back entrance

**File number (CNB):** 781

Address: 1113 Craven

Print: x

Negative:

Description: street view 3/4 front view from right

**File number (CNB):** 781.1

Address: 1113 Craven

Print: x

Negative:

Description: side view

**File number (CNB):** 781.2

Address: 1113 Craven

Print: x

Negative:

Description: rear and side

**File number (CNB):** 781.3

Address: 1113 Craven

Print: x

Negative:

Description: iron balustrade

**File number (CNB):** 781.4

Address: 1113 Craven

Print: x

Negative:

Description: back/side door

**File number (CNB):** 781.5

Address: 1113 Craven

Print: x

Negative:

Description: guest house/dependency

**File number (CNB):** 781.6

Address: 1113 Craven

Print: x

Negative:

Description: rear view of guest house

**File number (CNB):** 781.7

Address: 1113 Craven

Print: x

Negative:

Description: a wall with writing location unknown

**File number (CNB):** 781.8

Address: 1113 Craven

Print: x

Negative:

Description: main front entrance

**File number (CNB):** 781.9

Address: 1113 Craven

Print: x

Negative:

Description: 2nd view^

**File number (CNB): 781.10**

Address: 1113 Craven

Print: x

Negative:

Description: view of living room to right, wall and mantel

**File number (CNB): 781.11**

Address: 1113 Craven

Print: x

Negative:

Description: view of left living room across front hallway

**File number (CNB): 781.12**

Address: 1113 Craven

Print: x

Negative:

Description: close up of mantel

**File number (CNB): 781.13**

Address: 1113 Craven

Print: x

Negative:

Description: cornice detail

**File number (CNB): 781.14**

Address: 1113 Craven

Print: x

Negative:

Description: view of front hall

**File number (CNB): 781.15**

Address: 1113 Craven

Print: x

Negative:

Description: ceiling decoration detail

**File number (CNB): 781.16**

Address: 1113 Craven

Print: x

Negative:

Description: 2nd view of living room across front hall

**File number (CNB): 781.17**

Address: 1113 Craven

Print: x

Negative:

Description: cornice detail

**File number (CNB): 781.18**

Address: 1113 Craven

Print: x

Negative:

Description: ceiling decoration detail

**File number (CNB):** 781.19

Address: 1113 Craven

Print: x

Negative:

Description: doorframe detail

**File number (CNB):** 781.20

Address: 1113 Craven

Print: x

Negative:

Description: wall and mantel

**File number (CNB):** 782

Address: 412 East

Print: x

Negative:

Description: front view

**File number (CNB):** 782.2

Address: 412 East

Print: x

Negative:

Description: side view

**File number (CNB):** 782.1

Address: 412 East

Print: x

Negative:

Description: side view

**File number (CNB):** 782.3

Address: 412 East

Print: x

Negative:

Description: rear view

**File number (CNB):** 782.4

Address: 412 East

Print: x

Negative:

Description: front door

**File number (CNB):** 782.5

Address: 412 East

Print: x

Negative:

Description: other door, exterior

**File number (CNB):** 782.6

Address: 412 East

Print: x

Negative:

Description: stairwell and hallway

**File number (CNB):** 782.7

Address: 412 East

Print: x

Negative:

Description: living room

**File number (CNB):** 782.8

Address: 412 East

Print: x

Negative:

Description: cornice detail above window

**File number (CNB):** 782.9

Address: 412 East

Print: x

Negative:

Description: mantel detail

**File number (CNB):** 782.10

Address: 412 East

Print: x

Negative:

Description: dining room

**File number (CNB):** 782.11

Address: 412 East

Print: x

Negative:

Description: cornice detail

**File number (CNB):** 783

Address: 302 Federal

Print: x

Negative:

Description: front view

**File number (CNB):** 783.1

Address: 302 Federal

Print: x

Negative:

Description: side view

**File number (CNB):** 783.2

Address: 302 Federal

Print: x

Negative:

Description: rear view

**File number (CNB):** 783.3

Address: 302 Federal

Print: x  
Negative:  
Description: pediment detail  
**File number (CNB):** 783.4  
Address: 302 Federal  
Print: x  
Negative:  
Description: front door  
**File number (CNB):** 783.5  
Address: 302 Federal  
Print: x  
Negative:  
Description: ^^  
**File number (CNB):** 783.6  
Address: 302 Federal  
Print: x  
Negative:  
Description: stairwell and hallway  
**File number (CNB):** 783.7  
Address: 302 Federal  
Print: x  
Negative:  
Description: parlor/dinning room  
**File number (CNB):** 783.8  
Address: 302 Federal  
Print: x  
Negative:  
Description: mantel detail, entablature  
**File number (CNB):** 783.9  
Address: 302 Federal  
Print: x  
Negative:  
Description: dinning room  
**File number (CNB):** 783.10  
Address: 302 Federal  
Print: x  
Negative:  
Description:  
**File number (CNB):** 783.11  
Address: 302 Federal  
Print: x  
Negative:  
Description: cornice detail in dinning room  
**File number (CNB):** 784

Address: 303 Federal

Print: x

Negative:

Description: side view from street

**File number (CNB):** 784.1

Address: 303 Federal

Print: x

Negative:

Description: front view from street

**File number (CNB):** 784.2

Address: 303 Federal

Print: x

Negative:

Description: side view from street

**File number (CNB):** 784.3

Address: 303 Federal

Print: x

Negative:

Description: side view from yard

**File number (CNB):** 784.4

Address: 303 Federal

Print: x

Negative:

Description: front view from yard

**File number (CNB):** 784.5

Address: 303 Federal

Print: x

Negative:

Description: front porch door frame

**File number (CNB):** 784.6

Address: 303 Federal

Print: x

Negative:

Description: stair/front hall

**File number (CNB):** 784.7

Address: 303 Federal

Print: x

Negative:

Description: ceiling detail

**File number (CNB):** 784.8

Address: 303 Federal

Print: x

Negative:

Description: dining room

**File number (CNB): 784.9**

Address: 303 Federal

Print: x

Negative:

Description: wall detail under window in dining room

**File number (CNB): 784.10**

Address: 303 Federal

Print: x

Negative:

Description: cornice detail in dining room

**File number (CNB): 784.11**

Address: 303 Federal

Print: x

Negative:

Description: ceiling detail

**File number (CNB): 784.12**

Address: 303 Federal

Print: x

Negative:

Description: living room, curved exterior wall

**File number (CNB): 784.13**

Address: 303 Federal

Print: x

Negative:

Description: cornice detail

**File number (CNB): 784.14**

Address: 303 Federal

Print: x

Negative:

Description: ceiling decoration

**File number (CNB): 785**

Address: 315 Federal

Print: x

Negative:

Description: Front facing from yard

**File number (CNB): 785.1**

Address: 315 Federal

Print: x

Negative:

Description: side front door

**File number (CNB): 785.2**

Address: 315 Federal

Print: x

Negative:



Description: rear view

**File number (CNB): 785.3**

Address: 315 Federal

Print: x

Negative:

Description: parlor room wall and mantel

**File number (CNB): 785.4**

Address: 315 Federal

Print: x

Negative:

Description: mantel detail, relief in freize

**File number (CNB): 785.6**

Address: 315 Federal

Print: x

Negative:

Description: cornice detail

**File number (CNB): 785.7**

Address: 315 Federal

Print: x

Negative:

Description: dining room

**File number (CNB): 785.8**

Address: 315 Federal

Print: x

Negative:

Description: mantel detail in dining room, relief in freize

**File number (CNB): 785.9**

Address: 315 Federal

Print: x

Negative:

Description: cornice detail in dining room

**File number (CNB): 785.10**

Address: 315 Federal

Print: x

Negative:

Description: 3 mantel detail

**File number (CNB): 786**

Address: 207 Hancock

Print: x

Negative:

Description: front view from yard

**File number (CNB): 786.1**

Address: 207 Hancock

Print: x

Negative:

Description: side view

**File number (CNB):** 786.2

Address: 207 Hancock

Print: x

Negative:

Description: rear view

**File number (CNB):** 786.3

Address: 207 Hancock

Print: x

Negative:

Description: side view

**File number (CNB):** 786.4

Address: 207 Hancock

Print: x

Negative:

Description: front view from yard

**File number (CNB):** 786.5

Address: 207 Hancock

Print: x

Negative:

Description: detail of balcony balustrade

**File number (CNB):** 787

Address: 1 Laurens

Print: x

Negative:

Description: front view from yard

**File number (CNB):** 787.1

Address: 1 Laurens

Print: x

Negative:

Description: photo of original structure?

**File number (CNB):** 787.2

Address: 1 Laurens

Print: x

Negative:

Description: side view

**File number (CNB):** 787.3

Address: 1 Laurens

Print: x

Negative:

Description: rear view

**File number (CNB):** 787.4

Address: 1 Laurens

Print: x  
Negative:  
Description: side view  
**File number (CNB): 787.5**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: detail of balcony balustrade and eave decoration  
**File number (CNB): 787.6**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: front door  
**File number (CNB): 787.7**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: french doors to second floor balcony  
**File number (CNB): 787.8**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: front hall, stairs  
**File number (CNB): 787.9**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: dining room looking into front hall  
**File number (CNB): 787.10**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: cornice detail  
**File number (CNB): 787.11**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: dining room mantel and wall  
**File number (CNB): 787.12**  
Address: 1 Laurens  
Print: x  
Negative:  
Description: living room looking into front hall  
**File number (CNB): 787.13**

Address: 1 Laurens

Print: x

Negative:

Description: living room window frame detail

**File number (CNB):** 787.14

Address: 1 Laurens

Print: x

Negative:

Description: cornice detail in living room

**File number (CNB):** 787.15

Address: 1 Laurens

Print: x

Negative:

Description: ceiling decoration

**File number (CNB):** 787.16

Address: 1 Laurens

Print: x

Negative:

Description: second floor view looking out french doors

**File number (CNB):** 787.17

Address: 1 Laurens

Print: x

Negative:

Description: mantel detail, 2nd flr

**File number (CNB):** 787.18

Address: 1 Laurens

Print: x

Negative:

Description: attic space, gabled roof

**File number (CNB):** 788

Address: 100 Laurens

Print: x

Negative:

Description: front view from yard

**File number (CNB):** 788.1

Address: 100 Laurens

Print: x

Negative:

Description: side view of porch

**File number (CNB):** 788.2

Address: 100 Laurens

Print: x

Negative:

Description: side view

**File number (CNB): 788.3**

Address: 100 Laurens

Print: x

Negative:

Description: rear view

**File number (CNB): 788.4**

Address: 100 Laurens

Print: x

Negative:

Description: long shot side view of porch

**File number (CNB): 788.5**

Address: 100 Laurens

Print: x

Negative:

Description: detail of balcony and column

**File number (CNB): 788.6**

Address: 100 Laurens

Print: x

Negative:

Description: detail of column and entablature

**File number (CNB): 788.7**

Address: 100 Laurens

Print: x

Negative:

Description: detail of window eave and entablature on niche exterior

**File number (CNB): 788.8**

Address: 100 Laurens

Print: x

Negative:

Description: porch steps and balustrade

**File number (CNB): 788.9**

Address: 100 Laurens

Print: x

Negative:

Description: porch window and shutters

**File number (CNB): 788.10**

Address: 100 Laurens

Print: x

Negative:

Description: front door

**File number (CNB): 788.11**

Address: 100 Laurens

Print: x

Negative:

Description: parlor room wall and mantel

**File number (CNB):** 788.12

Address: 100 Laurens

Print: x

Negative:

Description: mantel detail, parlor

**File number (CNB):** 788.13

Address: 100 Laurens

Print: x

Negative:

Description: ceiling decoration

**File number (CNB):** 788.14

Address: 100 Laurens

Print: x

Negative:

Description: view from parlor into hallway/dinning room

**File number (CNB):** 788.15

Address: 100 Laurens

Print: x

Negative:

Description: cornice detail

**File number (CNB):** 788.16

Address: 100 Laurens

Print: x

Negative:

Description: mantel detail

**File number (CNB):** 788.18

Address: 100 Laurens

Print: x

Negative:

Description: living room

**File number (CNB):** 788.19

Address: 100 Laurens

Print: x

Negative:

Description: second floor landing, archway

**File number (CNB):** 788.20

Address: 100 Laurens

Print: x

Negative:

Description: 1st flr stairway and hall

**File number (CNB):** 789

Address: 201 Laurens

Print: x

Negative:

Description: front entrance, with gate

**File number (CNB):** 789.1

Address: 201 Laurens

Print: x

Negative:

Description: left facing view of front entrance

**File number (CNB):** 789.2

Address: 201 Laurens

Print: x

Negative:

Description: left facing view of side (two chimneys)

**File number (CNB):** 789.3

Address: 201 Laurens

Print: x

Negative:

Description: left facing rear view of the house

**File number (CNB):** 789.4

Address: 201 Laurens

Print: x

Negative:

Description: straight view of rear entrance

**File number (CNB):** 789.5

Address: 201 Laurens

Print: x

Negative:

Description: view of the right side of the house

**File number (CNB):** 789.6

Address: 201 Laurens

Print: x

Negative:

Description: detail outside of front door

**File number (CNB):** 789.7

Address: 201 Laurens

Print: x

Negative:

Description: detail (doric column) architrave, frieze, cornice of the second story porch roof

**File number (CNB):** 789.8

Address: 201 Laurens

Print: x

Negative:

Description: roof balustrade and column detail

**File number (CNB):** 789.9

Address: 201 Laurens

Print: x

Negative:

Description: rear view of corner

**File number (CNB):** 789.10

Address: 201 Laurens

Print: x

Negative:

Description: view from yard

**File number (CNB):** 789.11

Address: 201 Laurens

Print: x

Negative:

Description: ^

**File number (CNB):** 789.12

Address: 201 Laurens

Print: x

Negative:

Description: ^^

**File number (CNB):** 790

Address: 214 New

Print: x

Negative:

Description: street view of back left

**File number (CNB):** 790.1

Address: 214 New

Print: x

Negative:

Description: street view of back right

**File number (CNB):** 790.2

Address: 214 New

Print: x

Negative:

Description: street view of right

**File number (CNB):** 790.3

Address: 214 New

Print: x

Negative:

Description: view of living room interior, mantel, architrave and frieze

**File number (CNB):** 790.4

Address: 214 New

Print: x

Negative:

Description: detail of mantel

**File number (CNB):** 790.5



Address: 214 New

Print: x

Negative:

Description: detail of mantel

**File number (CNB):** 790.6

Address: 214 New

Print: x

Negative:

Description: barrel vault niche with cornice

**File number (CNB):** 790.7

Address: 214 New

Print: x

Negative:

Description: 1st floor hallway under stairs

**File number (CNB):** 791

Address: 601 New

Print: x

Negative:

Description: front of church

**File number (CNB):** 791.1

Address: 601 New

Print: x

Negative:

Description: right side view

**File number (CNB):** 791.2

Address: 601 New

Print: x

Negative:

Description: back right view

**File number (CNB):** 791.3

Address: 601 New

Print: x

Negative:

Description: left side

**File number (CNB):** 791.4

Address: 601 New

Print: x

Negative:

Description: interior facing apse

**File number (CNB):** 791.5

Address: 601 New

Print: x

Negative:

Description: interior facing entrance

**File number (CNB): 791.6**

Address: 601 New

Print: x

Negative:

Description: detail of organ and alter

**File number (CNB): 791.7**

Address: 601 New

Print: x

Negative:

Description: architrave, frieze, cornice detail of the balcony

**File number (CNB): 792**

Address: 501 Pinckney

Print: x

Negative:

Description: front exterior

**File number (CNB): 792.1**

Address: 501 Pinckney

Print: x

Negative:

Description: left side view

**File number (CNB): 792.2**

Address: 501 Pinckney

Print: x

Negative:

Description: rear view

**File number (CNB): 792.3**

Address: 501 Pinckney

Print: x

Negative:

Description: front door detail

**File number (CNB): 792.4**

Address: 501 Pinckney

Print: x

Negative:

Description: door frame

**File number (CNB): 792.5**

Address: 501 Pinckney

Print: x

Negative:

Description: 1st floor front hallway

**File number (CNB): 792.6**

Address: 501 Pinckney

Print: x

Negative:

Description: living room mantel and window

**File number (CNB):** 792.7

Address: 501 Pinckney

Print: x

Negative:

Description: detail of mantel

**File number (CNB):** 792.8

Address: 501 Pinckney

Print: x

Negative:

Description: dinning room facing mantel

**File number (CNB):** 792.9

Address: 501 Pinckney

Print: x

Negative:

Description: detail of mantel

**File number (CNB):** 792.10

Address: 501 Pinckney

Print: x

Negative:

Description: detail cornice

**File number (CNB):** 792.11

Address: 501 Pinckney

Print: x

Negative:

Description: 1st flr view of stairs

**File number (CNB):** 792.12

Address: 501 Pinckney

Print: x

Negative:

Description: second flr landing and view of stairs

**File number (CNB):** 793

Address: 604 Pinckney

Print: x

Negative:

Description: front facing street view

**File number (CNB):** 793.1

Address: 604 Pinckney

Print: x

Negative:

Description: left facing street view (porch)

**File number (CNB):** 793.2

Address: 604 Pinckney

Print: x

Negative:

Description: rear facing left side view

**File number (CNB):** 793.3

Address: 604 Pinckney

Print: x

Negative:

Description: straight on rear view

**File number (CNB):** 793.4

Address: 604 Pinckney

Print: x

Negative:

Description: rear right side view

**File number (CNB):** 793.5

Address: 604 Pinckney

Print: x

Negative:

Description: front porch entrance detail

**File number (CNB):** 793.6

Address: 604 Pinckney

Print: x

Negative:

Description: gate detail

**File number (CNB):** 793.7

Address: 604 Pinckney

Print: x

Negative:

Description: rear door detail

**File number (CNB):** 793.8

Address: 604 Pinckney

Print: x

Negative:

Description: foyer 1st floor - post and lintel framing

**File number (CNB):** 793.9

Address: 604 Pinckney

Print: x

Negative:

Description: 1st flr view of stairs

**File number (CNB):** 793.10

Address: 604 Pinckney

Print: x

Negative:

Description: cornice detail 1st floor view

**File number (CNB):** 793.11

Address: 604 Pinckney

Print: x  
Negative:  
Description: cantelever stairwell, stucco and wallpaper  
**File number (CNB):** 793.12  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: living room  
**File number (CNB):** 793.13  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: mantel detail - stone masonry  
**File number (CNB):** 793.14  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: doorway to porch  
**File number (CNB):** 793.15  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: cornice detail  
**File number (CNB):** 793.16  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: ceiling detail  
**File number (CNB):** 793.17  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: mantel detail - stone masonry  
**File number (CNB):** 793.18  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: dining room into living room  
**File number (CNB):** 793.19  
Address: 604 Pinckney  
Print: x  
Negative:  
Description: mantel, post and pediment  
**File number (CNB):** 793.20

Address: 604 Pinckney  
Print: x  
Negative:  
Description: 2nd flr stair landing  
**File number (CNB):** 794  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: front view  
**File number (CNB):** 794.1  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: left side, garage  
**File number (CNB):** 794.2  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: rear  
**File number (CNB):** 794.3  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: right side view  
**File number (CNB):** 794.4  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: detail of 2nd flr porch  
**File number (CNB):** 794.5  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: front door detail  
**File number (CNB):** 794.6  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: living room  
**File number (CNB):** 794.7  
Address: 500 Port Republic  
Print: x  
Negative:  
Description: mantel

**File number (CNB): 794.8**

Address: 500 Port Republic

Print: x

Negative:

Description: door and window frame

**File number (CNB): 794.9**

Address: 500 Port Republic

Print: x

Negative:

Description: cornice

**File number (CNB): 795**

Address: 915 Port Republic

Print: x

Negative:

Description: front

**File number (CNB): 795.1**

Address: 915 Port Republic

Print: x

Negative:

Description: side

**File number (CNB): 795.2**

Address: 915 Port Republic

Print: x

Negative:

Description: side

**File number (CNB): 795.3**

Address: 915 Port Republic

Print: x

Negative:

Description: rear porch

**File number (CNB): 795.4**

Address: 915 Port Republic

Print: x

Negative:

Description: front door exterior detail

**File number (CNB): 795.5**

Address: 915 Port Republic

Print: x

Negative:

Description: architrave, frieze, cornice detail of the balcony

**File number (CNB): 795.6**

Address: 915 Port Republic

Print: x

Negative:

Description: living room

**File number (CNB):** 795.7

Address: 915 Port Republic

Print: x

Negative:

Description: mantel and wall

**File number (CNB):** 795.8

Address: 915 Port Republic

Print: x

Negative:

Description: decorative cornice

**File number (CNB):** 795.9

Address: 915 Port Republic

Print: x

Negative:

Description: detail of cornice

**File number (CNB):** 795.10

Address: 915 Port Republic

Print: x

Negative:

Description: parlor/sitting room, mantel and cornice

**File number (CNB):** 795.11

Address: 915 Port Republic

Print: x

Negative:

Description: door way, dado and wall paper

**File number (CNB):** 795.12

Address: 915 Port Republic

Print: x

Negative:

Description:

**File number (CNB):** 795.13

Address: 915 Port Republic

Print: x

Negative:

Description:

**File number (CNB):** 796

Address: 511 Prince

Print: x

Negative:

Description: front of house

**File number (CNB):** 796.1

Address: 511 Prince

Print: x



Negative:

Description: side view

**File number (CNB):** 796.2

Address: 511 Prince

Print: x

Negative:

Description: back right view

**File number (CNB):** 796.3

Address: 511 Prince

Print: x

Negative:

Description: side view

**File number (CNB):** 796.4

Address: 511 Prince

Print: x

Negative:

Description: front door detail

**File number (CNB):** 796.5

Address: 511 Prince

Print: x

Negative:

Description: mantel detail - stone masonry

**File number (CNB):** 796.6

Address: 511 Prince

Print: x

Negative:

Description: wall decoration, cornice

**File number (CNB):** 796.7

Address: 511 Prince

Print: x

Negative:

Description: close up of mantel

**File number (CNB):** 796.8

Address: 511 Prince

Print: x

Negative:

Description: opposite side of room mantel

**File number (CNB):** 797

Address: 901 Prince

Print: x

Negative:

Description: front of house

**File number (CNB):** 797.1

Address: 901 Prince

Print: x  
Negative:  
Description: side view  
**File number (CNB):** 797.2  
Address: 901 Prince  
Print: x  
Negative:  
Description: rear  
**File number (CNB):** 797.3  
Address: 901 Prince  
Print: x  
Negative:  
Description: side view  
**File number (CNB):** 797.4  
Address: 901 Prince  
Print: x  
Negative:  
Description: second flr balcony detail  
**File number (CNB):** 797.5  
Address: 901 Prince  
Print: x  
Negative:  
Description: front door detail  
**File number (CNB):** 797.6  
Address: 901 Prince  
Print: x  
Negative:  
Description: window detail  
**File number (CNB):** 797.7  
Address: 901 Prince  
Print: x  
Negative:  
Description: side porch door detail  
**File number (CNB):** 797.8  
Address: 901 Prince  
Print: x  
Negative:  
Description: living room, mantel and chandelier  
**File number (CNB):** 797.9  
Address: 901 Prince  
Print: x  
Negative:  
Description: mantel detail - stone masonry  
**File number (CNB):** 797.10

Address: 901 Prince

Print: x

Negative:

Description: dining room

**File number (CNB):** 797.11

Address: 901 Prince

Print: x

Negative:

Description: side board and mantel

**File number (CNB):** 798

Address: 705 Washington

Print: x

Negative:

Description: front of house

**File number (CNB):** 798.1

Address: 705 Washington

Print: x

Negative:

Description: side view

**File number (CNB):** 798.2

Address: 705 Washington

Print: x

Negative:

Description: side

**File number (CNB):** 798.3

Address: 705 Washington

Print: x

Negative:

Description: rear

**File number (CNB):** 798.4

Address: 705 Washington

Print: x

Negative:

Description: front view of porches and door

**File number (CNB):** 798.5

Address: 705 Washington

Print: x

Negative:

Description: close up of front door

**File number (CNB):** 798.6

Address: 705 Washington

Print: x

Negative:

Description: window detail

**File number (CNB): 798.7**

Address: 705 Washington

Print: x

Negative:

Description: second flr rear window detail

**File number (CNB): 798.8**

Address: 705 Washington

Print: x

Negative:

Description: second flr landing facing rear window

**File number (CNB): 798.9**

Address: 705 Washington

Print: x

Negative:

Description: 2nd flr room with mantel

**File number (CNB): 798.10**

Address: 705 Washington

Print: x

Negative:

Description: window detail

**File number (CNB): 798.11**

Address: 705 Washington

Print: x

Negative:

Description: mantel detail -

**File number (CNB): 798.12**

Address: 705 Washington

Print: x

Negative:

Description: architrave, frieze, cornice detail

**File number (CNB): 798.13**

Address: 705 Washington

Print: x

Negative:

Description: mantel

**File number (CNB): 798.14**

Address: 705 Washington

Print: x

Negative:

Description: close up of mantel

**File number (CNB): 798.15**

Address: 705 Washington

Print: x

Negative:

Description: cornice above mantel detail

**File number (CNB):** 799

Address: 400 Wilmington

Print: x

Negative:

Description: street view of front from gate

**File number (CNB):** 799.1

Address: 400 Wilmington

Print: x

Negative:

Description: right side street view

**File number (CNB):** 799.2

Address: 400 Wilmington

Print: x

Negative:

Description: front door close up (iron balustrade)

**File number (CNB):** 799.3

Address: 400 Wilmington

Print: x

Negative:

Description: rear view

**File number (CNB):** 799.4

Address: 400 Wilmington

Print: x

Negative:

Description: front door in detail

**File number (CNB):** 799.5

Address: 400 Wilmington

Print: x

Negative:

Description: window/door to interior detail

**File number (CNB):** 799.6

Address: 400 Wilmington

Print: x

Negative:

Description: wooden decorative railing

**File number (CNB):** 799.7

Address: 400 Wilmington

Print: x

Negative:

Description: column and frieze/cornice detail

**File number (CNB):** 799.8

Address: 400 Wilmington

Print: x

Negative:

Description: main front door detail - framed w post and lintel pilaster

**File number (CNB):** 799.9

Address: 400 Wilmington

Print: x

Negative:

Description: 1st flr stair well

**File number (CNB):** 799.10

Address: 400 Wilmington

Print: x

Negative:

Description: door, mantel and cornice view facing back of the house

**File number (CNB):** 799.11

Address: 400 Wilmington

Print: x

Negative:

Description: mantel and mirror

**File number (CNB):** 799.12

Address: 400 Wilmington

Print: x

Negative:

Description: detail of front door, decorative framing

**File number (CNB):** 799.13

Address: 400 Wilmington

Print: x

Negative:

Description: framing detail and cornice

**File number (CNB):** 799.14

Address: 400 Wilmington

Print: x

Negative:

Description: detail of cornice

**File number (CNB):** 799.15

Address: 400 Wilmington

Print: x

Negative:

Description: ceiling decoration detail

**File number (CNB):** 799.16

Address: 400 Wilmington

Print: x

Negative:

Description: 1st flr cornice (detail)

**File number (CNB):** 799.17

Address: 400 Wilmington

Print: x

Negative:

Description: 1st flr living room looking toward parol and stairs, formal fire place (potentiall original

**File number (CNB):** 799.18

Address: 400 Wilmington

Print: x

Negative:

Description: Fire place, post and lintel mantel

**File number (CNB):** 799.19

Address: 400 Wilmington

Print: x

Negative:

Description: detail of cornice

**File number (CNB):** 801

Address: 321 East Bay

Print: x

Negative:

Description: Second floor hall way, decorative arch way and cornice

**File number (CNB):** 801

Address: 321 East Bay

Print:

Negative: X

Description: South and east sides; door frontispiece after 1940

**File number (CNB):** 801.1

Address: 321 East Bay

Print: X

Negative: X

Description: West and south sides

**File number (CNB):** 801.2

Address: 321 East Bay

Print: X

Negative: X

Description: West side entry steps

**File number (CNB):** 801.3

Address: 321 East Bay

Print:

Negative: X

Description: Detail, east side railing

**File number (CNB):** 802

Address: 332 East Bay

Print: X

Negative: X

Description: c.1817, Primrose House, west and south sides

**File number (CNB): 802.1**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, west and north sides

**File number (CNB): 802.2**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, south and east sides

**File number (CNB): 802.3**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, south and east sides showing pedimented masonry dormer

**File number (CNB): 802.4**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, southside masonry pedimented dormer from southwest

**File number (CNB): 802.5**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, westside gate, not original to site

**File number (CNB): 802.6**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, westside, portico steps and railing, not original to site

**File number (CNB): 802.7**

Address: 332 East Bay

Print: X

Negative: X

Description: Primrose House, 1st floor, portico, southside entry

**File number (CNB): 803 (1)**

Address: 35 Archdale

Print: X

Negative: X

Description: Carriage gate, 19th C, formerly at graveyard on Princess St.

**File number (CNB): 803 (2)**

Address: 35 Archdale

Print:

Negative: X



Description: Carriage gate, 19th C, formerly at graveyard on Princess St.

**File number (CNB):** 804

Address: 63 South Battery

Print: X

Negative: X

Description: Center pass gate and fencing, not original to site

**File number (CNB):** 804.1 (1)

Address: 63 South Battery

Print: X

Negative: X

Description: Half carriage gate and fencing, not original to site

**File number (CNB):** 804.1 (2)

Address: 63 South Battery

Print:

Negative: X

Description: Half carriage gate and fencing, not original to site

**File number (CNB):** 804.2

Address: 63 South Battery

Print: X

Negative: X

Description: Eastend pass gate

**File number (CNB):** 805

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, looking west. Woodwork (except mantel) formerly at 281 Meeting and altered to fit 2'0" lower ceiling. 281 destroyed Aug '47.

**File number (CNB):** 805.1

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, looking southeast

**File number (CNB):** 805.2

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, door case and cornice. Window case similar except wider. Shell cupboards not original to 281 Meeting.

**File number (CNB):** 805.3

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, door case, upper section

**File number (CNB):** 805.4

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, door case, center section

**File number (CNB):** 805.5

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, door case, lower section

**File number (CNB):** 805.6

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, cornice detail. Top of doorcase probably fit under bottom of bead moulding of enfablature originally, since cornice has been lowered 2'0"

**File number (CNB):** 805.7

Address: 17 Longitude Lane

Print: X

Negative: X

Description: 1st flr- southeast room, chimney piece, mantle not part of other woodwork, origin unknown

**File number (CNB):** 806

Address: 20 Elliott

Print: X

Negative:

Description: gate

**File number (CNB):** 806.1

Address: 20 Elliott

Print:

Negative: X

Description: Southside iron gate

**File number (CNB):** 807

Address: 22 Elliott

Print: X

Negative: X

Description: Southside entry. See Deas, pg 74

**File number (CNB):** 807.1

Address: 22 Elliott

Print:

Negative: X

Description: Southside, entry transom

**File number (CNB):** 808

Address: 8 St. Michael's Alley

Print: X

Negative: X

Description: House- c. 1848; EB White, Architect; JL Petigru, Builder; southwest side

**File number (CNB):** 808.1 (1)

Address: 8 St. Michael's Alley

Print: X

Negative: X

Description: Southside, balcony added after 1910; see photo, pg 168 "Charleston, Come Hell or High Water" with no evidence of fastening devices; compare 20 Charlotte, #816.1

**File number (CNB):** 808.1 (2)

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside, balcony added after 1910; see photo, pg 168 "Charleston, Come Hell or High Water" with no evidence of fastening devices; compare 20 Charlotte, #816.1

**File number (CNB):** 808.2 (1) H

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside carriage gates. Pass gate on opposite side of house, same as one leaf

**File number (CNB):** 808.2 (2) H

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside carriage gates. Pass gate on opposite side of house, same as one leaf

**File number (CNB):** 808.2 (3) H

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside carriage gates. Pass gate on opposite side of house, same as one leaf

**File number (CNB):** 808.2 (4) V

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside carriage gates. Pass gate on opposite side of house, same as one leaf

**File number (CNB):** 808.2 (5) V

Address: 8 St. Michael's Alley

Print:

Negative: X

Description: Southside carriage gates. Pass gate on opposite side of house, same as one leaf

**File number (CNB):** 809

Address: Fenwick Hall

Print: X

Negative: X

Description: Complex southside, left to right, c.1934 Kitchen, c.1787 house addition, c.1730 house

**File number (CNB): 809.1**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, southside, entry detail, c.1930. Doors shown, c.1979

**File number (CNB): 809.2**

Address: Fenwick Hall

Print: X

Negative: X

Description: Complex southeast corner, left to right, c.1750 carriage house, c.1787 house addition, 1730 house. A matching race horse breeding stable formerly balanced the carriage house on the eastside of the house

**File number (CNB): 809.3**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, eastside, 2nd floor doors. Iron gate and garden wall, c.1934

**File number (CNB): 809.4**

Address: Fenwick Hall

Print: X

Negative: X

Description: Complex northside, left to right, 1730 house, c.1787 house addition, c.1934 kitchen

**File number (CNB): 809.5**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, northside entry and Palladian window (narrow brick piers between sash).

Doors shown, c.1979

**File number (CNB): 809.6**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1934 Kitchen and 1787 house addition, westside

**File number (CNB): 809.7 (1)**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1934 Kitchen, 1787 house addition, 1730 house, southwest corner

**File number (CNB): 809.7 (2)**

Address: Fenwick Hall

Print:

Negative: X

Description: 1934 Kitchen, 1787 house addition, 1730 house, southwest corner

**File number (CNB): 809.8**

Address: Fenwick Hall

Print: X

Negative: X

Description: c.1750 carriage house and stable, southeast sides, brick wall c.1934

**File number (CNB):** 809.9

Address: Fenwick Hall

Print: X

Negative: X

Description: c.1750 carriage house and stable, northeast sides, doors c.1979

**File number (CNB):** 809.10

Address: Fenwick Hall

Print:

Negative: X

Description: 1730 house, southwest entry, 1st floor, north wall

**File number (CNB):** 809.11

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southwest room, stairs looking north

**File number (CNB):** 809.12

Address: Fenwick Hall

Print:

Negative: X

Description: 1730 house, 1st floor, southwest entry, east wall

**File number (CNB):** 809.13

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southwest room, south wall

**File number (CNB):** 809.14 (1)

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southwest entry, west wall chimney piece

**File number (CNB):** 809 14 (2)

Address: Fenwick Hall

Print:

Negative: X

Description: 1730 house, 1st floor, southwest entry, west wall chimney piece

**File number (CNB):** 809.15

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southwest entry, mantle

**File number (CNB): 809.16**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southwest room, cornice and panel mould detail

**File number (CNB): 809.17**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southeast room, east wall

**File number (CNB): 809.18**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southeast room, north wall

**File number (CNB): 809.19**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southeast room, west wall

**File number (CNB): 809.20**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southeast room, mantle

**File number (CNB): 809.21**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, southeast room, cornice

**File number (CNB): 809.22**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, northeast room, east wall; concealed door 1934

**File number (CNB): 809.23**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, northeast room, looking northwest

**File number (CNB): 809.24**

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 1st floor, northeast room, mantle

**File number (CNB):** 809.25

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, stair hall, looking north

**File number (CNB):** 809.26

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, southeast room, looking east. Right door to closet, left door formerly to closet, to portico roof c.1934

**File number (CNB):** 809.27

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, southeast room, door and panel detail. Concealed door c.1934

**File number (CNB):** 809.28

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, southeast room, mantle

**File number (CNB):** 809.29

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, northeast room, looking northeast; left door to closet; right door formerly to closet, to portico roof c.1934

**File number (CNB):** 809.30

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, northeast room, mantle, raised hearth, c.1934

**File number (CNB):** 809.31

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, southwest room, west wall

**File number (CNB):** 809.32

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, southwest room, mantle; Northwest room, mantle same.

**File number (CNB):** 809.33

Address: Fenwick Hall

Print: X

Negative: X

Description: 1730 house, 2nd floor, northwest room, east wall

**File number (CNB):** 809.34

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 1st floor, south room, west wall; 1979 mirror over mantle removed for repairs

**File number (CNB):** 809.35

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 1st floor, south room, mantle

**File number (CNB):** 809.36

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 1st floor, south room, looking southeast

**File number (CNB):** 809.37

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 1st floor, north room, looking northwest

**File number (CNB):** 809.38

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 1st floor, stairhall looking east into 1730 entry room

**File number (CNB):** 809.39

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 2nd floor, stair hall, looking west

**File number (CNB):** 809.40

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 2nd floor, south room, west wall, right side door to cupboard which is not original

**File number (CNB):** 809.41

Address: Fenwick Hall

Print: X



Negative: X

Description: 1787 house addition, 2nd floor, south room, mantle

**File number (CNB):** 809.42

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 2nd floor, south room, looking southeast, concealed door to 1934 bath

**File number (CNB):** 809.43

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 2nd floor, north room, west wall. Tall door to stair down to 1934 room over kitchen. Other doors to cupboards

**File number (CNB):** 809.44

Address: Fenwick Hall

Print: X

Negative: X

Description: 1787 house addition, 2nd floor, north room, east wall

**File number (CNB):** 809.45

Address: Fenwick Hall

Print: X

Negative: X

Description: c.1934 Kitchen, 2nd floor room, west wall, coved ceiling

**File number (CNB):** 810

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), southeast corner

**File number (CNB):** 810.1

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), eastside

**File number (CNB):** 810.2

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), eastside, Palladian window detail

**File number (CNB):** 810.3

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), northwest corner

**File number (CNB): 810.4**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), southwest sides

**File number (CNB): 810.5**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), southside entry. Northside same.

**File number (CNB): 810.6**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), southside, west jamb, completion date

**File number (CNB): 810.7**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), southside, entry, east jamb, mason's, architect's, and contractor's cipher

**File number (CNB): 810.8**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Nave, looking east

**File number (CNB): 810.9**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), chancel

**File number (CNB): 810.10**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Palladian window detail, interior

**File number (CNB): 810.11**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Nave, looking west

**File number (CNB): 810.12**

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Nave, looking northeast

**File number (CNB):** 810.13

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Nave, looking south

**File number (CNB):** 810.14 (1)

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Pulpit

**File number (CNB):** 810.14 (2)

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Pulpit

**File number (CNB):** 810.14 (3)

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Pulpit

**File number (CNB):** 810.15

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Pulpit detail

**File number (CNB):** 810.16

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Pulpit teaster soffitt

**File number (CNB):** 810.17

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Simon's memorial

**File number (CNB):** 810.18

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Northeast corner, damage exterior

**File number (CNB):** 810.19

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), west ceiling, damage

**File number (CNB):** 810.20

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), Northeast corner damage, interior

**File number (CNB):** 810.21

Address: Berkeley Co. Pompion Hill Chapel

Print:

Negative: X

Description: c.1767 (Episcopal), North wall, damage over door

**File number (CNB):** 811

Address: 75 Anson

Print:

Negative: X

Description: Entry, northside

**File number (CNB):** 811.1

Address: 75 Anson

Print:

Negative: X

Description: Entry, eastside

**File number (CNB):** 811

Address: 121 Broad

Print:

Negative: X

Description: Carriage and pass gates

**File number (CNB):** 812.1

Address: 121 Broad

Print:

Negative: X

Description: Fence detail

**File number (CNB):** 813

Address: 43 Bull

Print:

Negative: X

Description: Entry gate, c.1850

**File number (CNB):** 813.1

Address: 43 Bull

Print:

Negative: X

Description: Northwest corner, house, c.1830-40. Ironwork and ground floors bay c.1850

**File number (CNB):** 813.2

Address: 43 Bull

Print:

Negative: X

Description: Portico ironwork, c.1850

**File number (CNB):** 813.3

Address: 43 Bull

Print:

Negative: X

Description: Garden fountain, c.1850; figure, c.20th century

**File number (CNB):** 814

Address: 52 Bull

Print:

Negative: X

Description: Fence, carriage, and pass gates

**File number (CNB):** 815

Address: 16 Charlotte

Print:

Negative: X

Description: Entry gate

**File number (CNB):** 815.1 (1)

Address: 16 Charlotte

Print:

Negative: X

Description: Southside, stoop and stair railing; stairs may not be original to house since brick work differs

**File number (CNB):** 815.1 (2)

Address: 16 Charlotte

Print:

Negative: X

Description: Southside, stoop and stair railing; stairs may not be original to house since brick work differs

**File number (CNB):** 815.1 (3)

Address: 16 Charlotte

Print:

Negative: X

Description: Southside, stoop and stair railing; stairs may not be original to house since brick work differs

**File number (CNB):** 815.1 (4)

Address: 16 Charlotte

Print:

Negative: X

Description: Southside, stoop and stair railing; stairs may not be original to house since brick work differs

**File number (CNB):** 815.1 (5)

Address: 16 Charlotte

Print:

Negative: X

Description: Southside, stoop and stair railing; stairs may not be original to house since brick work differs

**File number (CNB):** 815.2 (1)

Address: 16 Charlotte

Print:

Negative: X

Description: Stoop railing detail

**File number (CNB):** 815.2 (2)

Address: 16 Charlotte

Print:

Negative: X

Description: Stoop railing detail

**File number (CNB):** 816

Address: 20 Charlotte

Print:

Negative: X

Description: c.1848 Joseph Aiken; JM Curtis, Architect; passgate

**File number (CNB):** 816.1

Address: 20 Charlotte

Print:

Negative: X

Description: Southside entry and column base

**File number (CNB):** 816.2

Address: 20 Charlotte

Print:

Negative: X

Description: Southside, 1st floor, railing

**File number (CNB):** 816.3

Address: 20 Charlotte

Print:

Negative: X

Description: Southside, balcony railing

**File number (CNB):** 816.4

Address: 20 Charlotte

Print:

Negative: X

Description: Southside balcony support

**File number (CNB):** 816.5

Address: 20 Charlotte

Print:

Negative: X

Description: Southside column cap

**File number (CNB): 817**

Address: 33 Charlotte

Print:

Negative: X

Description: Pass gate

**File number (CNB): 817.1**

Address: 33 Charlotte

Print:

Negative: X

Description: Stoop railing detail

**File number (CNB): 818**

Address: 44 Charlotte

Print:

Negative: X

Description: Pass gate and fence

**File number (CNB): 818.1**

Address: 44 Charlotte

Print:

Negative: X

Description: Carriage gate

**File number (CNB): 819**

Address: 11 Church

Print:

Negative: X

Description: Carriage and pass gates

**File number (CNB): 820**

Address: 15 Church

Print:

Negative: X

Description: Stoop railing and yard fence

**File number (CNB): 821**

Address: 51 Church

Print:

Negative: X

Description: Pass and carriage gates

**File number (CNB): 823 (1)**

Address: 53 Church

Print:

Negative: X

Description: Carriage gate by Ortmann Bros. (1900-32) Bragg

**File number (CNB): 823 (2)**

Address: 53 Church

Print:

Negative: X

Description: Carriage gate by Ortmann Bros. (1900-32) Bragg

**File number (CNB): 824**

Address: 73 Church

Print:

Negative: X

Description: Westside, balcony, by FJ Ortman (1875-1897) Bragg

**File number (CNB): 825**

Address: 107 Church

Print:

Negative: X

Description: Eastside, balcony (Sonn, 226) (Deas)

**File number (CNB): 826**

Address: 132 1/2 Church

Print:

Negative: X

Description: Carriage gate

**File number (CNB): 827**

Address: Magnolia Cemetery

Print:

Negative: X

Description: Cunningham Ave, Vanderhorst Mausoleum, F.D. Lee architect, from southeast

**File number (CNB): 827.1**

Address: Magnolia Cemetery

Print:

Negative: X

Description: Cunningham Ave, Vanderhorst Mausoleum, F.D. Lee architect, interior, westside

**File number (CNB): 827.2**

Address: Magnolia Cemetery

Print:

Negative: X

Description: Cunningham Ave, Middleton Stone

**File number (CNB): 828 (1)**

Address: 1 East Battery

Print:

Negative: X

Description: Eastside, 1st floor balcony and ground, floor entry hood

**File number (CNB): 828 (2)**

Address: 1 East Battery

Print:

Negative: X

Description: Eastside, 1st floor balcony and ground, floor entry hood

**File number (CNB): 828.1**

Address: 1 East Battery

Print:



Negative: X

Description: Eastside, ground floor balcony

**File number (CNB):** 828.2

Address: 1 East Battery

Print:

Negative: X

Description: Eastside, 2nd floor balcony

**File number (CNB):** 829

Address: 13 East Battery

Print:

Negative: X

Description: Eastside from southeast, showing also 9 E Battery on left

**File number (CNB):** 829.1

Address: 13 East Battery

Print:

Negative: X

Description: Northeast sides

**File number (CNB):** 829.2

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, 1st floor, entry

**File number (CNB):** 829.3 (1)

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, 2nd floor balcony, support brackets similar to 8 Meeting #378.2

**File number (CNB):** 829.3 (2)

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, 2nd floor balcony, support brackets similar to 8 Meeting #378.2

**File number (CNB):** 829.4

Address: 13 East Battery

Print:

Negative: X

Description: Southwest sides

**File number (CNB):** 829.5 (1)

Address: 13 East Battery

Print:

Negative: X

Description: Partial south side

**File number (CNB):** 829.5 (2)

Address: 13 East Battery

Print:

Negative: X

Description: Partial south side

**File number (CNB):** 829.6

Address: 13 East Battery

Print:

Negative: X

Description: Southside, balcony

**File number (CNB):** 829.7

Address: 13 East Battery

Print:

Negative: X

Description: Southside, balcony detail

**File number (CNB):** 829.8

Address: 13 East Battery

Print:

Negative: X

Description: Southside, balcony support bracket

**File number (CNB):** 829.9

Address: 13 East Battery

Print:

Negative: X

Description: Northside, looking southeast

**File number (CNB):** 829.10

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, carriage house, northside of dependency on left

**File number (CNB):** 829.11

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, ruin of brownstone column cap, 4 thus plus 2 pilaster caps, formerly supporting eastside portico, demolished in 1886 earthquake

**File number (CNB):** 829.12

Address: 13 East Battery

Print:

Negative: X

Description: Eastside, hitching post

**File number (CNB):** 830

Address: 17 East Battery

Print:

Negative: X

Description: Eastside, entry gate

**File number (CNB): 831**

Address: 29 East Battery

Print:

Negative: X

Description: Entry gate and fence

**File number (CNB): 831.1 (1)**

Address: 29 East Battery

Print:

Negative: X

Description: Double gate detail

**File number (CNB): 831.1 (2)**

Address: 29 East Battery

Print:

Negative: X

Description: Double gate detail

**File number (CNB): 832**

Address: 47 East Bay

Print:

Negative: X

Description: Carriage gate, by Ortmann, Bragg

**File number (CNB): 833**

Address: 51 East Bay

Print:

Negative: X

Description: Eastside, half of carriage gate

**File number (CNB): 834**

Address: 55 East Bay

Print:

Negative: X

Description: Balcony detail, compare 72 Meeting #413.2

**File number (CNB): 835**

Address: 57 East Bay

Print:

Negative: X

Description: Eastside, balcony detail. Compare 27 Meeting #388.1. Originally at 25 Queen c.1810. The cypher J.T. in the circle is for the 25 Queen builder, James Tate, who also built 23 Queen

**File number (CNB): 836**

Address: 59 East Bay

Print:

Negative: X

Description: North carriage gate, eastside

**File number (CNB): 836.1**

Address: 59 East Bay

Print:

Negative: X

Description: South pass gate, east side

**File number (CNB): 837**

Address: 83 East Bay

Print:

Negative: X

Description: Eastside balcony detail, formerly on State St (Frost). Compare 121 Church #1001

**File number (CNB): 838**

Address: 89 East Bay

Print:

Negative: X

Description: Eastside pass gate

**File number (CNB): 839**

Address: 91 East Bay

Print:

Negative: X

Description: Eastside, pass gate

**File number (CNB): 840 (1)**

Address: 301 East Bay

Print:

Negative: X

Description: Eastside, 2nd floor, cheval-de-frise, gone 1981; vertical on right hand side not in FB Johnson photograph c.1930

**File number (CNB): 840 (2)**

Address: 301 East Bay

Print:

Negative: X

Description: Eastside, 2nd floor, cheval-de-frise, gone 1981; vertical on right hand side not in FB Johnson photograph c.1930

**File number (CNB): 840 (3)**

Address: 301 East Bay

Print:

Negative: X

Description: Eastside, 2nd floor, cheval-de-frise, gone 1981; vertical on right hand side not in FB Johnson photograph c.1930

**File number (CNB): 840.1**

Address: 301 East Bay

Print:

Negative: X

Description: Piazza S scroll cheval-de-frise, gone

**File number (CNB): 841**

Address: 1 Elliott

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 842

Address: 28 Elliott

Print:

Negative: X

Description: Entry transom, Thibault or William Johnson (Sonn)

**File number (CNB):** 843

Address: 10 Franklin

Print:

Negative: X

Description: Entry gates

**File number (CNB):** 844

Address: 12 Franklin

Print:

Negative: X

Description: Entry fence

**File number (CNB):** 845

Address: 66 George

Print:

Negative: X

Description: Fence detail at building

**File number (CNB):** 845.1 (1)

Address: 66 George

Print:

Negative: X

Description: College of Charleston's Porter Lodge, pass gate by C. Warner c.1852

**File number (CNB):** 845.1 (2)

Address: 66 George

Print:

Negative: X

Description: College of Charleston's Porter Lodge, pass gate by C. Warner c.1852

**File number (CNB):** 845.2 (1)

Address: 66 George

Print:

Negative: X

Description: College of Charleston's Porter Lodge, carriage gate by C. Warner c.1852

**File number (CNB):** 845.2 (2)

Address: 66 George

Print:

Negative: X

Description: College of Charleston's Porter Lodge, carriage gate by C. Warner c.1852

**File number (CNB):** 845.3

Address: 66 George

Print:

Negative: X

Description: College of Charleston opposite Porter's Lodge, double pass gate

**File number (CNB):** 845.4

Address: 66 George

Print:

Negative: X

Description: Porter's Lodge, southwest side

**File number (CNB):** 845.5

Address: 66 George

Print:

Negative: X

Description: College of Charleston, Porter's Lodge southeast sides

**File number (CNB):** 846

Address: 35 Hasell

Print:

Negative: X

Description: Fence detail

**File number (CNB):** 847

Address: 37 Hasell

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 848

Address: 39 Hasell

Print:

Negative: X

Description: Double gate

**File number (CNB):** 849

Address: 48 Hasell

Print:

Negative: X

Description: St. Johannes Lutheran Church c.1842, southside; E.B. White, architect

**File number (CNB):** 849.1

Address: 48 Hasell

Print:

Negative: X

Description: Eastside

**File number (CNB):** 849.2

Address: 48 Hasell

Print:

Negative: X

Description: Northeast side

**File number (CNB):** 849.3

Address: 48 Hasell

Print:

Negative: X

Description: Entry gates- do not belong to fencing

**File number (CNB): 850**

Address: 50 Hasell

Print:

Negative: X

Description: Stoop railing and street fencing

**File number (CNB): 850.1**

Address: 50 Hasell

Print:

Negative: X

Description: Half of carriage gate

**File number (CNB): 850.2**

Address: 50 Hasell

Print:

Negative: X

Description: Pass gate

**File number (CNB): 851**

Address: 23 King

Print:

Negative: X

Description: Eastside, 2nd floor, balcony; same on 24 King opposite; originally on Broad (Deas); probably by same hand as 60-64 Broad #056.1 and #056.4

**File number (CNB): 851.1**

Address: 23 King

Print:

Negative: X

Description: Balcony detail

**File number (CNB): 852 (1)**

Address: 75 King

Print:

Negative: X

Description: Eastside, carriage gate

**File number (CNB): 852 (2)**

Address: 75 King

Print:

Negative: X

Description: Eastside, carriage gate

**File number (CNB): 852.1 (1)**

Address: 75 King

Print:

Negative: X

Description: c.1739, house from southwest showing rare external chimney for this period

**File number (CNB): 852.1 (2)**

Address: 75 King

Print:

Negative: X

Description: c.1739, house from southwest showing rare external chimney for this period

**File number (CNB): 852.2 (1)**

Address: 75 King

Print:

Negative: X

Description: Kitchen, original eastside exterior, Equipment and room c.1950

**File number (CNB): 852.2 (2)**

Address: 75 King

Print:

Negative: X

Description: Kitchen, original eastside exterior, Equipment and room c.1950

**File number (CNB): 852.3**

Address: 75 King

Print:

Negative: X

Description: Kitchen, original, looking west; wall above oven door was originally a dome, similar to 110 Broad #085.1

**File number (CNB): 852.4**

Address: 75 King

Print:

Negative: X

Description: Kitchen, original, looking east; "T" slot in masonry above fireplace recessed for spit mechanism; wood lintel over fireplace opening has concave champter on bottom back side

**File number (CNB): 852.5**

Address: 75 King

Print:

Negative: X

Description: Carriage gate detail

**File number (CNB): 853 (1)**

Address: 82 King

Print:

Negative: X

Description: Pass and altered carriage gates, probably not original to site

**File number (CNB): 853 (2)**

Address: 82 King

Print:

Negative: X

Description: Pass and altered carriage gates, probably not original to site

**File number (CNB): 854**

Address: 98 King



Print:

Negative: X

Description: Pass (left side) and carriage gate combined; not original to site

**File number (CNB):** 855

Address: 140 King

Print:

Negative: X

Description: Eastside of street; site originally Quaker church

**File number (CNB):** 856

Address: 161-163 King

Print:

Negative: X

Description: Unitarian church gateway c.1930 (Bragg)

**File number (CNB):** 856.1

Address: 161-163 King

Print:

Negative: X

Description: Gate detail (by Ortman Bros. 1900-1937) (Bragg)

**File number (CNB):** 857

Address: 22 Lamboll

Print:

Negative: X

Description: Grill in swell of garden

**File number (CNB):** 858 (1)

Address: 50 Laurens

Print:

Negative: X

Description: Wrought iron carriage gates with wicket in right side

**File number (CNB):** 858 (2)

Address: 50 Laurens

Print:

Negative: X

Description: Wrought iron carriage gates with wicket in right side

**File number (CNB):** 858 (3)

Address: 50 Laurens

Print:

Negative: X

Description: Wrought iron carriage gates with wicket in right side

**File number (CNB):** 858 (4)

Address: 50 Laurens

Print:

Negative: X

Description: Wrought iron carriage gates with wicket in right side

**File number (CNB):** 858 (5)

Address: 50 Laurens

Print:

Negative: X

Description: Wrought iron carriage gates with wicket in right side

**File number (CNB):** 858.1 (1)

Address: 50 Laurens

Print:

Negative: X

Description: c.1807, wrought iron pass gate and railing c.1828 by G.H. Ingram whose name appears in brass plate tangent to top of circle

**File number (CNB):** 858.1 (2)

Address: 50 Laurens

Print:

Negative: X

Description: c.1807, wrought iron pass gate and railing c.1828 by G.H. Ingram whose name appears in brass plate tangent to top of circle

**File number (CNB):** 858.1 (3)

Address: 50 Laurens

Print:

Negative: X

Description: c.1807, wrought iron pass gate and railing c.1828 by G.H. Ingram whose name appears in brass plate tangent to top of circle

**File number (CNB):** 858.1 (4)

Address: 50 Laurens

Print:

Negative: X

Description: c.1807, wrought iron pass gate and railing c.1828 by G.H. Ingram whose name appears in brass plate tangent to top of circle

**File number (CNB):** 859

Address: 2 1/2 Legare

Print:

Negative: X

Description: Carriage gate, gone 1984

**File number (CNB):** 859.1

Address: 2 1/2 Legare

Print:

Negative: X

Description: Column urn detail

**File number (CNB):** 859.2

Address: 2 1/2 Legare

Print:

Negative: X

Description: Railing and pilaster

**File number (CNB):** 860

Address: 7 Legare

Print:

Negative: X

Description: c.1887; Eastside pass gate and fencing, date unknown

**File number (CNB):** 861

Address: 10 Legare

Print:

Negative: X

Description: Entry gate and fencing

**File number (CNB):** 861.1

Address: 10 Legare

Print:

Negative: X

Description: Ground floor window guard

**File number (CNB):** 862

Address: 13 Legare

Print:

Negative: X

Description: Carriage gate and piazza cheval-de-frise

**File number (CNB):** 862.1

Address: 13 Legare

Print:

Negative: X

Description: Detail, cheval-de-frise

**File number (CNB):** 863

Address: 22 Legare

Print:

Negative: X

Description: Entry gate, probably c.1800; overthrow and lantern later; gate posts probably by C. Warner (Bragg)

**File number (CNB):** 864

Address: 23 Legare

Print:

Negative: X

Description: Carriage gates

**File number (CNB):** 864.1

Address: 23 Legare

Print:

Negative: X

Description: Carriage gates, north leaf detail

**File number (CNB):** 864.2

Address: 23 Legare

Print:

Negative: X

Description: Carriage gates, south leaf detail

**File number (CNB):** 865 (1)

Address: 32 Legare

Print:

Negative: X

Description: "Sword Gates" by C. Warner; this gate reputedly an extra one from one of many for use as window guards in the 1838 Guard House formerly on the southwest corner of Meeting and Broad

**File number (CNB):** 865 (2)

Address: 32 Legare

Print:

Negative: X

Description: "Sword Gates" by C. Warner; this gate reputedly an extra one from one of many for use as window guards in the 1838 Guard House formerly on the southwest corner of Meeting and Broad

**File number (CNB):** 865 (3)

Address: 32 Legare

Print:

Negative: X

Description: "Sword Gates" by C. Warner; this gate reputedly an extra one from one of many for use as window guards in the 1838 Guard House formerly on the southwest corner of Meeting and Broad

**File number (CNB):** 865.1

Address: 32 Legare

Print:

Negative: X

Description: Detail, sword gate

**File number (CNB):** 865.2

Address: 32 Legare

Print:

Negative: X

Description: Overthrow detail

**File number (CNB):** 866 (1)

Address: 38 Legare

Print:

Negative: X

Description: Westside, carriage gate reputedly from Sea Island Hotel, Beaufort SC; stretched at each leaf by two unfilled vertical panels and "C" scroll at top

**File number (CNB):** 866 (2)

Address: 38 Legare

Print:

Negative: X

Description: Westside, carriage gate reputedly from Sea Island Hotel, Beaufort SC; stretched at each leaf by two unfilled vertical panels and "C" scroll at top

**File number (CNB):** 866 (3)

Address: 38 Legare

Print:

Negative: X

Description: Westside, carriage gate reputedly from Sea Island Hotel, Beaufort SC; stretched at each leaf by two unfilled vertical panels and "C" scroll at top

**File number (CNB): 867**

Address: 41 Legare

Print:

Negative: X

Description: Eastside, window grille, not original to site

**File number (CNB): 868 (1)**

Address: 43 Legare

Print:

Negative: X

Description: Eastside, entry and carriage gate

**File number (CNB): 868 (2)**

Address: 43 Legare

Print:

Negative: X

Description: Eastside, entry and carriage gate

**File number (CNB): 868.1 (1)**

Address: 43 Legare

Print:

Negative: X

Description: Eastside, carriage gate by Ortmann Bros. (1900-32) (Bragg)

**File number (CNB): 868.1 (2)**

Address: 43 Legare

Print:

Negative: X

Description: Eastside, carriage gate by Ortmann Bros. (1900-32) (Bragg)

**File number (CNB): 869**

Address: 67 Legare

Print:

Negative: X

Description: Eastside, gate, fencing similar, one of two designs on site

**File number (CNB): 869.1**

Address: 67 Legare

Print:

Negative: X

Description: Eastside entry and fence, one of two designs on site

**File number (CNB): 870**

Address: 9 Limehouse

Print:

Negative: X

Description: c.1856; Eastside, entry

**File number (CNB): 870.1**

Address: 9 Limehouse

Print:

Negative: X

Description: Stoop railing detail, eastside

**File number (CNB):** 870.2 (1)

Address: 9 Limehouse

Print:

Negative: X

Description: Eastside, entry, fence detail at steps

**File number (CNB):** 870.2 (2)

Address: 9 Limehouse

Print:

Negative: X

Description: Eastside, entry, fence detail at steps

**File number (CNB):** 870.3

Address: 9 Limehouse

Print:

Negative: X

Description: Eastside, carriage gate, probably original

**File number (CNB):** 871

Address: 10 Limehouse

Print:

Negative: X

Description: Westside, entry

**File number (CNB):** 872

Address: 12 Limehouse

Print:

Negative: X

Description: Carriage gate and wall, formerly belonging to 10 Limehouse

**File number (CNB):** 873

Address: 4 Logan

Print:

Negative: X

Description: Entry stair railing, not original to house; ground floor gate c.1930, made in New Orleans by Warrington House, a home for wayward boys (John E. Gibbs) (1980)

**File number (CNB):** 874 (H)

Address: 10 Logan

Print:

Negative: X

Description: Pass gate; site and ironwork formerly St. Peter's Episcopal Church graveyard, c.1835

**File number (CNB):** 874 (V)

Address: 10 Logan

Print:

Negative: X

Description: Pass gate; site and ironwork formerly St. Peter's Episcopal Church graveyard, c.1835

**File number (CNB):** 874.1

Address: 10 Logan

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 875

Address: 16 Logan

Print:

Negative: X

Description: West side, entry gate and fencing

**File number (CNB):** 876

Address: 11 Meeting

Print:

Negative: X

Description: East side, balcony

**File number (CNB):** 876.1

Address: 11 Meeting

Print:

Negative: X

Description: Fencing, east side

**File number (CNB):** 876.2

Address: 11 Meeting

Print:

Negative: X

Description: East side, balcony support

**File number (CNB):** 877 (1)

Address: 21 Meeting

Print:

Negative: X

Description: Yard pass gate

**File number (CNB):** 877 (2)

Address: 21 Meeting

Print:

Negative: X

Description: Yard pass gate

**File number (CNB):** 878

Address: 23 Meeting

Print:

Negative: X

Description: Balcony, compare CNB 879

**File number (CNB):** 879

Address: 25 Meeting

Print:

Negative: X

Description: Balcony, compare CNB 878

**File number (CNB):** 880 (1)

Address: 87 East Bay

Print:

Negative: X

Description: Eastside, balcony detail, originally on State St (Frost); the original balcony on this site is now at 68 South Battery (Frost)

**File number (CNB):** 880 (2)

Address: 87 East Bay

Print:

Negative: X

Description: Eastside, balcony detail, originally on State St (Frost); the original balcony on this site is now at 68 South Battery (Frost)

**File number (CNB):** 881

Address: 30 Meeting

Print:

Negative: X

Description: Westside, carriage gate

**File number (CNB):** 882 (1)

Address: 37 Meeting

Print:

Negative: X

Description: c.1776; eastside, fencing, double pass gate c.1846

**File number (CNB):** 882 (2)

Address: 37 Meeting

Print:

Negative: X

Description: c.1776; eastside, fencing, double pass gate c.1846

**File number (CNB):** 882.1

Address: 37 Meeting

Print:

Negative: X

Description: c.1776; eastside, 2nd floor, balcony c.1846, compare 116 Broad #093.1

**File number (CNB):** 882.2

Address: 37 Meeting

Print:

Negative: X

Description: c.1776; eastside, wood carriage gates with iron inserts c.1846

**File number (CNB):** 882.3 (1)

Address: 37 Meeting

Print:

Negative: X

Description: East side, ground floor window guard



**File number (CNB): 882.3 (2)**

Address: 37 Meeting

Print:

Negative: X

Description: East side, ground floor window guard

**File number (CNB): 883 (1)**

Address: 36 Meeting

Print:

Negative: X

Description: Carriage and pass gates, by Philip Simmons, except scroll panels

**File number (CNB): 883 (2)**

Address: 36 Meeting

Print:

Negative: X

Description: Carriage and pass gates, by Philip Simmons, except scroll panels

**File number (CNB): 883.1**

Address: 36 Meeting

Print:

Negative: X

Description: Detail, gate panel, c.18th Century

**File number (CNB): 884 (1)**

Address: 43 Meeting

Print:

Negative: X

Description: Carriage and pass gates, c.1940 by Sabel Iron Works

**File number (CNB): 884 (2)**

Address: 43 Meeting

Print:

Negative: X

Description: Carriage and pass gates, c.1940 by Sabel Iron Works

**File number (CNB): 885**

Address: 50 Meeting

Print:

Negative: X

Description: Wrought iron cheval-de-frise over railing and at column

**File number (CNB): 886**

Address: 56 Meeting

Print:

Negative: X

Description: Pass gate and fencing; Reputedly from G. Manigault house destroyed in 1930, Southeast corner Meeting and George (Deas)

**File number (CNB): 887 (1)**

Address: 58 Meeting

Print:

Negative: X

Description: Awning bar, demolished 1983, not original to house. See Sonn Pl. 237, fig. 2 and Pl. 238, fig. 1

**File number (CNB): 887 (2)**

Address: 58 Meeting

Print:

Negative: X

Description: Awning bar, demolished 1983, not original to house. See Sonn Pl. 237, fig. 2 and Pl. 238, fig. 1

**File number (CNB): 888**

Address: 60 Meeting

Print:

Negative: X

Description: Balcony detail; Compare 54 Broad #049.1 and 94 Rutledge #545.5

**File number (CNB): 889 (1)**

Address: 63 Meeting

Print:

Negative: X

Description: Carriage gate c.1915 by JF Riley (Frost). Mentioned in 1971 Encyclopaedia Britannica

**File number (CNB): 889 (2)**

Address: 63 Meeting

Print:

Negative: X

Description: Carriage gate c.1915 by JF Riley (Frost). Mentioned in 1971 Encyclopaedia Britannica

**File number (CNB): 890**

Address: 29 Montagu

Print:

Negative: X

Description: Stoop railing

**File number (CNB): 890.1**

Address: 29 Montagu

Print:

Negative: X

Description: Carriage gate, 20th Century, overthrow early 19th Century

**File number (CNB): 891**

Address: 20 New

Print:

Negative: X

Description: Entry gate and fencing

**File number (CNB): 892**

Address: 24 New

Print:

Negative: X

Description: Entry gate and fencing

**File number (CNB): 893**

Address: 163 Queen

Print:

Negative: X

Description: West side balcony

**File number (CNB): 894**

Address: 165 Queen

Print:

Negative: X

Description: Porch railing

**File number (CNB): 894.1**

Address: 165 Queen

Print:

Negative: X

Description: Step and yard railing

**File number (CNB): 895 (1)**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 895 (2)**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 895 (3)**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 895 (4)**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 895 (5) H**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 895.1**

Address: 182 Rutledge

Print:

Negative: X

Description: Brith Shalom Beth Israel Synagogue; West fence, pass gate c.1947, Sabel

**File number (CNB): 896**

Address: 4 St. Michael's Alley

Print:

Negative: X

Description: Southside balcony

**File number (CNB): 897**

Address: 43-45 St. Phillip

Print:

Negative: X

Description: Between George and Green; carriage gate by C. Werner; compare 66 George #845.2

**File number (CNB): 897.1**

Address: 43-45 St. Phillip

Print:

Negative: X

Description: Between George and Green; carriage gate by C. Werner

**File number (CNB): 898**

Address: 42 Society

Print:

Negative: X

Description: Carriage gates

**File number (CNB): 899**

Address: 44 Society

Print:

Negative: X

Description: Carriage gate and 2 pass gates, moved from Meeting Street (Deas)

**File number (CNB): 899.1**

Address: 44 Society

Print:

Negative: X

Description: Detail, carriage and pass gate

**File number (CNB): 900**

Address: 52 Society

Print:

Negative: X

Description: Carriage gate

**File number (CNB): 901**

Address: 56 Society

Print:

Negative: X

Description: Carriage gate

**File number (CNB): 902 (1)**

Address: 28-30 South Battery

Print:

Negative: X

Description: Carriage gate #28, pass gate #30

**File number (CNB):** 902 (2)

Address: 28-30 South Battery

Print:

Negative: X

Description: Carriage gate #28, pass gate #30

**File number (CNB):** 903 (1)

Address: 58 South Battery

Print:

Negative: X

Description: Carriage gate; dog bars in bottom panel are double in number after c.1984 rebuilding of gate

**File number (CNB):** 903 (2)

Address: 58 South Battery

Print:

Negative: X

Description: Carriage gate; dog bars in bottom panel are double in number after c.1984 rebuilding of gate

**File number (CNB):** 904

Address: 65 South Battery

Print:

Negative: X

Description: Entry gate, not original to site

**File number (CNB):** 904.1 (1)

Address: 65 South Battery

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 904.1 (2)

Address: 65 South Battery

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 905

Address: 74 South Battery

Print:

Negative: X

Description: Stoop railing, 20th century

**File number (CNB):** 905.1

Address: 74 South Battery

Print:

Negative: X

Description: Double Entry gate, 20th century

**File number (CNB):** 906

Address: 13 State

Print:

Negative: X

Description: Balcony

**File number (CNB):** 906.1

Address: 13 State

Print:

Negative: X

Description: Balcony, cast iron support bracket

**File number (CNB):** 907 (1)

Address: 1 Tradd

Print:

Negative: X

Description: East side, 2nd floor balcony, originally on State (Frost)

**File number (CNB):** 907 (2)

Address: 1 Tradd

Print:

Negative: X

Description: East side, 2nd floor balcony, originally on State (Frost)

**File number (CNB):** 908

Address: 6 and 8 Tradd

Print:

Negative: X

Description: right to left: entry gate, woven, #8; W. I pass gate #6; compare #6 with 53 Broad #048.1, made by lusti, c.1848; the pair formerly between 179 and 181 Meeting

**File number (CNB):** 908.1

Address: 6 Tradd

Print:

Negative: X

Description: Detail, gate at #6

**File number (CNB):** 909 (1)

Address: 7 Tradd

Print:

Negative: X

Description: Entry gate, iron with brass rosettes

**File number (CNB):** 909 (2)

Address: 7 Tradd

Print:

Negative: X

Description: Entry gate, iron with brass rosettes

**File number (CNB):** 909.1

Address: 7 Tradd

Print:

Negative: X  
Description: Northside balcony  
**File number (CNB):** 910  
Address: 56 Tradd  
Print:  
Negative: X  
Description: Carriage gate  
**File number (CNB):** 911  
Address: 58 Tradd  
Print:  
Negative: X  
Description: Entry and Carriage gates  
**File number (CNB):** 911.1  
Address: 58 Tradd  
Print:  
Negative: X  
Description: Double entry gate  
**File number (CNB):** 911.2  
Address: 58 Tradd  
Print:  
Negative: X  
Description: Carriage gate  
**File number (CNB):** 912  
Address: 61 Tradd  
Print:  
Negative: X  
Description: Entry doors, wood and iron  
**File number (CNB):** 913  
Address: 75 Tradd  
Print:  
Negative: X  
Description: Entry gate  
**File number (CNB):** 913.1  
Address: 75-77 Tradd  
Print:  
Negative: X  
Description: left to right: Carriage gate #75, pass gate #77  
**File number (CNB):** 914  
Address: 100 Tradd  
Print:  
Negative: X  
Description: Pass gate and cheval-de-frise  
**File number (CNB):** 914.1  
Address: 100 Tradd

Print:

Negative: X

Description: Carriage gate by Philip Simmons, inspired by gates formerly at 26 George

**File number (CNB):** 915

Address: 122 Tradd

Print:

Negative: X

Description: Southside entry

**File number (CNB):** 915.1

Address: 122 Tradd

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 915.1 (H)

Address: 122 Tradd

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 916

Address: 128 Tradd

Print:

Negative: X

Description: c.1765; entry steps and railing, not original to house

**File number (CNB):** 916.1

Address: 128 Tradd

Print:

Negative: X

Description: East side, Palladian window

**File number (CNB):** 916.2

Address: 128 Tradd

Print:

Negative: X

Description: 1st floor, S room, mantle detail, console front

**File number (CNB):** 916.3

Address: 128 Tradd

Print:

Negative: X

Description: 1st floor, S room, mantle detail, console side

**File number (CNB):** 916.4

Address: 128 Tradd

Print:

Negative: X

Description: 2nd floor, S room, mantle crosette

**File number (CNB):** 916.5



Address: 128 Tradd

Print:

Negative: X

Description: 2nd floor, S room, mantle freize block

**File number (CNB):** 917

Address: 129 Tradd

Print:

Negative: X

Description: Typical Charleston brick gate pier with moulded brick cap and base and brick stop for gate

**File number (CNB):** 918

Address: 131 Tradd

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 918.1

Address: 131 Tradd

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 919

Address: 143 Tradd

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 920 (1)

Address: 6 Thomas

Print:

Negative: X

Description: South side of Vanderhorst; carriage gate, opposite Pitt; wicket in left side

**File number (CNB):** 920 (2)

Address: 6 Thomas

Print:

Negative: X

Description: South side of Vanderhorst; carriage gate, opposite Pitt; wicket in left side

**File number (CNB):** 920.1

Address: 6 Thomas

Print:

Negative: X

Description: Southside of Vanderhorst, fence detail; compare pg 14 "Colonial Ironwork in Old Philadelphia" PB Wallace, 1930

**File number (CNB):** 920.2

Address: 6 Thomas

Print:

Negative: X

Description: Southside of Vanderhorst; gate from early 20th century photograph

**File number (CNB):** 921

Address: 19 Wentworth

Print:

Negative: X

Description: Northside

**File number (CNB):** 921.1

Address: 19 Wentworth

Print:

Negative: X

Description: Northside, entry frontispiece; note moulded brick entablature and battered brick architrave

**File number (CNB):** 921.2 (1)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside railing and pass gate, with cast iron gate threshold and cast iron wall cap below railing

**File number (CNB):** 921.2 (2)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside railing and pass gate, with cast iron gate threshold and cast iron wall cap below railing

**File number (CNB):** 921.2 (3)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside railing and pass gate, with cast iron gate threshold and cast iron wall cap below railing

**File number (CNB):** 921.2 (H)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside railing and pass gate, with cast iron gate threshold and cast iron wall cap below railing

**File number (CNB):** 921.3 (1)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside, gate detail

**File number (CNB):** 921.3 (2)

Address: 19 Wentworth

Print:

Negative: X

Description: Northside, gate detail

**File number (CNB):** 922

Address: 153 Wentworth

Print:

Negative: X

Description: Railing

**File number (CNB):** 923

Address: 12 State

Print:

Negative: X

Description: Pass gate, 20th century

**File number (CNB):** 924

Address: 22 Meeting

Print:

Negative: X

Description: Southside, pass gate, west side same

**File number (CNB):** 925

Address: 22 Church

Print:

Negative: X

Description: West side balcony

**File number (CNB):** 926

Address: 27 Church

Print:

Negative: X

Description: East side, basement window grill

**File number (CNB):** 927

Address: 34 South Battery

Print:

Negative: X

Description: Southside, double pass gate; carriage gate similar, except wider

**File number (CNB):** 927.1

Address: 34 South Battery

Print:

Negative: X

Description: Southside, balcony detail

**File number (CNB):** 928 (1)

Address: 2 Water

Print:

Negative: X

Description: South side carriage gate, defaced by bad stretching with addition of center panel

**File number (CNB):** 928 (2)

Address: 2 Water

Print:

Negative: X

Description: South side carriage gate, defaced by bad stretching with addition of center panel

**File number (CNB):** 928 (3)

Address: 2 Water

Print:

Negative: X

Description: South side carriage gate, defaced by bad stretching with addition of center panel

**File number (CNB):** 928 (4)

Address: 2 Water

Print:

Negative: X

Description: South side carriage gate, defaced by bad stretching with addition of center panel

**File number (CNB):** 928.1 (1)

Address: 2 Water

Print:

Negative: X

Description: South side, foot scraper

**File number (CNB):** 928.1 (2) small

Address: 2 Water

Print:

Negative: X

Description: South side, foot scraper

**File number (CNB):** 928.1 (3) small

Address: 2 Water

Print:

Negative: X

Description: South side, foot scraper

**File number (CNB):** 929

Address: 43 Church

Print:

Negative: X

Description: Northeast corner

**File number (CNB):** 929.1

Address: 43 Church

Print:

Negative: X

Description: Northeast cornice detail; carved mouldings on east side only

**File number (CNB):** 929.2

Address: 43 Church

Print:

Negative: X

Description: Eastside, window detail

**File number (CNB):** 929.3

Address: 43 Church

Print:

Negative: X

Description: Northside, round head window

**File number (CNB):** 929.4

Address: 43 Church

Print:

Negative: X

Description: Eastside, step railing detail by Ortmann Bros (1900-1932) Bragg

**File number (CNB):** 930

Address: 2 Gibbes

Print:

Negative: X

Description: Southside, basement window grill

**File number (CNB):** 931

Address: 66 Hasell

Print:

Negative: X

Description: Southwest, third floor

**File number (CNB):** 931.1

Address: 66 Hasell

Print:

Negative: X

Description: Third floor, portico railings, c.1850

**File number (CNB):** 932

Address: 45 Hasell

Print:

Negative: X

Description: Southside, 3rd floor window, guard, not original to site

**File number (CNB):** 933

Address: 26 George

Print:

Negative: X

Description: House, gone; south entry gates, c.1817 gone, 1970-80.

**File number (CNB):** 933.1

Address: 26 George

Print:

Negative: X

Description: Detail, carriage gate

**File number (CNB):** 934

Address: 73 Rutledge

Print:

Negative: X

Description: West side, entry gate

**File number (CNB):** 935

Address: 42 Rutledge

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 936

Address: 41 Church

Print:

Negative: X

Description: South side, step railing detail

**File number (CNB):** 937

Address: 47 Meeting

Print:

Negative: X

Description: South side

**File number (CNB):** 937.1

Address: 47 Meeting

Print:

Negative: X

Description: South side, balcony detail, after 1967 when wood piazza removed

**File number (CNB):** 938

Address: 64 Montagu

Print:

Negative: X

Description: South side, pass gate to porch stairs, two thus

**File number (CNB):** 938.1

Address: 64 Montagu

Print:

Negative: X

Description: South side, pass gate to porch stairs, two thus

**File number (CNB):** 938.2

Address: 64 Montagu

Print:

Negative: X

Description: Southside, east end, pass and carriage gates, not original to site. Note knocker above top of large circle on pass gate.

**File number (CNB):** 940

Address: 8 Vanderhorst

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 941

Address: 12 Vanderhorst

Print:

Negative: X

Description: c.1884, Irish Volunteer Armory, south side

**File number (CNB):** 941.1

Address: 12 Vanderhorst

Print:

Negative: X

Description: South side, 1st floor medallion

**File number (CNB):** 941.2

Address: 12 Vanderhorst

Print:

Negative: X

Description: 2nd floor medallion

**File number (CNB):** 942

Address: 156 Wentworth

Print:

Negative: X

Description: Carriage gate by Cincinnati Iron Fence Co.

**File number (CNB):** 943

Address: 16 Legare

Print:

Negative: X

Description: c.1795 Amerinthes Elliott; garden entry railing c.1949, copied from railing in Charleston museum c.1750

**File number (CNB):** 943.1

Address: 16 Legare

Print:

Negative: X

Description: Cast iron column, origin unknown, placed here c.1949; compare columns 16 Broad #024.3

**File number (CNB):** 943.2

Address: 16 Legare

Print:

Negative: X

Description: Detail- cast iron column

**File number (CNB):** 943.3

Address: 16 Legare

Print:

Negative: X

Description: Garden railing installed 1949; originally on house at 4 Cumberland where A. McLeish lived and next door to which he operated Vulcan Iron Works

**File number (CNB):** 943.4 (1)

Address: 16 Legare

Print:

Negative: X

Description: Garden railing detail

**File number (CNB):** 943.4 (2)

Address: 16 Legare

Print:

Negative: X

Description: Garden railing detail

**File number (CNB):** 944 (1)

Address: 36 Chalmers

Print:

Negative: X

Description: Carriage gates c.1932; note owner's cypher "JP" Josephine Pinckney at top of meeting stile

**File number (CNB):** 944 (2)

Address: 36 Chalmers

Print:

Negative: X

Description: Carriage gates c.1932; note owner's cypher "JP" Josephine Pinckney at top of meeting stile

**File number (CNB):** 945

Address: 18 Church

Print:

Negative: X

Description: Kitchen, southside

**File number (CNB):** 945.1 (1)

Address: 18 Church

Print:

Negative: X

Description: Pass gate, formerly at 172 Rutledge; removed to Smith St (c.1880) entrance; removed to Church St. at unknown date; bottom panel removed.

**File number (CNB):** 945.1 (2)

Address: 18 Church

Print:

Negative: X

Description: Pass gate, formerly at 172 Rutledge; removed to Smith St (c.1880) entrance; removed to Church St. at unknown date; bottom panel removed.

**File number (CNB):** 945.2

Address: 18 Church

Print:

Negative: X

Description: House, partial southside

**File number (CNB):** 946

Address: 10 Chalmers

Print:

Negative: X

Description: South brick wall, cast iron grille, of one three

**File number (CNB):** 947

Address: 26-32 Chalmers

Print:



Negative: X

Description: Carriage gate, one of two, the other being on south side Queen, between Meeting and Church c.1959

**File number (CNB):** 949

Address: 16 Bull

Print:

Negative: X

Description: c.1851; pass gate c.1880, when house remodeled by O. Bentschuer; note initials in center circle

**File number (CNB):** 950

Address: unknown

Print:

Negative: X

Description: copy of photo by Amberty pc Postcard Co.; gate and railing

**File number (CNB):** 951 (1)

Address: 134 St. Philip

Print:

Negative: X

Description: c.1887; St. Peter's Roman Catholic Church entry gate; R.C. Keely, architect

**File number (CNB):** 951 (2)

Address: 134 St. Philip

Print:

Negative: X

Description: c.1887; St. Peter's Roman Catholic Church entry gate; R.C. Keely, architect

**File number (CNB):** 952

Address: 25 Legare

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 952.1

Address: 25 Legare

Print:

Negative: X

Description: Balcony detail

**File number (CNB):** 953

Address: 82 Pitt

Print:

Negative: X

Description: Carriage gate, formerly at 20 South Battery, see #489; stretched 4" at Meeting stile of each leaf, note gap; cresting flattened to accommodate added width

**File number (CNB):** 954

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: c.1819; southwest corner

**File number (CNB):** 954.1

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: c.1819; northeast corner

**File number (CNB):** 954.2

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: church, west side entry

**File number (CNB):** 954.3

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: Nave, looking east

**File number (CNB):** 954.4

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: Nave, looking west

**File number (CNB):** 954.5

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: Vestry building, northeast corner

**File number (CNB):** 954.6

Address: Berkeley Co. St. Thomas and St. Dennis Episcopal Church

Print:

Negative: X

Description: Vestry building, southwest corner

**File number (CNB):** 955

Address: 21 Queen

Print:

Negative: X

Description: Pass gate, originally at Planters and Mechanics Bank, formerly at 139 East Bay.

**File number (CNB):** 955.1 (1)

Address: 21 Queen

Print:

Negative: X

Description: Carriage gates- same source as 955

**File number (CNB):** 955.1 (2)

Address: 21 Queen

Print:

Negative: X

Description: Carriage gates- same source as 955

**File number (CNB):** 956

Address: 22-24 Queen

Print:

Negative: X

Description: Entry gates

**File number (CNB):** 957

Address: 71 East Bay

Print:

Negative: X

Description: East side, balcony detail

**File number (CNB):** 958

Address: 5 King

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 958.1

Address: 5 King

Print:

Negative: X

Description: Pilaster terminal detail

**File number (CNB):** 959 (1)

Address: 37 King

Print:

Negative: X

Description: Carriage gates

**File number (CNB):** 959 (2)

Address: 37 King

Print:

Negative: X

Description: Carriage gates

**File number (CNB):** 959 (3)

Address: 37 King

Print:

Negative: X

Description: Carriage gates

**File number (CNB):** 960 (1)

Address: 82 Queen

Print:

Negative: X

Description: Cast iron centerpiece, source unknown

**File number (CNB):** 960 (2)

Address: 82 Queen

Print:

Negative: X

Description: Cast iron centerpiece, source unknown

**File number (CNB):** 960 (3)

Address: 82 Queen

Print:

Negative: X

Description: Cast iron centerpiece, source unknown

**File number (CNB):** 961

Address: 54 Montague

Print:

Negative: X

Description: Carriage house, westside, central bay window altered; note consoles which supported original pediment, since removed

**File number (CNB):** 961.1

Address: 54 Montague

Print:

Negative: X

Description: Carriage house, westside, north bay

**File number (CNB):** 961.2

Address: 54 Montague

Print:

Negative: X

Description: Carriage house, westside, circular window detail

**File number (CNB):** 962

Address: 44 Queen

Print:

Negative: X

Description: c.1800; cast iron leader boot

**File number (CNB):** 962.2

Address: 44 Queen

Print:

Negative: X

Description: c.1800; southside balcony; cypher "JS" of John Schirer who bought house in 1819

**File number (CNB):** 963 (1)

Address: 25 1/2 State

Print:

Negative: X

Description: Carriage gate built from scraps

**File number (CNB):** 963 (2)

Address: 25 1/2 State

Print:

Negative: X

Description: Carriage gate built from scraps

**File number (CNB): 964**

Address: 65 Meeting

Print:

Negative: X

Description: Carriage gate by Ortmann Bros (Bragg)

**File number (CNB): 965**

Address: 2 Stoll's Alley

Print:

Negative: X

Description: Pass gate

**File number (CNB): 966 (1)**

Address: 4 Stoll's Alley

Print:

Negative: X

Description: Pass gate

**File number (CNB): 966 (2)**

Address: 4 Stoll's Alley

Print:

Negative: X

Description: Pass gate

**File number (CNB): 967**

Address: 7 1/2 Stoll's Alley

Print:

Negative: X

Description: Pass gate

**File number (CNB): 968 (1)**

Address: 16 S Adger's Wharf

Print:

Negative: X

Description: Livingroom mantle, reputedly from 281 Meeting (destroyed 1947). See also 17 Longitude Lane

**File number (CNB): 968 (2)**

Address: 16 S Adger's Wharf

Print:

Negative: X

Description: Livingroom mantle, reputedly from 281 Meeting (destroyed 1947). See also 17 Longitude Lane

**File number (CNB): 968 (3)**

Address: 16 S Adger's Wharf

Print:

Negative: X

Description: Livingroom mantle, reputedly from 281 Meeting (destroyed 1947). See also 17 Longitude Lane

**File number (CNB): 969**

Address: 46 Murray Blvd

Print:

Negative: X

Description: Pass gate by Philip Simmons, 20th Century

**File number (CNB):** 969.1

Address: 46 Murray Blvd

Print:

Negative: X

Description: Carriage gate by Philip Simmons, c. 20th Century

**File number (CNB):** 970

Address: 48 Murray Blvd

Print:

Negative: X

Description: Portico railing, not original to site

**File number (CNB):** 971

Address: 44 Meeting

Print:

Negative: X

Description: Southside, 2nd floor balcony, 20th Century with 19th Century elements

**File number (CNB):** 971.1

Address: 44 Meeting

Print:

Negative: X

Description: Southside, 2nd floor balcony, detail

**File number (CNB):** 972

Address: 46 Wentworth

Print:

Negative: X

Description: Southwest side, one of smallest houses in Charleston. See also 98 Broad #973

**File number (CNB):** 973

Address: 98 Broad

Print:

Negative: X

Description: Southwest corner

**File number (CNB):** 974

Address: 244-246 King

Print:

Negative: X

Description: Westside

**File number (CNB):** 974.1

Address: 246 King

Print:

Negative: X

Description: Eastside

**File number (CNB): 975**

Address: Convention Center

Print:

Negative: X

Description: Meeting St, west side, from corner of N. Market

**File number (CNB): 975.1**

Address: Convention Center

Print:

Negative: X

Description: Meeting St, west side, King Street west side, northside of site, from southeast corner of Meeting and Market

**File number (CNB): 975.2**

Address: Convention Center

Print:

Negative: X

Description: Meeting St, east side

**File number (CNB): 975.3**

Address: Convention Center

Print:

Negative: X

Description: Northside buildings, east end, from southside Market

**File number (CNB): 975.4**

Address: Convention Center

Print:

Negative: X

Description: Northside buildings, west end, from southside Market

**File number (CNB): 975.5**

Address: Convention Center

Print:

Negative: X

Description: King St, westside from southside Market, looking west

**File number (CNB): 975.5a (1)**

Address: Convention Center

Print:

Negative: X

Description: King St, eastside from southside Market, looking northwest

**File number (CNB): 975.5a (2)**

Address: Convention Center

Print:

Negative: X

Description: King St, eastside from southside Market, looking northwest

**File number (CNB): 975.5a (3)**

Address: Convention Center

Print:

Negative: X

Description: King St, eastside from southside Market, looking northwest

**File number (CNB):** 975.56

Address: Convention Center

Print:

Negative: X

Description: King St, westside from southside Market, looking north up King

**File number (CNB):** 975.5c (1)

Address: Convention Center

Print:

Negative: X

Description: King St, eastside, from center of site looking west

**File number (CNB):** 975.5c (2)

Address: Convention Center

Print:

Negative: X

Description: King St, eastside, from center of site looking west

**File number (CNB):** 975.6

Address: Convention Center

Print:

Negative: X

Description: King St, westside and Market St, southside from Meeting St

**File number (CNB):** 975.7

Address: Convention Center

Print:

Negative: X

Description: Looking east across site and down Market from King

**File number (CNB):** 975.8

Address: Convention Center

Print:

Negative: X

Description: Market St, southside, east end

**File number (CNB):** 975.9

Address: Convention Center

Print:

Negative: X

Description: Market St, southside, west end

**File number (CNB):** 975.9a

Address: Convention Center

Print:

Negative: X

Description: Looking southeast across site from southeast corner King and Hasell

**File number (CNB):** 975.10

Address: Convention Center



Print:

Negative: X

Description: Looking west across site from southeast corner Meeting and Market

**File number (CNB):** 975.11

Address: Convention Center

Print:

Negative: X

Description: Market St, southside; King St eastside

**File number (CNB):** 975.12

Address: Convention Center

Print:

Negative: X

Description: King St, eastside, from northwest corner of King and Market

**File number (CNB):** 975.13

Address: Convention Center

Print:

Negative: X

Description: Looking northeast across site from Market

**File number (CNB):** 975.14 (1)

Address: Convention Center

Print:

Negative: X

Description: Looking southeast across site from King and Hasell

**File number (CNB):** 975.14 (2)

Address: Convention Center

Print:

Negative: X

Description: Looking southeast across site from King and Hasell

**File number (CNB):** 976

Address: 207-235 Meeting

Print:

Negative:

Description:

**File number (CNB):** 976

Address: 207-235 Meeting

Print: X

Negative: X

Description: left to right: Westside, from southwest corner, Hasell south

**File number (CNB):** 977

Address: 207-213 Meeting

Print: X

Negative: X

Description: Eastside (left to right)

**File number (CNB):** 978

Address: 215-219 Meeting

Print: X

Negative: X

Description: Eastside (left to right)

**File number (CNB):** 979

Address: 221-227 Meeting

Print: X

Negative: X

Description: Eastside (left to right)

**File number (CNB):** 979.1

Address: 227 Meeting

Print:

Negative: X

Description: Eastside, cast iron front

**File number (CNB):** 980

Address: 229-235 Meeting

Print: X

Negative: X

Description: Left to right, eastside

**File number (CNB):** 980.1

Address: 233 Meeting

Print:

Negative: X

Description: Eastside during demolition

**File number (CNB):** 981 (1)

Address: 262 Meeting

Print:

Negative: X

Description: Gazebo c.1887 over artesian well, c.1845

**File number (CNB):** 981 (2)

Address: 262 Meeting

Print:

Negative: X

Description: Gazebo c.1887 over artesian well, c.1845

**File number (CNB):** 981.1

Address: 262 Meeting

Print:

Negative: X

Description: Cornice detail

**File number (CNB):** 981.2

Address: 262 Meeting

Print:

Negative: X

Description: Freize detail

**File number (CNB): 982**

Address: 220 King

Print:

Negative: X

Description: Westside

**File number (CNB): 982.1**

Address: 220 King

Print:

Negative: X

Description: Northside

**File number (CNB): 983 (1)**

Address: 21 Archdale

Print:

Negative: X

Description: Eastside, double gate, compare with 10 Logan #874.1 and 43 Wentworth #718.2

**File number (CNB): 983 (2)**

Address: 21 Archdale

Print:

Negative: X

Description: Eastside, double gate, compare with 10 Logan #874.1 and 43 Wentworth #718.2

**File number (CNB): 985**

Address: 41-43 Tradd

Print: X

Negative: X

Description: Northwest corner

**File number (CNB): 985.1**

Address: 43 Tradd

Print:

Negative: X

Description: Entry gate at 43

**File number (CNB): 986**

Address: 123 Tradd

Print: X

Negative: X

Description: c.1800, Northwest corner

**File number (CNB): 986.1**

Address: 123 Tradd

Print: X

Negative: X

Description: c.1800, North entry

**File number (CNB): 987**

Address: 38 Tradd

Print: X

Negative: X

Description: Southside

**File number (CNB): 988**

Address: 21 Cumberland

Print:

Negative: X

Description: Powder magazine, c.1713; Northside, passgate, date unknown

**File number (CNB): 989 (1)**

Address: 293 East Bay

Print:

Negative: X

Description: Northeast corner from old photograph, showing altered original building, North Heyward c.1788, demolished c.1965

**File number (CNB): 989 (2)**

Address: 293 East Bay

Print:

Negative: X

Description: Northeast corner from old photograph, showing altered original building, North Heyward c.1788, demolished c.1965

**File number (CNB): 990**

Address: 10 Exchange

Print:

Negative: X

Description: Eastside

**File number (CNB): 990.1 (1)**

Address: 10 Exchange

Print:

Negative: X

Description: Eastside, 2nd floor, balcony detail

**File number (CNB): 990.1 (2)**

Address: 10 Exchange

Print:

Negative: X

Description: Eastside, 2nd floor, balcony detail

**File number (CNB): 990.2**

Address: 10 Exchange

Print:

Negative: X

Description: Eastside, 2nd floor, balcony detail, bracket

**File number (CNB): 991**

Address: 315-323 Meeting

Print:

Negative: X

Description: Eastside, 2nd floor, bay window guard

**File number (CNB): 991.1**

Address: 315-323 Meeting

Print:

Negative: X

Description: Eastside, 2nd floor, window guard

**File number (CNB):** 992 (1)

Address: 120 Broad

Print:

Negative: X

Description: St. Andrews Society, c.1819 (Deas), carriage gate

**File number (CNB):** 992 (2)

Address: 120 Broad

Print:

Negative: X

Description: St. Andrews Society, c.1819 (Deas), carriage gate

**File number (CNB):** 993

Address: 96 Ashley

Print:

Negative: X

Description: Double pass gate

**File number (CNB):** 995 (1)

Address: 5 East Battery

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 995 (2)

Address: 5 East Battery

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 996

Address: 68 Meeting

Print:

Negative: X

Description: Pass gate

**File number (CNB):** 996.1

Address: 68 Meeting

Print:

Negative: X

Description: One half carriage gate on Rope Lane, formerly on Meeting St; compare with 65 Meeting #964

**File number (CNB):** 996.2

Address: 68 Meeting

Print:

Negative: X

Description: Carriage gate, copy of photo (no date) by Ambertype Post Card Co., showing gates in original positions

**File number (CNB):** 997

Address: 80 Alexander

Print:

Negative: X

Description: Carriage gate

**File number (CNB):** 998

Address: 7 Orange

Print:

Negative: X

Description: Carriage gate, c.1940-41

**File number (CNB):** 998.1

Address: 7 Orange

Print:

Negative: X

Description: c.1769, stoop railing, probably original to house

**File number (CNB):** 998.2

Address: 7 Orange

Print:

Negative: X

Description: c.1769, stoop railing, panel detail

**File number (CNB):** 999

Address: 116 Church

Print:

Negative: X

Description: Westside balcony

**File number (CNB):** 1000

Address: 119 Church

Print:

Negative: X

Description: Eastside balcony

**File number (CNB):** 1001

Address: 121 Church

Print:

Negative: X

Description: Eastside balcony, compare 83 E Bay #837

**File number (CNB):** 1003

Address: 124 Church

Print:

Negative: X

Description: Westside balcony

**File number (CNB):** 1004

Address: 67 Broad

Print:

Negative: X

Description: c.1760, northside, before renovation

**File number (CNB):** 1004.1

Address: 67 Broad

Print:

Negative: X

Description: c.1760, northside, after renovation

**File number (CNB):** 1004.2 (1)

Address: 67 Broad

Print:

Negative: X

Description: c.1760, northside, pass gate design Robert Hollings, 1981. Fabricated by Philip Simmons

**File number (CNB):** 1004.2 (2)

Address: 67 Broad

Print:

Negative: X

Description: c.1760, northside, pass gate design Robert Hollings, 1981. Fabricated by Philip Simmons

**File number (CNB):** 1005

Address: 12 14 16 Broad

Print:

Negative: X

Description: Southside (right to left)

**File number (CNB):** 1006

Address: 73 Meeting

Print:

Negative: X

Description: Post office park, southwest bird's eye

**File number (CNB):** 1006.3

Address: 73 Meeting

Print:

Negative: X

Description: Northwest bird's eye from 69 Meeting

**File number (CNB):** 1006.4

Address: 73 Meeting

Print:

Negative: X

Description: Post office park, view northwest from 72 Meeting

**File number (CNB):** 1006.5

Address: 73 Meeting

Print:

Negative: X

Description: Post office park, view southwest

**File number (CNB):** 1006.6

Address: 73 Meeting

Print:

Negative: X

Description: Post office park, view northeast

**File number (CNB):** 1006.7

Address: 73 Meeting

Print:

Negative: X

Description: Post office park, view southeast

**File number (CNB):** 1007

Address: 4 Cumberland

Print: X

Negative: X

Description: site of JF Riley Iron Works; parts of cast iron balcony are now in garden of 16 Legare

**File number (CNB):** 1008

Address: 73 King

Print:

Negative: X

Description: Carriage gate, not original to site

**File number (CNB):** 1009

Address: 28 Chapel

Print:

Negative: X

Description: Southside, side yard railing by C Warner (Deas); compare with 16 Charlotte #815.1

**File number (CNB):** 1009.1

Address: 28 Chapel

Print:

Negative: X

Description: Southside, stoop and stair railing by C Warner. Compare 16 Charlotte #815.1

**File number (CNB):** 1009.2

Address: 28 Chapel

Print:

Negative: X

Description: Southside, entry gate by C Warner. Compare 16 Charlotte. Gate now at 261 Confederate Place.

**File number (CNB):** 1010

Address: 10 Gillion

Print:

Negative: X

Description: Southside, pass guide

**File number (CNB):** 1011 (1)

Address: 23 Archdale

Print:

Negative: X



Description: Carriage gate, 20th Century, made in Florida

**File number (CNB):** 1011 (2)

Address: 23 Archdale

Print:

Negative: X

Description: Carriage gate, 20th Century, made in Florida

**File number (CNB):** 1012 (1)

Address: 101 East Bay

Print:

Negative: X

Description: Wrought iron balcony original on frame house at 7 Elizabeth St, c.1843, now demolished, with cypher "CP" for Clause Prigge who owned the property 1841-96

**File number (CNB):** 1012 (2)

Address: 101 East Bay

Print:

Negative: X

Description: Wrought iron balcony original on frame house at 7 Elizabeth St, c.1843, now demolished, with cypher "CP" for Clause Prigge who owned the property 1841-96

**File number (CNB):** 1013

Address: 2 Courthouse Square

Print:

Negative: X

Description: Eastside double pass gate, designed by Albert Simons, FAIA, fabricated by Cooper Iron Works, 1970

**File number (CNB):** 1013.1

Address: 2 Courthouse Square

Print:

Negative: X

Description: Eastside, railing and gate braces

**File number (CNB):** 1014 (1)

Address: 114 Broad

Print:

Negative: X

Description: Foot scraper

**File number (CNB):** 1014 (2) small

Address: 114 Broad

Print:

Negative: X

Description: Foot scraper

**File number (CNB):** 1014 (3) small

Address: 114 Broad

Print:

Negative: X

Description: Foot scraper

**File number (CNB):** 1015 (1)

Address: 109 Broad

Print:

Negative: X

Description: Foot scraper

**File number (CNB):** 1015 (2) small

Address: 109 Broad

Print:

Negative: X

Description: Foot scraper

**File number (CNB):** 1017

Address: Calhoun

Print:

Negative: X

Description: Southside, between St. Philip and Coming; wrought iron double gate and railing by Albert Simons, FAIA, fabricated by McClammy Iron Works, 1968, looking north

**File number (CNB):** 1017.1

Address: Calhoun

Print:

Negative: X

Description: Southside, between St. Philip and Coming; wrought iron double gate and railing by Albert Simons, FAIA, fabricated by McClammy Iron Works, 1968, looking south

**File number (CNB):** 1018

Address: 55 Society

Print:

Negative: X

Description: c.1842; E.B. White, architect; carriage gates and 2 single gates, 2 sets, thus, c.1950; Cresting new, copied from gates on opposite side of building

**File number (CNB):** 1019

Address: 48 South Battery

Print: X

Negative: X

Description: Northside, foot scraper

**File number (CNB):** 1020

Address: 38 Chalmers

Print:

Negative: X

Description: Southside, pass gate with cheval-de-frise transom bar

**File number (CNB):** 1021

Address: 4 Legare

Print:

Negative: X

Description: Westside, balcony

**File number (CNB):** 1022

Address: 2 Unity Alley

Print:

Negative: X

Description: McCrady Tavern; interior courtyard, west side

**File number (CNB):** 1022.1

Address: 2 Unity Alley

Print:

Negative: X

Description: McCrady Tavern; interior courtyard, northwest corner

**File number (CNB):** 1022.2

Address: 2 Unity Alley

Print:

Negative: X

Description: Interior courtyard looking northwest thru west wall arch

**File number (CNB):** 1022.3

Address: 2 Unity Alley

Print:

Negative: X

Description: McCrady Tavern; northside diapering

**File number (CNB):** 1022.5

Address: 2 Unity Alley

Print:

Negative: X

Description: McCrady Tavern; westside diapering

**File number (CNB):** 1023

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Charleston Co., southside, c.1768

**File number (CNB):** 1023.1 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Westside

**File number (CNB):** 1023.1 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Westside

**File number (CNB):** 1023.2 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Westside, door and window detail. Note projecting brick plinth and key blocks in brick

arches- these occur on east and west windows and doors only

**File number (CNB):** 1023.2 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, brick column, base detail

**File number (CNB):** 1023.3 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Northside, portico originally open as south portico, filled in between center columns to provide [...?]

**File number (CNB):** 1023.3 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, brick columns, cap detailed

**File number (CNB):** 1023.4

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Eastside

**File number (CNB):** 1023.5 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Eastside, palladian window; half circle above center window bricked in, date unknown; center and side shutters added, date unknown; note large and crude mortise for center shutter hinges; window sill appears to have been altered as window pilasters projec

**File number (CNB):** 1023.5 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Eastside, palladian window; half circle above center window bricked in, date unknown; center and side shutters added, date unknown; note large and crude mortise for center shutter hinges; window sill appears to have been altered as window pilasters projec

**File number (CNB):** 1023.6

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, moulded brick column cap and wood cornice detail; column shaft brick, 4 courses = 13" with 2 3/4" - 3" brick height

**File number (CNB):** 1023.7

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, moulded brick column base detail

**File number (CNB):** 1023.8

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, entry door; all exterior doors 5' 0" wide x 9' 11" high

**File number (CNB):** 1023.9

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Nave, looking north; raised dais and furniture not original; doors show opening into room on north portico originally exterior doors opening into church aisle; no applied finish on any interior wood work, except sash; Door architrave on plaster walls 9' 3

**File number (CNB):** 1023.1

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Nave, looking northeast, ceiling coved

**File number (CNB):** 1023.11

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: East wall, pulpit and palladian windows; half circle above center window filled in; side light exterior shutters nailed shut, sash remain; window architrave on plaster wall 9' 3" wide overall and 12 1/2" wide; arch segmented into 2 parts on each side

**File number (CNB):** 1023.12

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Southside, entry door

**File number (CNB):** 1023.13 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Nave, looking southwest

**File number (CNB):** 1023.13 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Nave, looking southwest

**File number (CNB):** 1023.14

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Typical window head detail; architrave on plaster wall 6' 10 1/2" wide; arch segmented into 1 part on each side

**File number (CNB):** 1023.15 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Pew detail; paneling 52 1/2" above brick floor, 46 3/4" above wood pew floor

**File number (CNB):** 1023.15 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Pew detail; paneling 52 1/2" above brick floor, 46 3/4" above wood pew floor

**File number (CNB):** 1023.16

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Pew hinge

**File number (CNB):** 1023.17 (1)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Typical exterior door hinge; horizontal leg 20", vertical legs 17 1/2", both 1/4" thick. Vertical legs 5 1/4" wide with 1 1/2" between; hinge pin case 1" diam x 6" high

**File number (CNB):** 1023.17 (2)

Address: St. James Santee Episcopal Church

Print:

Negative: X

Description: Typical exterior door hinge; horizontal leg 20", vertical legs 17 1/2", both 1/4" thick. Vertical legs 5 1/4" wide with 1 1/2" between; hinge pin case 1" diam x 6" high

**File number (CNB):** 1024.5

Address: 69 Meeting

Print:

Negative:

Description: 1st floor hall (1974) looking north

**File number (CNB):** 1024.6

Address: 69 Meeting

Print:

Negative:

Description: mantle

**File number (CNB):** 1024.16 (1) H

Address: 69 Meeting

Print:

Negative:

Description: mantle

**File number (CNB):** 1024.16 (2) H

Address: 69 Meeting

Print:

Negative:

Description: mantle

**File number (CNB):** 1024.16 (3) V

Address: 69 Meeting

Print:

Negative:

Description: mantle

**File number (CNB):** 1024.24

Address: 69 Meeting

Print:

Negative:

Description:

**File number (CNB):** 1024.39 (1)

Address: 69 Meeting

Print:

Negative: X

Description: Victorian necessary formerly on west side of house, removed 1971

**File number (CNB):** 1024.39 (2) small

Address: 69 Meeting

Print:

Negative: X

Description: Victorian necessary formerly on west side of house, removed 1971

**File number (CNB):** 1024.39 (3) small

Address: 69 Meeting

Print:

Negative: X

Description: Victorian necessary formerly on west side of house, removed 1971

**File number (CNB):** 1024.40 (1)

Address: 69 Meeting

Print:

Negative: X

Description: Victorian necessary, door

**File number (CNB):** 1024.40 (2) small

Address: 69 Meeting

Print:

Negative: X

Description: Victorian necessary, door

**File number (CNB):** 1024.41 (1)

Address: 69 Meeting

Print:  
Negative: X  
Description: Victorian necessary door and panel detail  
**File number (CNB):** 1024.41 (2) small  
Address: 69 Meeting

Print:  
Negative: X  
Description: Victorian necessary, door and panel detail  
**File number (CNB):** 1024.42 (1)  
Address: 69 Meeting

Print:  
Negative: X  
Description: Victorian necessary, cornice detail  
**File number (CNB):** 1024.42 (2) small  
Address: 69 Meeting

Print:  
Negative: X  
Description: Victorian necessary, cornice detail  
**File number (CNB):** 1025  
Address: 183-207 East Bay

Print:  
Negative: X  
Description: Southeast corner  
**File number (CNB):** 1026  
Address: 183-185 East Bay

Print:  
Negative: X  
Description: Eastside  
**File number (CNB):** 1026  
Address: 183 East Bay

Print:  
Negative: X  
Description: Eastside  
**File number (CNB):** 1026.1  
Address: 183 East Bay

Print:  
Negative: X  
Description: Southside  
**File number (CNB):** 1027  
Address: 191 East Bay

Print:  
Negative: X  
Description: Eastside  
**File number (CNB):** 1028



Address: 195-199 East Bay

Print:

Negative: X

Description: Eastside

**File number (CNB):** 1029

Address: 203 East Bay

Print:

Negative: X

Description: Eastside

**File number (CNB):** 1030

Address: 183-203 East Bay

Print:

Negative: X

Description: Northeast corner

**File number (CNB):** 1031

Address: 205 East Bay

Print:

Negative: X

Description: Eastside

**File number (CNB):** 1032

Address: 205-207 East Bay

Print:

Negative: X

Description: Southeast corner

**File number (CNB):** 1033

Address: 42-44 State

Print:

Negative: X

Description: Westside (Lodge Alley between)

**File number (CNB):** 1034

Address: 46-50 State

Print:

Negative: X

Description: Westside

**File number (CNB):** 1035

Address: 60 State

Print:

Negative: X

Description: Westside (corner Cumberland)

**File number (CNB):** 1036

Address: 16 State

Print:

Negative: X

Description: Westside (corner Queen)

**File number (CNB): 1036.1**

Address: 16 State

Print:

Negative: X

Description: Northwest side

**File number (CNB): 1037 (1)**

Address: 290 East Bay

Print:

Negative: X

Description: (Behind); c.1844; Westside; Gov Thomas Bennett's Rice Mill, abandoned c.1960; Industrial palladianism, undated post card

**File number (CNB): 1037 (2)**

Address: 290 East Bay

Print:

Negative: X

Description: (Behind); c.1844; Westside; Gov Thomas Bennett's Rice Mill, abandoned c.1960; Industrial palladianism, undated post card

**File number (CNB): 1037 (3)**

Address: 290 East Bay

Print:

Negative: X

Description: (Behind); c.1844; Westside; Gov Thomas Bennett's Rice Mill, abandoned c.1960; Industrial palladianism, undated post card

**File number (CNB): 1037 (4)**

Address: 290 East Bay

Print:

Negative: X

Description: (Behind); c.1844; Westside; Gov Thomas Bennett's Rice Mill, abandoned c.1960; Industrial palladianism, undated post card